

Date : 24/02/2020
To : LONPAC INSURANCE BHD.

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTHCVE000182 Accident Date : 19/02/2020

Vehicle No : GBJ-4020-P Make & Model : TOYOTA DYNA 150 (EURO 6) 3.0 DIESEL G (H

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
List Item			
1	FRONT PANEL RESTORE	1150.00	0.00
1	FRONT PANEL EMBLEM DYNA	65.00	65.00
1	FRONT GRILLE	550.00	550.00
1	FRONT GRILLE LOGO	75.00	75.00
1	FRONT WINDSCREEN MOULDING	305.00	0.00
Sub Total		995.00	690.00
Discount 25% On Parts		(0.00)	(172.50)
Labour & Misc			
	LABOUR TO FACILITATE REPAIR	600.00	400.00
	LABOUR TO SPRAY PAINT AFFECTED AREAS	600.00	200.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00	0.00
	TO RUST PROOF AFFECTED AREA	60.00	0.00

1/P = \$690 - 25% = \$517.50

Repair days: 03

2 = \$600.00

\$1117.50 - 20% = COR = \$900.00

PAGE : 1



Date : 24/02/2020

To : LONPAC INSURANCE BHD.

Attn : Motor Claim Department

FAX :

Owner : ETHOZ Group Ltd

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D19MTHCVE000182 Accident Date : 19/02/2020

Vehicle No : GBJ-4020-P Make & Model : TOYOTA DYNA 150 (EURO 6) 3.0 DIESEL G (M

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	TO REMOVE & REFIT FRONT WINDSCREEN GLASS	120.00	0.00
	Sub Total	1410.00	600.00
Sub Total		3,018.75	1,117.50
GST 7.0 %		211.31	78.22
Total		3,230.06	1,195.72

Surveyor Name : GUO QIANG - LKK

Date & Time : 20/02/2020 5:30:00 PM

Ng Boon Kai

PAGE : 2

CLAIM DEPARTMENT

DID : 6654_7617

FAX :