



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 27/02/2020

User ID : CatherineLee

Section A - Accident Details

Registration Number	SG1222H
Case Reference Number	BUS/02/20/6003
Registration Date	27/12/2017
Company Type	SMRT Buses Ltd
Make	MERCEDES
Model	MBOC530
Name of Driver	Lim Kok Tiong
Type of Accident	Head to Rear
Accident Date and Time	20/2/2020 11:26 AM
Accident Reported Date and Time	20/2/2020 1:15 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24105840
Special Instruction to ARC, if any	SG1222H-REAR PORTION SHD4262M (TP) INSURED WITH iii
Prepared Date and Time	20/2/2020 4:17 PM
Chassis Number	WEB62806323130956
Mileage	
Work Shop	
Repair Completion Date and Time	

LKK Auto Consultants hence notify
the Repairer of the following:



- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - Summary of Repair Estimates

Summary of Repair Estimates	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$265.00
Total Spray Cost	\$354.00	\$262.00
Total Spare Part Cost	\$1,612.20	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$2,761.20	\$527.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	1.0
Prepared / Adjusted By	Boon Chew Tay	Sun Pin (LKK)
ARC / Surveyor Sign Off Date	20/02/2020 4:20 PM	21/02/2020 2:39 PM
Signature		
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 20/02/2020

User ID : GohKK2

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$795.00	265
Total Labour	\$795.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$354.00	262
Total Spray Painting & Panel Beating	\$354.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009907	Body		BUMPER-REAR,CENTR E, FOR MB CITARO O530	1.00	\$1,791.33	10.00	\$1,612.20	Replace	XR
Total					\$1,791.33		\$1,612.20		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Repair day - 1 days
~~1 day~~ P/P

After paint photo.

Sun Pm (Lklk)

21/02/2020

TP without prejudice.




SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 20/02/2020

User ID : GohKK2

Section A - Accident Details		
Registration Number	SG1222H	
Case Reference Number	BUS/02/20/6003	
Registration Date	27/12/2017	
Company Type	SMRT Buses Ltd	
Make	MERCEDES	
Model	MBOC530	
Name of Driver	Lim Kok Tiong	
Type of Accident	Head to Rear	
Accident Date and Time	20/2/2020 11:26 AM	
Accident Reported Date and Time	20/2/2020 1:15 PM	
Is Surveyor Required?	No	
Survey by		
Vehicle is Towed Back?	No	
Towed Back Date and Time		
Replacement Vehicle issued?	No	
Job Card Number		
Special Instruction to ARC, if any	SG1222H-REAR PORTION SHD4262M (TP) INSURED WITH III	
Prepared Date and Time	20/2/2020 4:17 PM	
Chassis Number	WEB62808323130956	
Mileage		
Work Shop		
Repair Completion Date and Time		

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$795.00	\$0.00
Total Spray Cost	\$0.00	\$0.00
Total Spare Part Cost	\$1,612.20	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$2,407.20	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	
Prepared / Adjusted By	ARC Manager Team	
ARC / Surveyor Sign Off Date	20/02/2020 4:20 PM	
Signature		x
Remarks		

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 27/02/2020

User ID : CatherineLee

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$795.00	\$265.00 /
Total Labour	\$795.00	\$265.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$354.00	\$262.00 /
Total Spray Painting & Panel Beating	\$354.00	\$262.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Other Costs		

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009907	Body		BUMPER:REAR,CENTR E, FOR MB CITARO O530	1.00	\$1,791.33	100.00	\$0.00	Replace	Repair X 12
Total					\$1,791.33		\$0.00		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

\$527.

1 days

Oi Sun Pin (LKK Auto)

From: Oi Sun Pin (LKK Auto)
Sent: Monday, 16 March, 2020 9:44 AM
To: Catherine Lee Sau Chan (Auto Svcs/ARC/ARC/Buses)
Subject: RE: Finalisation - SG1222H (BUS/02/20/6003) - India Int Ins

Hi Catherine,

Confirm the finalize amount \$527. Repair day 1 days under part by part repair.

Thank you.

Best Regards,

Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Lee Sau Chan (Auto Svcs/ARC/ARC/Buses) [<mailto:catherineleesc@smrt.com.sg>]
Sent: Thursday, 12 March, 2020 11:14 AM
To: Oi Sun Pin (LKK Auto); SUR; Admin A
Subject: FW: Finalisation - SG1222H (BUS/02/20/6003) - India Int Ins

Hi Sunpin,

This case has not finalised yet.
Please expedite.

Thank you

Regards
Catherine Lee

From: Catherine Lee Sau Chan (Auto Svcs/ARC/ARC/Buses)
Sent: Thursday, 27 February 2020 15.48
To: sunpin@lkkauto.com; SUR; Admin A
Cc: 'Koo Yew Chung (Auto Svcs/ARC/ARC)'; 'AutoSvs-ARC (Bus)'
Subject: Finalisation - SG1222H (BUS/02/20/6003) - India Int Ins

Hi Sun Pin,

Attached herewith our copy and your marked copy of the bus repair estimate for the case.
Our finalised amount is \$527.00 @ 1 working day under part by part repair. Attached after repair photos for your perusal.

Please confirm the COR by return email ASAP.

Thank you

Best Regards