

ANNEX A

REPAIR DETAILS

Recommended Parts

No	Qty	Description	Condition	Repairer's Amount	Adjuster's Amount
1	1	Front bumper assy (AMG Sport) <i>cra</i>	deformed/cracked	\$ 2,880.10	\$ 1,113 2,880.10
2	2	Front bumper lower bracket <i>rec</i>	LH bent/necessary <i>RA-SK</i>	\$ 183.20	\$ 91.60 183.20
3	2	Front bumper side retainer <i>rec</i>	bent/necessary	\$ 210.60	\$ 135 210.60
4	1	Front bumper tow cover <i>mis</i>	missing	\$ 90.20	\$ 72 90.20
5	1	Front bumper reinforcement <i>BT</i>	dented	\$ 392.30	\$ 392.30
6	1	Front bumper lower grille <i>cra</i>	cracked	\$ 281.10	\$ 198 281.10
7	1	Front bumper lower spoiler <i>cra</i>	cracked	\$ 2,220.50	\$ 1020 2,220.50
8	1	Front grille assy (AMG Sport) <i>DEF</i>	warped/necessary	\$ 988.80	\$ 656 988.80
9	1	Front grille emblem <i>rec</i>	necessary	\$ 151.20	\$ 80 151.20
10	1	Front right fender assy <i>BUC</i>	deformed	\$ 1,455.20	\$ 755 1,455.20
11	1	Front left fender assy <i>DD(R) X</i>	dented	\$ 1,455.20	\$ 1,455.20
12	1	Front right fender Turbo AMG emblem <i>rec</i>	necessary	\$ 125.40	\$ 68 125.40
13	1	Front left fender Turbo AMG emblem <i>rec</i>	necessary	\$ 125.40	\$ 68 125.40
14	1	Front bonnet assy <i>BUC</i>	dented	\$ 2,851.50	\$ 1990 2,851.50
15	1	Front support top panel <i>DD</i>	dented	\$ 1,140.40	\$ 1,140.40
16	1	Front support panel top garnish <i>xnn</i>	necessary	\$ 133.40	\$ 133.40
17	1	Front left support side panel <i>DD</i>	cracked	\$ 369.80	\$ 369.80
18	1	Front right support side panel <i>X(R)</i>	cracked	\$ 369.80	\$ 369.80
19	1	Front left support panel side garnish <i>cra</i>	cracked	\$ 116.70	\$ 116.70
20	1	Front right support panel side garnish <i>xnn</i>	cracked	\$ 116.70	\$ xnn 116.70
21	2	Front lock mechanism <i>BT</i>	LH bent/necessary <i>RA-SK</i>	\$ 195.00	\$ 182 195.00
22	1	Front lock mechanism bracket <i>rec</i>	bent/necessary	\$ 95.00	\$ 45 95.00
23	1	Front left xenon headlamp with module <i>cra</i>	cracked	\$ 3,640.80	\$ 3100 3,640.80
24	1	Front right xenon headlamp with module <i>xnn</i>	cracked	\$ 3,640.80	\$ 3,640.80
25	1	Front left spray nozzle <i>X(R)</i>	malfunction	\$ 291.30	\$ 291.30
26	1	Front right spray nozzle <i>X(R)</i>	malfunction	\$ 291.30	\$ 291.30
27	1	Front air-con condenser assy <i>xnn</i>	cracked/bent	\$ 1,256.50	\$ 1,256.50
28	1	Front air-con high pressure pipe <i>xnn</i>	bent/necessary	\$ 316.60	\$ 316.60
29	1	Front air-con low pressure pipe <i>xnn</i>	bent/necessary	\$ 292.60	\$ 292.60
30	1	Front radiator assy <i>xnn</i>	cracked/bent	\$ 1,450.70	\$ 1,450.70
31	1	Front radiator fan cowling with motor assy <i>xnn</i>	cracked/malfunction	\$ 1,427.40	\$ 1,427.40
32	1	Front radiator top hose <i>xnn</i>	warped/necessary	\$ 140.40	\$ 140.40
33	1	Front radiator bottom hose <i>xnn</i>	warped/necessary	\$ 140.40	\$ 140.40
34	1	Front radiator top cover <i>xnn</i>	cracked/necessary	\$ 165.70	\$ 165.70
35	1	Front radiator expansion tank assy <i>xnn</i>	necessary	\$ 134.60	\$ 134.60
36	1	Front left chassis member <i>X(R)</i>	bent	\$ 789.10	\$ 789.10
37	1	Front right chassis member <i>X(R)</i>	bent	\$ 789.10	\$ 789.10
38	1	Front left xenon headlamp support bracket <i>cra</i>	cracked	\$ 295.10	\$ 195 295.10
39	1	Front right xenon headlamp support bracket <i>xnn</i>	cracked	\$ 295.10	\$ 295.10
				\$ 12296.8	\$ 31,305.00
				\$ 1229.68	\$ 3,130.50
Less 10%				\$ 11067.12	\$ 28,174.50