

ASS. REC. BY:

REF:

es/CTI 2000 3063 / Rlsd3

n2

Special Instructions:

Surveyor: Rasul

ASSIGNMENT (Office)

From (Person): Ben Tang

of CTI

Date/Time: 24/2/2020 1:59pm

Estimated Cost:

Bill to:

OT / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SLG 9065A

Insured:

GU 4030T

at Workshop m/n

Kah motor

Tel:

9678 6493

of

15 ubi Road 4

Policy No:

Claim No:

3NM20D200938/GU4030T/BEN

Sum Insured:

Excess:

Make of Vela:

(Client's Record)

D.O.A. 21/02/2020

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 2:22pm @ 24/2/2020

Person Contacted:

poh soon

Vehicle

IN/OUT

Date/Time

Action/Instruction

1-shmale ✓

SLG 9065A-X

GU 4030T-NM / INC 10007497 / 11

20A: 17/4/2020

ASS. REC. BY:

REF:

CTI

2550

ASSIGNMENT

From:

Date:

24/2/2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SLG 9065 A

at Workshop m/s

Kah Motor

of

15 ubi Road 4

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

poh soon @ 9678 6493

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLG 9065A

Yr Regn:

2016 / 04

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

HONDA CITY 1.5 SV CVT c.c. 1497

Colour

MAROON

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MRHGM6660HP000272

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/55R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

21/02/2020

D.O.I.

24/02/2020

Survey held at

KAH MOTOR

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

0/3 FR

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Recd Confirmed P/P \$ 4,021.56 @ 5 days with
(\$ 3,742.75 Red - 48%)

RECEIVED 30 MAR 2020

30/3/2020

Date/Time, File Pass to?

30/03/20

1)

Type

Date/Time, File Return to?

2)

Report Format:

Lump Sum / L.B.I. (\$

4,021.56 r/p

Days Of Repair:

5

Resurvey No. of Trip:

1

Add Fee:



Site Insp (\$



Interview (\$



Tech. Invs (\$



Week-end (\$

Survey Fee:

Transportation:

\$ + RS. \$

Phone

Others

TOTAL

220

Nivitha (LKK Auto)

From: Ben Tang <Ben.Tang@sg.cntaiping.com>
Sent: Monday, 24 February 2020 1:59 PM
To: assignments
Subject: FW: OUR REF: SNM20D200938/GU4030T/BEN - DIRECT SETTLEMENT OF VEHICLE NO. SLG9065A AGAINST GU4030T

Dear Sirs

We refer to above matter.

Please assist to arrange for PRS survey of TP vehicle SLG9065A.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: You Po Soon <psyous@honda.com.sg>
Sent: Monday, February 24, 2020 1:25 PM
To: Ben Tang <Ben.Tang@sg.cntaiping.com>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: RE: OUR REF: SNM20D200938/GU4030T/BEN - DIRECT SETTLEMENT OF VEHICLE NO. SLG9065A AGAINST GU4030T

DeaR BEN,

We would like to choose as per below to conduct this case survey : -

XING QUO QIANG

Thank you

Best Regards,

You Po Soon
Bodyshop Service Advisor
Kah motor Co. Sdn Bhd
15, Ubi Road 4

Singapore 408610
E-mail : psyou@honda.com.sg
TEL : 9678 6493

From: Ben Tang <Ben.Tang@sg.cntaiping.com>
Sent: Monday, 24 February 2020 1:21 PM
To: You Po Soon <psyou@honda.com.sg>
Cc: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Subject: RE: OUR REF: SNM20D200938/GU4030T/BEN - DIRECT SETTLEMENT OF VEHICLE NO. SLG9065A AGAINST GU4030T

WITHOUT PREJUDICE

Dear Sir,

We refer to your email dated 22 February 2020.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

LKK / LBS / STA

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

If we do not hear from you within two days of this letter, you shall have deemed to have agreed that the surveyor appointed by us shall be Single Joint Expert for this matter.

Thank you.

Best Regards
Ben Tang
Executive
Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #XX-00 Springleaf Tower Singapore 079909
DID: (65) 6389 6175 | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: Claims Dept of CTI
Sent: Monday, February 24, 2020 12:12 PM
To: Ben Tang <Ben.Tang@sg.entaiping.com>; psyou@honda.com.sg
Cc: Claims Dept of CTI <claimsdept@sg.entaiping.com>
Subject: OUR REF: SNM20D200938/GU4030T/BEN - DIRECT SETTLEMENT OF VEHICLE NO. SLG9065A AGAINST GU4030T

Dear Ben,

Please conduct PRS for SLG9065A.

Note : officer in charge – Ben Tang 63896175.

*** Kindly quote our reference number when replying.

Thank you

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #15-00 Springleaf Tower Singapore 079909
DID: (65) 63896116 | F: (65) 62247175

W: www.sg.entaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG

Disclaimer: This e-mail and any files transmitted with it is intended only for the named recipients and may contain confidential information. Any unauthorized disclosure, use or dissemination of this message, either in whole or partial, is prohibited. If you are not the intended recipient, please notify the sender immediately. Please delete the e-mail and any copies of it thereafter.

From: You Po Soon <psyou@honda.com.sg>
Sent: Saturday, February 22, 2020 8:33 AM
To: Claims Dept of CTI <claimsdept@sg.entaiping.com>
Subject: DIRECT SETTLEMENT OF VEHICLE NO. SLG9065A AGAINST GU4030T

To The Officer In Charge,

Please Refer The Above Attachment For Your Reference.

Kindly Advice on Liability,

Kindly Help To Arrange Surveyor To Survey This Vehicle SLG6065A.


Your Insured vehicle number is GU4030T, Accident Date 21/2/2020.

Thank You

Best Regards,

You Po Soon
Bodyshop Service Advisor
Kah motor Co. Sdn Bhd
15, Ubi Road 4

Singapore 408610
E-mail : psy@honda.com.sg
TEL : 9678 6493



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/02/2020 18:17
Date Of Accident	21/02/2020 12:30
Exact Location Of Accident	CAR PARK AT BUKIT TIMAH LINK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG9065A
Insured/Policyholder	
Name Of Registered Owner	ISABEL CHLOE TAN CJINH PING
NRIC No	SXXXX255D
Email Address	ISABELCTAN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-83898269
Alternative Phone No	OTHERS-83898269

Vehicle Particulars

Manufacturer	HONDA
Model	CITY-1.5 L I-VTEC (A)
Exact Purpose for which vehicle was being used at time of accident	PARKED VEHICLE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD18V10516/VPC2/R01
Cover Note Number	

Driver

Name of Driver	ISABEL CHLOE TAN CJINH PING
NRIC No	SXXXX255D
Date Of Birth	06/04/1976
Occupation	INDOOR
Date Of Driving Pass	23/09/1995
Driving Experience	24 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-83898269
Fax Number	
Contact Number	OTHERS-83898269
EMail Address	ISABELCTAN@GMAIL.COM

Address	10 JALAN JAMBU MAWAR SINGAPORE
Postcode	588671
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	HIT AND RUN / VANDALISM / DAMAGED WHILST PARKED
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACHED STATEMENT - THIRD PARTY DIRECT SETTLEMENT

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GU4030T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	NG BA BI
NRIC/Passport Number	SXXXX351A
Contact Number	98346815
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Vehicle Number: SLH4065ASKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
 - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



 Policyholder's Signature
 Date & Time: 21/02/2020

 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:


 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Vehicle Number: SLG9065A

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I returned to my car at about 12.30pm on 21/02/2020 and found the car was damaged. Mr Ng Ba Bi left a note for me to contact him.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE (S'PORE) PTE	Document No.	: SQT20000862	Page	1
	3 ANSON ROAD #16-00	Date	: 22. Feb 2020		
	SPRINGLEAF TOWER	Customer No.	: WZC008		
	SINGAPORE 079909	Svc Advisor	: YOU PO SOON		
Registration No	: SLG9065A	Engine No	: L15Z14112407		
Chassis No	: MRHGM6660HP000272	Date Time	: 22. Feb 2020 8:03:03 AM		
Model	: CITY 1.5SV CVT 2017	Surveyor Name	:		
Owner's Name	: ISABEL CHLOE TAN CJINH PING	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 21/2/2020				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: ISABEL CHLOE TAN CJINH PING						
	OWNER INSURER: LIBERTY INSURANCE						
	ACC DATE: 21-02-2020						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: C.TAIPING INSURANCE						
	TP VEH: GU4030T						
71101-T9A-T00ZZ	FACEFR.BUMPER <i>CR</i>	1	459.80	5	436.81	30.58	467.39 ✓
71193-T9A-T00	SPACERR.FR.BUMPER SIDE <i>CR</i>	1	10.40	5	9.88	0.69	10.57 ✓
71198-T9A-T00	SPACERL.FR.BUMPER SIDE <i>X SVC</i>	1	10.40	5	9.88	0.69	10.57
71130-T9A-T00ZZ	BEAM COMPFR.BUMPER <i>X SVC</i>	1	265.60	5	252.32	17.66	269.98
71102-T9A-T50	GARNISHR.FR.FOGLIGHT <i>X SVC</i>	1	23.60	5	22.42	1.57	23.99
91505-TM8-003	CLIP.BUMPER <i>CR</i>	26	2.30	5	56.81	3.98	60.79 ✓
71140-T9A-T00	BEAMR.FR.BUMPER UPPER <i>CR</i>	1	27.50	5	26.12	1.83	27.95 ✓
71190-T9A-T00	BEAML.FR.BUMPER UPPER <i>X SVC</i>	1	27.50	5	26.12	1.83	27.95
71104-T9A-T00ZB	COVERFR.TOWING HOOK T99 <i>X SVC</i>	1	14.80	5	14.06	0.98	15.04
71103-T9A-T00	GRILLEFR.BUMPER LOWER <i>X SVC</i>	1	88.00	5	83.60	5.85	89.45
71121-T9A-T00	BASEFR.GRILLE <i>CR</i>	1	86.90	5	82.55	5.78	88.33
71122-T9A-T20	MOLDINGFR.GRILLE UPPER <i>X SVC</i>	1	189.00	5	179.55	12.57	192.12
75700-TF0-000	EMBLEM (H) <i>CR</i>	1	22.90	5	21.75	1.52	23.27 ✓
90301-ST0-003	NUTPUSH 3MM <i>CR</i>	2	2.10	5	3.99	0.28	4.27 ✓
71125-T9A-T10	MOLDINGFR.GRILLE LOWER <i>X SVC</i>	1	45.10	5	42.84	3.00	45.84
60210-T9A-T50ZZ	PANEL COMP.R FR FENDER <i>Turn</i>	1	343.80	5	326.61	22.86	349.47 ✓
74100-T9A-T00	FENDER ASSYR.FR INNER <i>CR</i>	1	76.80	5	72.96	5.11	78.07 ✓
91501-TR0-003	CLIP INNER FENDER <i>CR</i>	11	2.80	5	29.26	2.05	31.31 ✓
74105-T9A-T10	ENCLOSURER.FR.FENDER <i>CR</i>	1	7.30	5	6.93	0.49	7.42 ✓

Printed on 22/2/2020 8:26:33 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE (S'PORE) PTE	Document No.	: SQT20000862	Page	2
	3 ANSON ROAD #16-00	Date	: 22. Feb 2020		
	SPRINGLEAF TOWER	Customer No.	: WZC008		
	SINGAPORE 079909	Svc Advisor	: YOU PO SOON		
Registration No	: SLG9065A	Engine No	: L15Z14112407		
Chassis No	: MRHGM6660HP000272	Date Time	: 22. Feb 2020 8:03:03 AM		
Model	: CITY 1.5SV CVT 2017	Surveyor Name	:		
Owner's Name	: ISABEL CHLOE TAN CJINH PING	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 21/2/2020				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
91555-T9D-K01	CLIPAMBIENT SENSOR <i>X Svc</i>	1	1.30	5	1.23	0.09	1.32
33100-T9A-T01	HEADLIGHT ASSY,R <i>CR</i>	1	324.10	5	307.89	21.55	329.44
33900-T0A-H01	LIGHT ASSYFR.FOG <i>X Svc</i>	1	277.90	5	264.00	18.48	282.48
04674-T9A-T00ZZ	EXTENSION SETR.FR.SHOCK ABS <i>repair</i>	1	91.80	5	87.21	6.10	93.31
60844-T9A-T00ZZ	PLATER.SIDE FRAME GUSSET <i>X Svc</i>	1	48.50	5	46.07	3.22	49.29
60845-T9A-T00ZZ	GUSSETR.FR.SIDE FRAME <i>X Svc</i>	1	59.10	5	56.14	3.93	60.07
42700-T9A-T91	DISKALUMINIUM WHEEL 16X6J <i>X Svc</i>	1	407.70	5	387.31	27.11	414.42
Sum Item					2854.31	199.80	3,054.11

BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4 <i>X M</i>	1	180.00		180.00	12.60	192.60
Sum Ext. Service					180.00	12.60	192.60

BOSUN	SUNDRIES <i>REL</i>	1	50.00 <i>20</i>		50.00	3.50	53.50
BOJSE	BODY JOINT SEALANT	1	100.00 <i>X M</i>		100.00	7.00	107.00
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	180.00 <i>150</i>		180.00	12.60	192.60
BKBH11S	REPAIR BULKHEAD & CUT WHEELHOUSE EXTENSION	1	2400.00 <i>1120</i>		2400.00	168.00	2568.00
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (4P)	1	2000.00 <i>1350</i>		2000.00	140.00	2140.00
Sum Labor					4730.00	331.10	5,061.10

Survey By	<i>RASUL - Hp 90010068</i>	Total Amount	7,764.31	543.50	8,307.81
Date & Time	<i>24/02/2020 @ 1616</i> <i>5 days</i>	Total (Inclusive of GST)			8,307.81
Excess					
Status	<i>Repair after fire print</i>				
Signature	<i>[Signature]</i>				

LIK Auto Consultants works only
the Repaired of the following:

- Is repaired before/after spray painting
- To display damaged part/during recovery
- Parts prices are subject to confirmation
- Third party survey is via a "Third Party" body
- No legal action will be taken
- Supplementary item(s) must be inspected and is subject to final approval from insurance Company

Printed on 22/2/2020 8:26:33 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

Acknowledged by Repaired

Signature



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: CU0102538 / CHINA TAIPING
 Chassis No: MRHGM6660HP000272
 License No: SLG9065A
 Mileage: 38282
 Engine No: L15Z14112407

Document No: SVO20012709
 Printed By: PSYOU
 Order Date: 25. February 2020
 Order Time: 7:05:48 PM
 Service Advisor: YOU PO SOON

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Incl GST
	TP DIRECT SETTLEMENT (J/NO: 74352) OWNER: ISABEL CHLOE TAN CJINH PING OWNER INSURER: LIBERTY INSURANCE ACC DATE: 21-02-2020 SURVEYED BY: RASUL DATE: 24-2-2020 REF NO: TP INSURER: C.TAIPING INSURANCE TP VEH: GU4030T						
71101-T9A-T00ZZ	FACEFR.BUMPER	1	459.80	5	436.81	30.58	467.39 ✓
71193-T9A-T00	SPACERR.FR.BUMPER SIDE	1	10.40	5	9.88	0.69	10.57 ✓
91505-TM8-003	CLIP,BUMPER	26	2.30	5	56.81	3.98	60.79 ✓
71140-T9A-T00	BEAMR.FR.BUMPER UPPER	1	27.50	5	26.12	1.83	27.95 ✓
71121-T9A-T00	BASEFR.GRILLE	1	86.90	5	82.55	5.78	88.33 ✓
75700-TF0-000	EMBLEM (H)	1	22.90	5	21.75	1.52	23.27 ✓
90301-ST0-003	NUTPUSH 3MM	2	2.10	5	3.99	0.28	4.27 ✓
60210-T9A-T50ZZ	PANEL COMP,R.FR.FENDER	1	343.80	5	326.61	22.86	349.47 ✓
74100-T9A-T00	FENDER ASSYR.FR INNER	1	76.80	5	72.96	5.11	78.07 ✓
91501-TR0-003	CLIP,INNER FENDER	11	2.80	5	29.26	2.05	31.31 ✓
33100-T9A-T01	HEADLIGHT ASSY,R	1	324.10	5	307.89	21.55	329.44 ✓
74105-T9A-T10	ENCLOSURER.FR.FENDER	1	7.30	5	6.93	0.49	7.42 ✓
	SUM PARTS:				1,381.56	96.72	1,478.28
BOSUN	0760	1	20.00 ✓		20.00	1.40	21.40
	SUNDRIES						
BML01I	EXT-YJ	1	150.00 ✓		150.00	10.50	160.50
	INSPECT FR LIGHTING MECHANISMS & FOCUS						
	HEADLIGHTS.(N)						
BKBH11S	EXT-YJ	1	1,120.00 ✓		1,120.00	78.40	1,198.40
	REPAIR BULKHEAD & CUT WHEELHOUSE EXTENSION INCLUDING FITTINGS ON ATTACHMENT ITEMS.						
BP04R	EXT-YBH	1	1,350.00 ✓		1,350.00	94.50	1,444.50
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(4P)						
	SUM LABOUR:				2,640.00	184.80	2,824.80
	TOTAL SGD				4,021.56	281.52	4,303.08
	Total Payable (SGD)						4,303.08

GST Amount is calculated from individual line(s)

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20003063/R1SD3N2
Date: 01/04/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN30165519000
Claimant Vehicle No :	SLG9065A	Insured Vehicle No :	GU4030T
Date of Loss:	21/02/2020	Nature of Claim:	TP
		Claim No:	SNM20D200938

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLG9065A	Engine No:	L15Z14112407
Make & Model:	HONDA CITY, 1.5 VTEC (A)	Chassis No:	MRHGM6660HP000272
Reg. Date:	18/10/2016 (Man. Year: 2016)	Odometer:	0 km
Colour:	Maroon		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55R16	Rear Tyre Size:	185/55R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,904.31	1,401.56	1,502.75	51.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,860.00	2,620.00	2,240.00	46.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,764.31	4,021.56	3,742.75	48.20
+ GST 7.00/7.00% (S\$)	543.50	281.51	261.99	48.20
Nett Amount (S\$)	8,307.81	4,303.07	4,004.74	48.20

INSPECTION

Date of Assignment:	30/03/2020		
Date Inspected:	24/02/2020	Inspected At:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4 Singapore 408610
Estimated Period of Repair:	5.0 days		

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Apr 2020)
Parts:	143	HONDA CITY 1.5 VTEC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLG9065A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FACEFR BUMPER	Cracked	436.81 FS	*436.81 FS
2	1		*SPACERR FR BUMPER SIDE	Necessary	9.88 FS	*9.88 FS
3	1		*SPACERL FR BUMPER SIDE	Serviceable	9.88 FS	*- FS
4	1		*BEAM COMPFR BUMPER	Serviceable	252.32 FS	*- FS
5	1		*GARNISHR FR FOGLIGHT	Serviceable	22.42 FS	*- FS
6	1		*CLIP,BUMPER (26 Pcs)	Necessary	56.81 FS	*56.81 FS
7	1		*BEAMR FR BUMPER UPPER	Cracked	26.12 FS	*26.12 FS
8	1		*BEAML FR BUMPER UPPER	Serviceable	26.12 FS	*- FS
9	1		*COVERFR TOWING HOOK T99	Serviceable	14.06 FS	*- FS
10	1		*GRILLEFR BUMPER LOWER	Serviceable	83.60 FS	*- FS
11	1		*BASEFR GRILLE	Cracked	82.55 FS	*82.55 FS
12	1		*MOLDINGFR GRILLE UPPER	Serviceable	179.55 FS	*- FS
13	1		*EMBLEM H	Necessary	21.75 FS	*21.75 FS
14	1		*NUTPUSH 3MM (2 Pcs)	Necessary	3.99 FS	*3.99 FS
15	1		*MOLDINGFR GRILLE LOWER	Serviceable	42.84 FS	*- FS
16	1		*PANEL,COMP R FR FENDER	Torn	326.61 FS	*326.61 FS
17	1		*FENDER ASSYR FR INNER	Cracked	72.96 FS	*72.96 FS
18	1		*CLIP,INNER FENDER (11 Pcs)	Necessary	29.26 FS	*29.26 FS
19	1		*ENCLOSURER FR FENDER	Cracked	6.93 FS	*6.93 FS
20	1		*CLIPAMBIENT SENSOR	Serviceable	1.23 FS	*- FS
21	1		*HEADLIGHT ASSY,R	Cracked	307.89 FS	*307.89 FS
22	1		*LIGHT ASSYFR FOG	Serviceable	264.00 FS	*- FS
23	1		*EXTENSION SETR FR SHOCK ABS	Repair	87.21 FS	*- FS
24	1		*PLATER SIDE FRAME GUSSET	Serviceable	46.07 FS	*- FS
25	1		*GUSSETR FR SIDE FRAME	Serviceable	56.14 FS	*- FS
26	1		*DISKALUMINIUM WHEEL 16X6J	Serviceable	387.31 FS	*- FS
27	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	2,904.31	1,401.56
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	WHEEL ALIGNMENT X4	New	180.00	0.00
2	BODY JOINT SEALANT	New	100.00	0.00
3	INSPECT FR LIGHTING MECHANISMS & FOCUS	New	180.00	150.00
4	REPAIR BULKHEAD & CUT WHEELHOUSE EXTENSION	New	2,400.00	1,120.00
5	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (4P)	New	2,000.00	1,350.00
Gross Labour Cost (S\$)			4,860.00	2,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >