

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

22/02/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TP Ax A.
Xiao Tang

Accident date: 22/02/2022

Estimated repair cost for vehicle no: SLD1994L MITSUBISHI ATTRAGE 1.2 A '19

CHASSIS:

S/n	Qty	Items	U/price	Amount	
1	1	Rear Boot Lid <i>Dented</i>		\$854.20	✓
2	2	Rear Boot Lid Hinge <i>new</i>	\$234.00	\$468.00	+
3	1	Rear Boot Lid Emblem Logo <i>2</i>		\$45.50	✓
4	1	Rear Boot Lid Attrage Logo <i>free</i>		\$32.50	✓
5	1	Rear Boot Lid Cc Logo		\$35.00	✓
6	2	Rear Boot Lid Number Plate Lamp <i>new</i>	\$58.30	\$116.60	+
7	1	Rear Boot Lid Center Chrome Moulding <i>free</i>		\$206.30	+
8	1	Rear Boot Lid Outer Lock Switch Button		\$85.70	+
9	1	Rear Boot Lid Inner Lock <i>Damaged</i>		\$198.70	✓
10	1	Rear Boot Lid Inner Rubber <i>lid</i>		\$180.20	✓
11	2	Rear Tail Lamp <i>at</i>	\$336.50	\$673.00	✓
12	4	Rear Tail Lamp Clip <i>new</i>	\$8.00	\$32.00	20
13	2	Rear Tail Lamp Panel <i>Repis</i>	\$169.20	\$338.40	+
14	1	Rear Bumper <i>Distorted</i>		\$835.50	✓
15	10	Rear Bumper Clip <i>new</i>	\$6.50	\$65.00	30
16	2	Rear Bumper Side Retainer <i>new</i>	\$47.30	\$94.60	✓
17	2	Rear Bumper Side Reflector <i>not new</i>	\$44.20	\$88.40	+
18	2	Rear Fender <i>Repis</i>	\$843.80	\$1,687.60	+
19	2	Rear Fender Inner Panel <i>Repis</i>	\$375.70	\$751.40	+
20	2	Rear Fender Cowling <i>free</i>	\$39.80	\$79.60	+
21	16	Rear Fender Cowling Clip <i>new</i>	\$6.50	\$104.00	+
22	2	Rear Fender Inner Trim Board <i>new new</i>	\$487.60	\$975.20	+
23	16	Rear Fender Inner Trim Board Clip <i>new</i>	\$6.50	\$104.00	+
24	1	Rear End Panel <i>Dented</i>		\$397.50	✓
25	1	Rear End Panel Top Garnish <i>Deformed</i>		\$145.50	✓
26	1	Rear Spare Tyre Panel Assy <i>Repis</i>		\$1,427.30	+
27	1	Rear Spare Tyre Panel Carpet <i>not new</i>		\$248.70	+
28	1	Rear Spare Tyre Panel Top Cover <i>to be</i>		\$304.20	✓
29	1	Rear Exhaust <i>not new</i>		\$604.90	+

30	2	Rear Exhaust Mounting	2 MP	\$38.70	\$77.40	*
31	1	Rear Center Exhaust	2 MP		\$1,204.70	*
				3846.40	Subtotal:-	\$12,461.60
				3461.76		

S/n	Qty	Items / Special Nett	U/price	Amount	
1	1	Rear Boot Lid Number Plate	200	\$50.00	
4	1	Rear Bumper Reverse Sensor	Damaged	\$380.00 200	
				Subtotal:-	\$430.00

Labour charges

To remove & refit reverse sensor	\$120.00	50
To remove & refit rear exhaust	\$280.00	*
To check wiring	\$150.00	30
Tuff kote	\$150.00	60
Towing fee	\$150.00	*
Panel beating	\$2,400.00	100
Spray painting	\$2,000.00	100
Subtotal :-	\$5,250.00	

Total:- \$18,141.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Adrian Lij
M/S 24/02/20
06 days
total: 5801.76.
M/S : A.B.K.
4.61K