

ESTIMATE

Our Ref: AC2020012/TP/SKU1163R- 20.02.2020

Vehicle number: SKU1163R

Vehicle Made & Model: TOYOTA ALPHARD

Items	Qty	List Items	Amount \$
1	1	Front bumper <i>cr</i>	<i>\$1580</i> 1,806.45
2	1	Front bumper fog lamp - RH <i>1xnn</i>	395.45
3	1	Front bumper fog lamp cover - RH <i>1xnn</i>	148.35
4	1	Front bumper PDC sensor - RH <i>1xnn</i>	391.65
5	2	Front bumper side retainers - L/R @ 84.45 <i>xnn</i>	168.90
6	1	Front fender - RH <i>xnn</i>	1,082.60
7	1	Front headlamp - RH <i>scr</i>	<i>\$2022</i> 3,682.50
8	1	Front shock absorber - RH <i>1xnn</i>	581.90
9	1	Front shock absorber top mount <i>1xnn</i>	221.50
10	1	Front lower arm <i>scr</i>	<i>\$513</i> 760.90
11	1	Front lower arm ball joint <i>1xnn</i>	216.20
12	1	Front knuckle arm <i>1xnn</i>	631.50
13	1	Front wheel hub <i>1xnn</i>	480.60
14	1	Front wheel bearing <i>scr, nec</i>	<i>\$160</i> 215.60
15	1	Front anti roll bar <i>xnn</i>	341.60
16	1	Front anti roll bar link <i>xnn</i>	186.10
17	1	Washer tank <i>1xnn</i>	286.90
Sub-total			11,598.70
Less 25%			2,899.68
Total List			8,699.03

3206.25

Special Nett Items			
18	1	Front sport wheel <i>scr</i>	<i>\$600</i> 1,200.00
19	1	Front tyre <i>xnn</i>	650.00
20	1 set	Front bumper clip <i>nec</i>	45.00
Total Special Nett			1,895.00

<u>Labour charges</u>		
21	To check front electrical wiring	50.00
22	To remove, refix front undercarriage	350.00
23	To check wheel alignment	120.00
24	To respray undercoating	60.00
25	To respray painting and etc	800.00
26	Panel beating, cut, weld remove & replacing above parts	800.00
Total Labour		2,180.00

RAM (LKK)
25/02/2020
mesaram@lkkauto.com
88622778
3 repair days

xnn
\$80
\$350
\$400

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

L/S: \$3800
12,774.03