

ESTIMATE

Our Ref: AC2020012/TP/SKU1163R- 20.02.2020

Vehicle number: SKU1163R

Vehicle Made & Model: TOYOTA ALPHARD

Items	Qty	List Items	Amount \$
1	1	Front bumper <i>cra</i>	<i>\$1580</i> 1,806.45
2	1	Front bumper fog lamp - RH <i>1xnn</i>	395.45
3	1	Front bumper fog lamp cover - RH <i>1xnn</i>	148.35
4	1	Front bumper PDC sensor - RH <i>1xnn</i>	391.65
5	2	Front bumper side retainers - L/R @ 84.45 <i>xnn</i>	168.90
6	1	Front fender - RH <i>xnn</i>	1,082.60
7	1	Front headlamp - RH <i>scr</i>	<i>\$2022</i> 3,682.50
8	1	Front shock absorber - RH <i>1xnn</i>	581.90
9	1	Front shock absorber top mount <i>1xnn</i>	221.50
10	1	Front lower arm <i>scr</i>	<i>\$93</i> 760.90
11	1	Front lower arm ball joint <i>xnn</i>	216.20
12	1	Front knuckle arm <i>xnn</i>	631.50
13	1	Front wheel hub <i>xnn</i>	480.60
14	1	Front wheel bearing <i>scr</i>	<i>\$160</i> 215.60
15	1	Front anti roll bar <i>xnn</i>	341.60
16	1	Front anti roll bar link <i>xnn</i>	186.10
17	1	Washer tank <i>1xnn</i>	286.90

Sub-total 11,598.70
Less 25% 2,899.68
Total List 8,699.03

3206.25

<u>Special Nett Items</u>			
18	1	Front sport wheel <i>scr</i>	<i>\$600</i> 1,200.00
19	1	Front tyre <i>xnn</i>	650.00
20	1 set	Front bumper clip <i>scr</i>	45.00

Total Special Nett 1,895.00

<u>Labour charges</u>	
21	To check front electrical wiring
22	To remove, refix front undercarriage
23	To check wheel alignment
24	To respray undercoating
25	To respray painting and etc
26	Panel beating, cut, weld remove & replacing above parts

Ram (LKC)
25/02/2020
mesuram@lkc-auto.com
88622772
3 repair days

	50.00
	350.00 <i>xnn</i>
	120.00 <i>\$80</i>
	60.00
	800.00 <i>\$350</i>
	800.00 <i>\$400</i>
Total Labour	2,180.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

L/S: \$3800
12,774.03