

22/03/2002

ASS. REC. BY:

REF: CS/CTI 20003074 Rlyf3

Special Instruction:

Surveyor: Rusu

ASSIGNMENT (Office)

From (Person): Irene Tay Hui Ping of CTIDate/Time: 24.2.2020 1535

Estimated Cost:

OD TP/WS/TP RES/OD RES/EVA/INV/MV/CSTo Inspect Vehicle No: YP 44T

Insured:

Tel: 62686183at Workshop m/s Sng Ah Tzeof BK 3 Pio Nur Road NUA h #01-18Policy No: DMCVSN 3079901900Claim No: SNM200200813/YP44T/IRENEExcess: \$500.00

Sum Insured:

D.O.A. 11-2-2020

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 24/2/2020 3.41p.m

Person Contacted:

Samman

H.O.D. Endorsement:

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>YP 44T - CS/CTI 18006373/UVd3q.2</u> <u>D.O.A - 10/03/2018</u>
<u>28/2/20</u>	<u>Recd approved from Alfred by merimen</u>
<u>2/3/20</u>	<u>Informed Joyce c/A LS not exceeding \$33000/ ex \$500 by email</u>

ASS. REC. BY:

REF:

7354

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

① TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: YP 44Tat Workshop m/s SNL AH TCC

of _____

Insured: CTI

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: 500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 44K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: YP 44T Yr Regn: 2015 / NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: MITSUBISHI CANTER FEB 21 C.C. 2998Colour: WHITE A/C: Insured / Std / NI / NASp. Reading: 306436 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: FEB 21 EA 10438 *

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: M5/85R15R: 2 2

③ BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 7 mm R/Bal. 7/7 mmL/Bal. 7 mm L/Bal. 7/7 mmD.O.A. 11/02/2020 D.O.I. 24/02/2020Survey held at SNL AH TCCDes. of Damages: Frnt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
<u>26/2</u>	<u>Revert Via Merimen</u>
<u>26/2</u>	<u>Wait for Workshop to call</u>
<u>28/2</u>	<u>Call Irene cannot reach in 3-00pm (Never Ans).</u>
<u>12/1/21</u>	<u>LS \$28,100 confirmed by email (Red 21,246.32,43%)</u>
	<u>\$28100/-</u>
	<u>Limit \$33K</u>

Date/Time, File Pass to?

☐ : Preli. ReportDays Of Repair: 20

1)

☐ : Final ReportResurvey No. of Trip: 1

Date/Time, File Return to?

2) 12/1/21-TypistAdd Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

____ S + RS. ____ SI

Photos

Others

TOTAL

Rep. Format: MerimenLump Sum / H.B. : \$28,100

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	19 Feb 2020 Sendback Est	19 Feb 2020 15:26 S\$41,846.32	24 Feb 2020 15:35 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	ADF WATERPROOF PTE. LTD., Co. Reg. No.: 200617735G		
Vehicle Reg. No.:	YP44T	Date of Loss:	11/02/2020 13:00 - :59 [0 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM20D200813/YP44T/IRENE	Policy/Cover Note No.:	DMCVSN3079901900 (Comprehensive)
		Excess:	S\$500.00
Repairer:	Sng Ah Tee Motor & Panel Service Pte Ltd (Pioneer) Blk 3 Pioneer Road North, #01-18, 628457 Pioneer - Tel: 6268 6183		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 04/03/2020]		
Driver/Custodian:	PARAMASIVAM RAJKUMAR (33 / Male) , NRIC: G8157925W, Tel: +6584324667 Email: delsonsh@gmail.com		
Adj Asg. Remarks:	PLEASE SURVEY AND REVERT		

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Monday, 2 March 2020 9:20 AM
To: admin@sngahtee.com; Yvonne Wong (LKK Auto); sharon@sngahtee.com
Cc: Rasul (LKKAUTO); sam@sngahtee.com; SUR
Subject: RE: OD VEHICLE YP44T DOA: 11/02/20

Dear Joyce,

As instructed by our client , please proceed to repair the **insured vehicle YP 44T Not exceeding Lump Sum \$33,000/- or whichever lower, (Excess \$500/-).**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler (ON BEHALF OF YVONNE)

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: admin@sngahtee.com <admin@sngahtee.com>
Sent: Friday, 28 February 2020 11:39 AM
To: Yvonne Wong (LKK Auto) <yvonnnewong@lkkauto.com>; sharon@sngahtee.com
Cc: Rasul (LKKAUTO) <Rasul@lkkauto.com>; sam@sngahtee.com
Subject: RE: OD VEHICLE YP44T DOA: 11/02/20

Dear Yvonne,

We accept \$33k lump sum repair.

Thanks

Best Regards

Joyce Tan

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



From: Yvonne Wong (LKK Auto) <yvonnewong@lkkauto.com>
Sent: Wednesday, February 26, 2020 6:42 PM
To: sharon@sngahtee.com; admin@sngahtee.com
Cc: Rasul (LKKAuto) <Rasul@lkkauto.com>; sam@sngahtee.com
Subject: OD VEHICLE YP44T DOA: 11/02/20

Dear Sir/Madam,

WITHOUT PREJUDICE

Kindly advise whether your workshop able to repair the above vehicle within \$33,000.00 on Part by Part basis or Lump Sum basis.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnewong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

YP44T (SNM20D200813/YP44T/IRENE)

OD

Feb 11 2020 1:00PM

[ADF WATERPROOF PTE. LTD.]

Sng Ah Tee Motor & Panel Service Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on **28/02/2020 14:37 PM.**

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$34236.00) - YP44T - Claim Handler: Irene Tay Hui Ping

Approved:34236.00:Please proceed to authorize repairs NO MORE THAN \$34,236.00 before Excess of \$500.00. Re-inspection of vehicle is required.

DOCUMENTS SUMMARY

There are no documents.

Yvonne Wong (LKK Auto)

From: admin@sngahtee.com
Sent: Friday, February 28, 2020 11:39 AM
To: Yvonne Wong (LKK Auto); sharon@sngahtee.com
Cc: Rasul (LKKAuto); sam@sngahtee.com
Subject: RE: OD VEHICLE YP44T DOA: 11/02/20

Dear Yvonne,

We accept \$33k lump sum repair.

Thanks

Best Regards

Joyce Tan

SNG AH TEE MOTOR & PANEL SERVICE PTE LTD | BLK 3 PIONEER ROAD NORTH #01-18 SINGAPORE 628457
TEL: 62686183 (4LINES) | FAX: 62681429 | Find us at <http://www.sngahtee.com>



From: Yvonne Wong (LKK Auto) <yvonnewong@lkkauto.com>
Sent: Wednesday, February 26, 2020 6:42 PM
To: sharon@sngahtee.com; admin@sngahtee.com
Cc: Rasul (LKKAuto) <Rasul@lkkauto.com>; sam@sngahtee.com
Subject: OD VEHICLE YP44T DOA: 11/02/20

Dear Sir/Madam,

WITHOUT PREJUDICE

Kindly advise whether your workshop able to repair the above vehicle within \$33,000.00 on Part by Part basis or Lump Sum basis.

Thank you.

Best Regards,

Yvonne Wong (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: yvonnewong@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

View Received Message

This mail is associated with :

YP44T (SNM20D200813/YP44T/IRENE)

OD

Feb 11 2020 1:00PM

[ADF WATERPROOF PTE. LTD.]

Sng Ah Tee Motor & Panel Service Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From China Taiping Insurance (Singapore) Pte. Ltd. (HQ) (CHINA_TAIPING), sent on 27/02/2020 10:44 AM.

To LKK_HQ

CC irene.tay@sg.cntaiping.com; CNTP_ALFRED

Subject Mandate for YP44T (SNM20D200813)

Dear Su Thing/Yvonne

We refer to the above and future cases.

Please confirmed with the repairer their Undertaking Amount for the repair, before putting up to **Adjuster Mandate Request**.

27	26 Feb 2020 12:16	Adj Mandate Request	Cur.Reg:40113.32:DAMAGED CONSISTENT. PENDING REPAIRER FOR REPAIR COST	[A] YVONNE WONG YIN CHENG
----	----------------------	--------------------------------	--	------------------------------

Adjuster Mandate Request box, supposed to be the area for confirmed of Mandate request.

Do come back to me if you are not clear.

Thanks

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front/rear/u/c portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	41,846.32
Revised Amount	:S\$	20,432.32
Check Items (Estimated)	:S\$	19,681.00
Total	:S\$	40,113.32

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	44,000.00
COE / PARF Rebate	:S\$	9,764.00
Salvage Value	:S\$	
Margin for Repair	:S\$	34,236.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : **Pending repairer for repair cost.**

Regards
Eddie Sim

DOCUMENTS SUMMARY

There are no documents.

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 26 Feb 2020

Preliminary Advice

Vehicle No	: YP44T	Accident Date	: 11/02/2020
Make	: MITSUBISHI CANTER	Policy No.	: DMCVSN3079901900
Assignment Date	: 24/02/2020	Excess	: S\$500.00
Date of Inspection	: 24/02/2020	Est. Duration of Repair	: 20.00
Inspection At	: SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-18 SINGAPORE 628457		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front/rear/u/c portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	41,846.32
Revised Amount	:S\$	20,432.32
Check Items (Estimated)	:S\$	19,681.00
Total	:S\$	40,113.32

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	44,000.00
COE / PARF Rebate	:S\$	9,764.00
Salvage Value	:S\$	
Margin for Repair	:S\$	34,236.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Pending repairer for repair cost.

26/2/2020

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	735G
Vehicle Details	
Vehicle No.:	YP44T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	26 Feb 2020
Vehicle Make:	MITSUBISHI
Vehicle Model:	CANTER FEB21ER4SDEB (CBU)
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	4P10B81197
Chassis No.:	FEB21EA10438
Maximum Power Output:	-
Open Market Value:	\$28,557.00
Original Registration Date:	12 Nov 2015
First Registration Date:	12 Nov 2015
Transfer Count:	1
Actual ARF Paid:	\$1,428.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	11 Nov 2025
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$17,091.00
COE Rebate Amount:	\$9,760.00
Total Rebate Amount:	\$9,760.00

The information contained herein is correct as at 26 Feb 2020

OK



Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 735G

Vehicle Details

Vehicle No.: YP44T

Vehicle to be Exported: No

Intended Deregistration Date: 25 Feb 2020

Vehicle Make: MITSUBISHI

Vehicle Model: CANTER FEB21ER4SDEB (CBU)

Primary Colour: White

Manufacturing Year: 2015

Engine No.: 4P10B81197

Chassis No.: FEB21EA10438





First Registration Date:	12 Nov 2015
--------------------------	-------------

Transfer Count:	1
-----------------	---

Actual ARF Paid:	\$1,428.00
------------------	------------

Intended PARF Rebate Details

PARF Eligibility:	No
-------------------	----

PARF Eligibility Expiry Date:	-
-------------------------------	---

PARF Rebate Amount:	\$0.00
---------------------	--------

Intended COE Rebate Details

COE Expiry Date:	11 Nov 2025
------------------	-------------

COE Category:	C - Goods Vehicle & Bus
---------------	-------------------------

COE Period(Years):	10
--------------------	----

PQP Paid:	\$17,091.00
-----------	-------------

COE Rebate Amount:	\$9,764.00
--------------------	------------

Total Rebate Amount:	\$9,764.00
----------------------	------------





Mitsubishi Fuso Canter FEB21

**\$44,800**

(90% loan at \$707/mth)

06-Nov-2015 (5yrs 8mths COE left)



DEPRE \$7,860 / yr

Bell Auto Pte Ltd

Mitsubishi Fuso Canter FEB21

**\$38,800**

(90% loan at \$628/mth)

15-Sep-2015 (5yrs 6mths COE left)



DEPRE \$6,980 / yr

Mitsubishi Fuso Canter FEB21

**\$42,800**

(90% loan at \$741/mth)

08-Apr-2015 (5yrs 1mth COE left)



DEPRE \$8,360 / yr

Index Credit

Sell your Car for \$3,000 More



With a 500+ Dealer Network, Car Auctions via sgCarMart Quotz typically get up to \$3,000 above market value. Highest Price Guaranteed in SG - or you get \$100 cash from us.

Find out more!

Mitsubishi Fuso Canter FEB21



-

03-Nov-2015 (5yrs 8mths COE left)



DEPRE -

ABWIN (1994) Pte Ltd

Mitsubishi Fuso Canter FEB21



-

19-May-2015 (5yrs 2mths COE left)



DEPRE -

Car Search



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/02/2020 18:00
Date Of Accident	11/02/2020 13:15
Exact Location Of Accident	ALONG PIONEER RD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	YP44T
Insured/Policyholder	
Name Of Registered Owner	ADF WATERPROOF PTE. LTD.
Co Reg No	2XXXXX735G
Email Address	ADMIN@ADF.SG
Mobile Phone No	(LOCAL) +65-98535119
Alternative Phone No	OFFICE-63627586

Vehicle Particulars

Manufacturer	MITSUBISHI
Model	CANTER-3.0 D FEB21 (M)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? YES

If No, Please state action to be taken

Vehicle Category	COMMERCIAL VEHICLE
------------------	--------------------

Insurance Company

Name of Insurance Company	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMCVSN3079901900
Cover Note Number	

Driver

Name of Driver	PARAMASIVAM RAJKUMAR
NRIC No	GXXXX925W
Date Of Birth	08/04/1986
Occupation	OUTDOOR
Date Of Driving Pass	21/02/2019
Driving Experience	0 YEAR AND 11 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-84324667
Fax Number	
Contact Number	
Email Address	DELSONSH@GMAIL.COM

Address	N/A
Postcode	
Was driver an employee of the Insured's Company	YES
If No, Relationship of the Driver with the Insured	
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PROPERTY
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	1
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : RAMU GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	NANYANG N.P.C
Police Station Address	ROAD: 2 JURONG WEST AVE 5 , POSTCODE: 649482 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7929999 - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT T/20200211/2129

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	
Vehicle Make/Model/Colour	
Details Of Properties	RAILING
Vehicle Category	GOVERNMENT
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE


1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:



Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

I AM AWARE THAT MY INSURER MAY HAVE A **14 DAYS TIMEFRAME** FOR ME TO SUBMIT AN OWN DAMAGE CLAIM UNDER MY OWN POLICY. I WILL CHECK MY POLICY FOR MORE DETAILS.

GENERAL SKETCH PLAN Pg. 1

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report T/20200211/2129

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:

P. P. P.

Driver's Signature
(If driver is not the policyholder)
Date & Time:

☒ Claim own policy
☐ Claim third party
☐ Claim OD / TP at other workshop
☐ For record purpose

Policy No. DMCVSN 3079901900
Insurer China Veh. No. YP44T

[Signature]
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

POLICE REPORT Pg. 1



**SINGAPORE
POLICE FORCE**



T/20200211/2129

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

1 of 3

Report No. T/20200211/2129

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 11/02/2020 20:40		Vide Report No.:		Station Diary No.: 128	
Informant's Particulars					
Name of Informant: PARAMASIVAM RAJKUMAR			Address: 1 23 Mandai Estate #04-07 Westlite Dormitory SINGAPORE 729937		
ID Type / ID No.: FIN NO / G8157925W			Contact No.: Home/Office: Mobile: 84324667		
Nationality: INDIAN			Email:		
Sex: Male	Age: 33	Date of Birth: 08/04/1986	Type of Informant: Driver		
Race: Indian			Language:		Institution / School Name:
Occupation: Lorry driver			Driving Licence Information: Class: Date of Expiry:		

General Information of the Accident				
Type of Accident:	Non-Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 11/02/2020 13:15	Type of Location: Straight Road
Location: Along Road 1 PIONEER ROAD Towards Tuas Lamp Post Number: 165				
Weather: Raining		Road Surface: Wet	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working	Traffic Volume: Light	
Type of Collision: Moving Vehicle Against - Others			Anyone conveyed by ambulance: No	

Details of Vehicle Involved						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
YP44T	Lorry				Seriously Damaged	1

POLICE REPORT Pg. 2



**SINGAPORE
POLICE FORCE**



T/20200211/2129

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

2 of 3

Report No. T/20200211/2129

CONTINUATION OF REPORT

Brief Details.

On 11/02/2020 at about 1315hrs, I was driving my lorry, YP44T along Pioneer Road going towards Tuas at my workplace. While I was driving, it was raining and the floor was wet. I was driving on the left lane. As there was a bus stopped at a bus stop, I wanted to change lane to the right lane to overtake the bus. However, as the road was wet, my lorry skidded as I was changing lane. I stepped on the brake immediately but still lost control of my lorry. My lorry drove across the other side of the road and all the way to the grass and hit the railing of the canal. The railing broke and my car stopped on top of the canal.

The right front door and window was fully broken. The front bonnet was also badly damaged. The front light also broke. The front mirror was totally broken. Both the wipers also broke. ERP machine was broken. Both the front tires were badly damaged. The back cabinet was also broken. The below parts of the lorry was also badly damaged.

No other government property was damaged except for the canal railing. No people was injured. Soon after the accident occurred, Traffic Police attended to my case.

I am making this report for insurance claim purpose.
The vide report number is J/20200211/0067.

POLICE REPORT Pg. 3



SINGAPORE
POLICE FORCE



T/20200211/2129

Police Station Of Origin:
Nanyang N.P.C
2 Jurong West Avenue 5 SINGAPORE
649482
Tel No: 1800-7929999

3 of 3

Report No. T/20200211/2129

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J/

SC2 M AHMED TUSHAR

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

11/02/2020 20:40

Officer In Charge Of Case:

TP / GIT /

Sgt 2 PHUA TIAK YEE

Classification Of Case:

Contact No.: 65472077



SINGAPORE
POLICE FORCE

Authentication Stamp

NP168



Victory Recovery

(Business Reg No.: 53096358B)

65 Teban Gardens Rd #23-617, Singapore 600065.

Mobile: 9618 0311 Fax: 6267 8996

OD China

CASH /
W.O. No. 105479

TOW JOB WORKS ORDER

M Sng Ah Tee Svc Date 11/2/20
Car Make/Model MIT 1477 Vehicle No. YP 44
M'ship/NRIC No./Card No. Contact No.
Time - Rec'd Arrived 13-50 Completed 20-00
Amount Charge S\$ \$450 4 Hr. Tow Truck No YH 3661
Destination (from) Pioneer Rd x Gul (to) 8 pioneer
Remark (if any) Recovery, crane up, Whole Lowry Smash into
Drain.

Tow Driver's Signature

Member's Signature

☐ Change Tyres & Towing
☐ Basement / Multi Carpark
☐ Causeway / 2nd Link

☐ Using King Drolley

☐ Low Spoiler / Low Oil Sump

☒ Accident / Over-turn

☐ Use Car Carrier

☐ Release Brake / Shaft

☐ Loaded

Note : The owner or his representative is required to follow along to the towing destination, failing which the tow operator shall not be liable for any alleged damages to the car nor missing items from the same. Vehicle is towed at owner's risk. The tow operator accepts no responsibility for any damages to the owner's vehicle whilst being towed.

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North, #01-18,
628457

Insurer Reference:
Repairer Reference: YP44T-OD CHINA
Date calculated: 19/02/2020 1:48 PM

Full Report
Registration: YP44T
Printed: 19/02/2020 1:48 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	DARREN SNG	Currency:	SGD
Claim Reference:		Date of Incident:	11/02/20
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	FUSO
Model:	CANTER (FB/FE/FG)
Sub Model:	BASE MODEL
Model Sheet Number:	32 87 01
Registration:	YP44T
VIN number:	
Odometer:	

Model Specs

FROM 10/2015	AIR CONDITIONING	3.0 LTR 96 KW	5 SPEED GEARBOX
FRT LEAF SPRING	ABS	GWR 3.5T	REAR WHEEL DRIVE
SINGLE CAB	LOADING PLATFORM	TWO COAT METALLIC	PREPARE OFF VEHICLE


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	RENEW R/F WHEELHOUSE REINFORCEMENT REAR	15.0		63.00
NO NUMBER	RENEW FRONT BUMPER	11.0		46.20
	INCLUDES: R + R NECESSARY ATTACHED PARTS			
NO NUMBER	R + R RADIATOR GRILLE	12.0		50.40
NO NUMBER	R + R L/F REPEATER LAMP	4.0		16.80
NO NUMBER	R + R R/F REPEATER LAMP	4.0		16.80
NO NUMBER	RENEW FRONT MANUFACTURER BADGE	3.0		12.60
NO NUMBER	R + R WINDSCREEN	25.0		105.00
	INCLUDES: COWL GRILLE, WIPER ARM AND WIPER LINKAGE REMOVE AND REFIT.			
NO NUMBER	R + R L/F STEP	6.0		25.20
NO NUMBER	R + R R/F STEP BOARD	2.0		8.40
NO NUMBER	R + R REAR WING COVER	2.0		8.40
NO NUMBER	DETACH + REFIT HEADLINING	2.0		8.40
NO NUMBER	RENEW L/A-PILLAR	46.0		193.20
NO NUMBER	RENEW L/F DOOR	69.0		289.80
	INCLUDES: R + R DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY			
NO NUMBER	RENEW R/A-PILLAR	46.0		193.20
NO NUMBER	RENEW R/F DOOR	18.0		75.60
	INCLUDES: R + R DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY			
NO NUMBER	R + R L/F SEAT	2.0		8.40
NO NUMBER	R + R R/F SEAT	2.0		8.40
NO NUMBER	R + R STEERING COLUMN ASSY	10.0		42.00
NO NUMBER	R + R L/SUPPORTING JOINT	2.0		8.40
NO NUMBER	R + R R/SUPPORTING JOINT	2.0		8.40
NO NUMBER	R + R COMPLETE AIR FILTER INSERT	3.0		12.60
NO NUMBER	R + R LEFT ENGINE BRACKET	7.0		29.40
NO NUMBER	R + R RIGHT ENGINE BRACKET	7.0		29.40
NO NUMBER	R + R ENGINE OIL PAN	14.0		58.80
NO NUMBER	R + R MANUAL GEARBOX	30.0		126.00
NO NUMBER	R + R GEARBOX HOUSING	26.0		109.20
NO NUMBER	DETACH + REFIT RADIATOR	4.0		16.80
NO NUMBER	R + R RADIATOR OVERFLOW TANK	2.0		8.40
NO NUMBER	R + R CONDENSER	8.0		33.60
NO NUMBER	R + R PRESSURE PIPE	3.0		12.60
NO NUMBER	REMOVE AND REFIT CONDENSOR/DRYER HOSE	1.0		4.20
NO NUMBER	R + R AIR CON COMPRESSOR/DRYER PIPE	5.0		21.00
NO NUMBER	DRAIN + REFILL AIR CONDITIONING	5.0		21.00
NO NUMBER	DRAIN-REFILL COOLENT LIQUID	8.0		33.60
NO NUMBER	DETACH + REFIT EXHAUST SYSTEM	3.0		12.60
NO NUMBER	R + R FRONT EXHAUST PIPE	5.0		21.00
NO NUMBER	R + R CTR EXHAUST PIPE	2.0		8.40
NO NUMBER	R + R EXHAUST	4.0		16.80
NO NUMBER	RENEW FUEL TANK	11.0		46.20
NO NUMBER	R + R LEFT FRONT SHOCK ABSORBER	5.0		21.00
NO NUMBER	R + R RIGHT FRONT SHOCK ABSORBER	5.0		21.00
NO NUMBER	R + R L/F CONTROL ARM	12.0		50.40
NO NUMBER	R + R R/F STEERING KNUCKLE	12.0		50.40

Code	Description	WU	Price SGD
NO NUMBER	DETACH + REFIT L/FR BRAKE CALIPER	1.0	4.20
NO NUMBER	DETACH + REFIT R/FR BRAKE CALIPER	1.0	4.20
NO NUMBER	R + R L/F SPRING	7.0	29.40
NO NUMBER	R + R R/F SPRING	7.0	29.40
NO NUMBER	R + R FRONT AXLE MEMBER	10.0	42.00
NO NUMBER	R + R L/F WHEEL	1.0	4.20
NO NUMBER	R + R R/F WHEEL	1.0	4.20
NO NUMBER	R + R AND BALANCE L/F TYRE	6.0	25.20
NO NUMBER	R + R AND BALANCE R/F TYRE	6.0	25.20
NO NUMBER	R + R REAR PROP SHAFT	2.0	8.40
NO NUMBER	ADJUST HEADLAMPS	2.0	8.40
Labour Cost		Hrs	WU
Panel / Mechanical Labour		50.90	509.0
Total of Labour			2,137.80

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	FRONT BUMPER NEW PART PAINTING	11.0
	R/F CORNER PANEL NEW PART PAINTING	8.0
	LEFT FRONT DOOR NEW PART PAINTING	15.0
	RIGHT FRONT DOOR NEW PART PAINTING	15.0
	LEFT A-PILLAR NEW PART PAINTING	8.0
	RIGHT A-PILLAR NEW PART PAINTING	8.0
	R/F W-HOUSE RR REINF SURFACE PAINT	4.0
	R/F WHEEL NEW PART PAINTING	9.0
	L/F BUMPER CORNER NEW PART PAINT K1N	4.0
	R/F BUMPER CORNER NEW PART PAINT K1N	4.0
	FRONT GRILLE NEW PART PAINT K1N	10.0
	L/F STEP NEW PART PAINT K1N	4.0
	R/F STEP NEW PART PAINT K1N	4.0
	L/F CORNER PANEL SURFACE PAINT	4.0

Paint Material Per Part

Code	Description	Price SGD
0281	FRONT BUMPER NEW PART PAINTING	24.77
0888	R/F CORNER PANEL NEW PART PAINTING	9.29
1481	LEFT FRONT DOOR NEW PART PAINTING	39.22
1482	RIGHT FRONT DOOR NEW PART PAINTING	39.22
2227	LEFT A-PILLAR NEW PART PAINTING	2.20
2228	RIGHT A-PILLAR NEW PART PAINTING	2.20
4236	R/F W-HOUSE RR REINF SURFACE PAINT	3.98
7202	R/F WHEEL NEW PART PAINTING	15.48
0289	L/F BUMPER CORNER NEW PART PAINT K1N	6.74
0290	R/F BUMPER CORNER NEW PART PAINT K1N	6.74
0410	FRONT GRILLE NEW PART PAINT K1N	38.22
2205	L/F STEP NEW PART PAINT K1N	6.74
2206	R/F STEP NEW PART PAINT K1N	6.74
0887	L/F CORNER PANEL SURFACE PAINT	4.48

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor			42.00 SGD/h
Time Paint		108.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.80	8.0	33.60
Total	10 WU/h	14.10	141.0

Material Cost - Paint

	Price SGD
New Part Painting	132.38
New Part Painting - Plastic K1N	65.18
Surface-/Blend Paint	8.46
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	247.32

Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Supplier	Price SGD
0735	AERIAL	MK645932	Bro ✓	50.00 ✓
1016	AIRCON BRACKET	.	bt ✓	500.00 ✓
8391	AIR FILTER ASSY	ME422881	? X	470.00
0413	CLIP 8X5	MK676916	ne ✓	25.00 ✓
0414	CLIP FASTENING	MC939286	ne ✓	25.00 ✓
4500	COMPRESSOR PIPE	MK574768	bt ✓	300.00 ✓
4498	CONDENSER/TANK HOSE	MK574799	bt ✓	90.00 ✓
4466	CONDENSER CPL	ML272230	bt ✓	830.00 ✓
8818	CTR EXHAUST PIPE	ME557102	bt ✓	350.00 ✓
8065	ENGINE SUMP	QC000459	bt ✓	550.00 ✓
6775	EXPANSION TANK	ME402056	X ✓	100.00 ✓
0281	FRONT BUMPER	MC978515	bt ✓	550.00 ✓
8815	FRONT EXHAUST PIPE	ML281652	sc ✓	770.00 ✓
0410	FRONT GRILLE	MC975208	? ✓	530.00 ✓
0431	FRONT MANUFACT	MK546616	? ✓	40.00 ✓
	BADGE			
0257	FRONT NUMBER PLATE	NO NUMBER	bt ✓	15.00 ✓
4069	FRONT TANK CARRIER	MK473711	? ✓	450.00 ✓
7011	FRT AXLE CARRIER	MK309884	? X	3,300.00
1000	FRT SIDE MIRROR	ROUND CAP RH	X	10.00
1001	FRT SIDE MIRROR	TOP COVER RH	com ✓	25.00 ✓
4059	FRT TANK STRAP	MK473712	bt ✓	80.00 ✓
4057	FUEL TANK	ML280148	bt ✓	550.00 ✓
8863	GEARBOX HOUSING	ME530592	sc ✓	1,330.00 ✓
0435	L/BADGE	MK676977	X ✓	0.00 ✓
1006	L/CORNER PANEL	RUBBER SEAL	X	25.00
0319	L/COVER BRACKET	MK580695	. X	9.00
1009	L/DOOR	@ DOOR	ne ✓	200.00 ✓
	WEATHERSTRIPE			
8621	L/ENGINE BRACKET	ML241602	? X	140.00
0283	L/F BUMPER BRACKET	MK617973	bt ✓	110.00 ✓
0289	L/F BUMPER CORNER	MK617983	mis ✓	190.00 ✓
1012	L/F DOOR AIR	VENT	de ✓	28.00 ✓
1509	L/F DOOR FRAME SEAL	MK403139	? X	330.00
0677	L/F INDICATOR	MK581219	bro ✓	160.00 ✓
7123	L/F INN WHEEL BRG	MH043168	? X	76.00

Code	Description	Part Number	Supplier	Price SGD
1017	L/F LOWER ARM	ASSY		1,400.00
7087	L/F SHOCK ABSORBER	MK459972		150.00
1005	L/F SIDE MIRROR	ROUND		39.00
7081	L/F STEERING KNUCKLE	MK527620		1,300.00
2205	L/F STEP	MK677506		310.00
1019	L/F TOP ARM	ASSY		1,100.00
7227	L/F TYRE	195/75 R 16 C.. R	cut 70% \$126 ✓	180.00
7131	L/F WHEEL HUB	MK527014		380.00
1453	L/F WIPER ARM	ML259169		80.00
1457	L/F WIPER BLADE	MK581040		40.00
0717	L/POSITION LAMP	MK580529		110.00
7311	L/TIE ROD BALL JOINT	MK997628		110.00
2227	LEFT A-PILLAR	MK704923	repair 25w	780.00
1481	LEFT FRONT DOOR	MK702223		1,000.00
0561	LEFT HEADLAMP ASSY	MK580525		320.00
0436	R/BADGE	MK676978		0.00
1007	R/CORNER PANEL	RUBBER SEAL		25.00
0320	R/COVER BRACKET	MK580695		9.00
1740	R/DOOR MIRROR ARM	MK547647		220.00
1738	R/DOOR MIRROR ASSY	MK486111		65.00
1010	R/DOOR WEATHERSTRIPE	@DOOR		200.00
8622	R/ENGINE BRACKET	ML241602		140.00
0284	R/F BUMPER BRACKET	MK617974		110.00
0290	R/F BUMPER CORNER	MK617989		190.00
0888	R/F CORNER PANEL	MC976411		260.00
1013	R/F DOOR AIR	VENT		28.00
1506	R/F DOOR CHECK	MK403138		38.00
1008	R/F DOOR CIGARETTE	BOX		65.00
1510	R/F DOOR FRAME SEAL	MK403140		220.00
1011	R/F DOOR GLASS	QUARTER GARNISH	bro de ✓	22.00
1712	R/F DOOR TRIM	MK580882		350.00
1520	R/F DOOR WINDOW	MK580872		280.00
0678	R/F INDICATOR	MK581220		160.00
7124	R/F INN WHEEL BRG	MH043168		76.00
1018	R/F LOWER ARM	ASSY		1,400.00
1626	R/F OUT WINDOW SEAL	MK580489		22.00
7088	R/F SHOCK ABSORBER	MK459972		150.00
7082	R/F STEERING KNUCKLE	MK527621		1,300.00
2206	R/F STEP	MK677507		310.00
1020	R/F TOP ARM	ASSY		1,100.00
7228	R/F TYRE	195/75 R 16 C.. R	Punctured 180 ✓	180.00
7202	R/F WHEEL	ML106452		200.00
7132	R/F WHEEL HUB	MK527014		380.00
4236	R/F W-HOUSE RR REINF	MK997127		75.00
1598	R/F WINDOW CHANNEL	MK580533		160.00
1548	R/F WINDOW REGULATOR	MK581272		550.00
1454	R/F WIPER ARM	ML259169		80.00
1458	R/F WIPER BLADE	MK581040		40.00
1578	R/INN DOOR LOCK	MK434990		190.00
0718	R/POSITION LAMP	MK580530		110.00
7312	R/TIE ROD BALL JOINT	MK997629		110.00
4942	R/UPP A-PILLAR TRIM	MK405508		70.00
2446	R/WING TRIM	MK403146		40.00
0418	RAD GRILLER CTR BRKT	MK614805		17.00

Code	Description	Part Number	Supplier	Price SGD
4497	REAR PRESSURE HOSE	MK629045	7- ✓	300.00
4070	REAR TANK CARRIER	MK473711	7- ✓	450.00
4060	REAR TANK STRAP	MK473712	7- ✓	80.00
2228	RIGHT A-PILLAR	MK704924	bt - ✓	780.00
1482	RIGHT FRONT DOOR	MK702224	bt - ✓	1,000.00
0562	RIGHT HEADLAMP ASSY	MK580526	ca - ✓	320.00
8823	SILENCER	ME558120	bt - ✓	800.00
1024	SPEED GEAR BOX	PTO COVER	bt - ✓	45.00
1022	STEERING BOX ASSY	. Bro - ✓		900.00
7359	STEERING COLUMN CPL	MK569670	bt - ✓	780.00
1023	STEERING LOWER	JOINT	7- ✓	340.00
1021	STEERING RACK	ASSY	7- ✓	3,300.00
1014	VACUUM TANK	. bt - ✓		130.00
1015	VACUUM TANK	BRACKET	ne - ✓	20.00
1401	WINDSCREEN	MK403591	bro - ✓	700.00
1411	WINDSCREEN BOND KIT	Z2156507	ne - ✓	0.00
1410	WINDSCREEN SEAL	MK435031	ne - ✓	220.00
f: OEM Parts				0.00
n: Non-OEM Parts				38,614.00
u: Used parts				38,614.00
Savings				0.00
Subtotal				38,614.00
Total				38,614.00

Extras

Code	Description	Price SGD
1002	FRT ERP BRACKET ne - ✓	15.00*
1003	R/F DOOR ROC STICKER ne - ✓	20.00*
1004	L/F DOOR ROC STICKER ne - ✓	20.00*
1025	GEAR BOX FLUID 4LITRE ne - ✓	80.00*
1026	ENGINE OIL 7 LITRE ne - ✓	100.00*
1027	COOLANT . + ? ✓	20.00*
1028	REAR DECK ASSY . bt - ✓	0.00*
Total Extras		255.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul

Hp 90010068

20 days

4/5

24/02/2020 @ 1700

EXCESS: 500

REPAIR

Resurvey after repair

Final Calculation

	SGD	SGD
Parts	38,614.00	
Total Parts		38,614.00
Labour Time Base 10 WU/h		
Total 509.0 WU X 42.00 SGD/h	2,137.80	
Total of Labour		2,137.80
Total Of Extras		255.00
Paint Work Time Base 10 WU/h		
Labour Cost 141.0 WU X 42.00 SGD/h	592.20	
Material Cost	247.32	
Total Paint Including Material		839.52
Repair Cost Excludes GST		41,846.32
GST (+7.0%)		2,929.24
Repair Cost Included GST		44,775.56

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

Revert

LKK Auto Consultants
#01-25 Paya Ubi Industrial Park, 51
Ubi Avenue 1
408933

Insurer Reference:
Repairer Reference: YP44T-OD CHINA
Date calculated: 26/02/2020 11:18 AM

Full Report
Registration: YP44T
Printed: 26/02/2020 11:18 AM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	KK LAU	Currency:	SGD
Claim Reference:		Date of Incident:	11/02/20
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details


Vehicle			
Manufacturer:	FUSO		
Model:	CANTER (FB/FE/FG)		
Sub Model:	BASE MODEL		
Model Sheet Number:	32 87 01		
Registration:	YP44T		
VIN number:			
Odometer:			
Model Specs			
FROM 10/2015	AIR CONDITIONING	3.0 LTR 96 KW	5 SPEED GEARBOX
FRT LEAF SPRING	ABS	GWR 3.5T	REAR WHEEL DRIVE
SINGLE CAB	LOADING PLATFORM	TWO COAT METALLIC	PREPARE OFF VEHICLE

Vehicle Condition

Vehicle Status
Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	RENEW FRONT BUMPER	11.0	46.20	
	INCLUDES: R + R NECESSARY ATTACHED PARTS			
NO NUMBER	R + R RADIATOR GRILLE	12.0	50.40	
NO NUMBER	R + R L/F REPEATER LAMP	4.0	16.80	
NO NUMBER	R + R R/F REPEATER LAMP	4.0	16.80	
NO NUMBER	RENEW FRONT MANUFACTURER BADGE	3.0	12.60	
NO NUMBER	R + R WINDSCREEN	25.0	105.00	
	INCLUDES: COWL GRILLE, WIPER ARM AND WIPER LINKAGE REMOVE AND REFIT.			
NO NUMBER	R + R L/F STEP	6.0	25.20	
NO NUMBER	R + R R/F STEP BOARD	2.0	8.40	
NO NUMBER	R + R REAR WING COVER	2.0	8.40	
NO NUMBER	DETACH + REFIT HEADLINING	2.0	8.40	
NO NUMBER	R + R AERIAL	2.0	8.40	
NO NUMBER	RENEW L/F DOOR	69.0	289.80	
	INCLUDES: R + R DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY			
NO NUMBER	RENEW R/A-PILLAR	46.0	193.20	
NO NUMBER	RENEW R/F DOOR	18.0	75.60	
	INCLUDES: R + R DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY			
NO NUMBER	R + R R/F SEAT	2.0	8.40	
NO NUMBER	R + R STEERING COLUMN ASSY	10.0	42.00	
NO NUMBER	R + R ENGINE OIL PAN	14.0	58.80	
NO NUMBER	R + R MANUAL GEARBOX	30.0	126.00	
NO NUMBER	R + R GEARBOX HOUSING	26.0	109.20	
NO NUMBER	DETACH + REFIT RADIATOR	4.0	16.80	
NO NUMBER	R + R CONDENSER	8.0	33.60	
NO NUMBER	REMOVE AND REFIT CONDENSOR/DRYER HOSE	1.0	4.20	
NO NUMBER	R + R AIR CON COMPRESSOR/DRYER PIPE	5.0	21.00	
NO NUMBER	DRAIN + REFILL AIR CONDITIONING	5.0	21.00	
NO NUMBER	DETACH + REFIT EXHAUST SYSTEM	3.0	12.60	
NO NUMBER	R + R FRONT EXHAUST PIPE	5.0	21.00	
NO NUMBER	R + R CTR EXHAUST PIPE	2.0	8.40	
NO NUMBER	R + R EXHAUST	4.0	16.80	
NO NUMBER	RENEW FUEL TANK	11.0	46.20	
NO NUMBER	R + R L/F WHEEL	1.0	4.20	
NO NUMBER	R + R R/F WHEEL	1.0	4.20	
NO NUMBER	R + R AND BALANCE L/F TYRE	6.0	25.20	
NO NUMBER	R + R AND BALANCE R/F TYRE	6.0	25.20	
NO NUMBER	R + R REAR PROP SHAFT	2.0	8.40	
NO NUMBER	ADJUST HEADLAMPS	2.0	8.40	
0320	R/COVER BRACKET CHECK			
0410	FRONT GRILLE CHECK			
0418	RAD GRILLER CTR BRKT CHECK			
0431	FRONT MANUFACT BADGE CHECK			
1506	R/F DOOR CHECK CHECK			
1509	L/F DOOR FRAME SEAL CHECK			
1548	R/F WINDOW REGULATOR CHECK			
4060	REAR TANK STRAP CHECK			

Code	Description	WU	Price SGD
4069	FRONT TANK CARRIER CHECK		
4070	REAR TANK CARRIER CHECK		
4236	R/F W-HOUSE RR REINF CHECK		
4497	REAR PRESSURE HOSE CHECK		
4942	R/UPP A-PILLAR TRIM CHECK		
7011	FRT AXLE CARRIER CHECK		
7081	L/F STEERING KNUCKLE CHECK		
7082	R/F STEERING KNUCKLE CHECK		
7087	L/F SHOCK ABSORBER CHECK		
7088	R/F SHOCK ABSORBER CHECK		
7123	L/F INN WHEEL BRG CHECK		
7124	R/F INN WHEEL BRG CHECK		
7131	L/F WHEEL HUB CHECK		
7132	R/F WHEEL HUB CHECK		
7311	L/TIE ROD BALL JOINT CHECK		
7312	R/TIE ROD BALL JOINT CHECK		
8391	AIR FILTER ASSY CHECK		
8622	R/ENGINE BRACKET CHECK		
1017	L/F LOWER ARM CHECK		
1018	R/F LOWER ARM CHECK		
1019	L/F TOP ARM CHECK		
1020	R/F TOP ARM CHECK		
1021	STEERING RACK CHECK		
1023	STEERING LOWER CHECK		
1027	COOLANT CHECK		

Labour Cost	Hrs	WU	
Panel / Mechanical Labour	35.40	354.0	1,486.80
Total of Labour			1,486.80

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	FRONT BUMPER NEW PART PAINTING	11.0
	R/F CORNER PANEL NEW PART PAINTING	8.0
	LEFT FRONT DOOR NEW PART PAINTING	15.0
	RIGHT FRONT DOOR NEW PART PAINTING	15.0
	LEFT A-PILLAR NEW PART PAINTING	8.0
	RIGHT A-PILLAR NEW PART PAINTING	8.0
	R/F W-HOUSE RR REINF SURFACE PAINT	4.0
	R/F WHEEL NEW PART PAINTING	9.0
	L/F BUMPER CORNER NEW PART PAINT K1N	4.0
	R/F BUMPER CORNER NEW PART PAINT K1N	4.0
	FRONT GRILLE NEW PART PAINT K1N	10.0
	L/F STEP NEW PART PAINT K1N	4.0
	R/F STEP NEW PART PAINT K1N	4.0
	L/F CORNER PANEL SURFACE PAINT	4.0

Paint Material Per Part

Code	Description	Price SGD
0281	FRONT BUMPER NEW PART PAINTING	24.77

Paint Material Per Part

Code	Description	Price SGD
0888	R/F CORNER PANEL NEW PART PAINTING	9.29
1481	LEFT FRONT DOOR NEW PART PAINTING	39.22
1482	RIGHT FRONT DOOR NEW PART PAINTING	39.22
2227	LEFT A-PILLAR NEW PART PAINTING	2.20
2228	RIGHT A-PILLAR NEW PART PAINTING	2.20
4236	R/F W-HOUSE RR REINF SURFACE PAINT	3.98
7202	R/F WHEEL NEW PART PAINTING	15.48
0289	L/F BUMPER CORNER NEW PART PAINT K1N	6.74
0290	R/F BUMPER CORNER NEW PART PAINT K1N	6.74
0410	FRONT GRILLE NEW PART PAINT K1N	38.22
2205	L/F STEP NEW PART PAINT K1N	6.74
2206	R/F STEP NEW PART PAINT K1N	6.74
0887	L/F CORNER PANEL SURFACE PAINT	4.48

Labour Cost - Paint

Factor	42.00 SGD/h	Hrs	WU	Price SGD
Time Paint			108.0	
Preparation Main Work Metal		2.50	25.0	105.00
Preparation Comp. Work Plastic		0.80	8.0	33.60
Total	10 WU/h	14.10	141.0	592.20

Material Cost - Paint

	Price SGD
New Part Painting	132.38
New Part Painting - Plastic K1N	65.18
Surface-/Blend Paint	8.46
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	247.32

Spare Parts

Code	Description	Part Number	Supplier	prices as at 2015-06-01	Price SGD
0735	AERIAL	MK645932			50.00
1016	AIRCON BRACKET	.			500.00
0413	CLIP 8X5	MK676916			25.00
0414	CLIP FASTENING	MC939286			25.00
4500	COMPRESSOR PIPE	MK574768			300.00
4498	CONDENSER/TANK HOSE	MK574799			90.00
4466	CONDENSER CPL	ML272230			830.00
8818	CTR EXHAUST PIPE	ME557102			350.00
8065	ENGINE SUMP	QC000459			550.00
0281	FRONT BUMPER	MC978515			550.00
8815	FRONT EXHAUST PIPE	ML281652			770.00
0257	FRONT NUMBER PLATE	NO NUMBER			15.00
1001	FRT SIDE MIRROR	TOP COVER RH			25.00
4059	FRT TANK STRAP	MK473712			80.00
4057	FUEL TANK	ML280148			550.00
8863	GEARBOX HOUSING	ME530592			1,330.00
0435	L/BADGE	MK676977			0.00

Code	Description	Part Number	Supplier	Price SGD
1009	L/DOOR WEATHERSTRIPE	@ DOOR		200.00
0283	L/F BUMPER BRACKET	MK617973		110.00
0289	L/F BUMPER CORNER	MK617983		190.00
1012	L/F DOOR AIR	VENT		28.00
0677	L/F INDICATOR	MK581219		160.00
2205	L/F STEP	MK677506		310.00
7227	L/F TYRE	195/75 R 16 C .. R		126.00
1453	L/F WIPER ARM	ML259169		80.00
1457	L/F WIPER BLADE	MK581040		40.00
0717	L/POSITION LAMP	MK580529		110.00
1481	LEFT FRONT DOOR	MK702223		1,000.00
0561	LEFT HEADLAMP ASSY	MK580525		320.00
0436	R/BADGE	MK676978		0.00
1007	R/CORNER PANEL	RUBBER SEAL		25.00
1740	R/DOOR MIRROR ARM	MK547647		220.00
1738	R/DOOR MIRROR ASSY	MK486111		65.00
1010	R/DOOR WEATHERSTRIPE	@DOOR		200.00
0284	R/F BUMPER BRACKET	MK617974		110.00
0290	R/F BUMPER CORNER	MK617989		190.00
0888	R/F CORNER PANEL	MC976411		260.00
1013	R/F DOOR AIR	VENT		28.00
1510	R/F DOOR FRAME SEAL	MK403140		220.00
1011	R/F DOOR GLASS	QUARTER GARNISH		22.00
1712	R/F DOOR TRIM	MK580882		350.00
1520	R/F DOOR WINDOW	MK580872		280.00
0678	R/F INDICATOR	MK581220		160.00
1626	R/F OUT WINDOW SEAL	MK580489		22.00
2206	R/F STEP	MK677507		310.00
7228	R/F TYRE	195/75 R 16 C .. R		180.00
7202	R/F WHEEL	ML106452		200.00
1598	R/F WINDOW CHANNEL	MK580533		160.00
1454	R/F WIPER ARM	ML259169		80.00
1458	R/F WIPER BLADE	MK581040		40.00
1578	R/INN DOOR LOCK	MK434990		190.00
0718	R/POSITION LAMP	MK580530		110.00
2446	R/WING TRIM	MK403146		40.00
2228	RIGHT A-PILLAR	MK704924		780.00
1482	RIGHT FRONT DOOR	MK702224		1,000.00
0562	RIGHT HEADLAMP ASSY	MK580526		320.00
8823	SILENCER	ME558120		800.00
1024	SPEED GEAR BOX	PTO COVER		45.00
1022	STEERING BOX ASSY	.		900.00
7359	STEERING COLUMN CPL	MK569670		780.00
1014	VACUUM TANK	.		130.00
1015	VACUUM TANK	BRACKET		20.00
1401	WINDSCREEN	MK403591		700.00
1411	WINDSCREEN BOND KIT	Z2156507		0.00
1410	WINDSCREEN SEAL	MK435031		220.00
f: OEM Parts	Savings			0.00
n: Non-OEM Parts	Subtotal			17,871.00
u: Used parts	Total			17,871.00

Extras

Code	Description	Price SGD
1002	FRT ERP BRACKET	15.00*
1003	R/F DOOR ROC STICKER	20.00*
1004	L/F DOOR ROC STICKER	20.00*
1025	GEAR BOX FLUID 4LITRE	80.00*
1026	ENGINE OIL 7 LITRE	100.00*
1028	REAR DECK ASSY .	0.00*
Total Extras		235.00

Final Calculation

	SGD	SGD
Parts	17,871.00	
Total Parts		17,871.00
Labour Time Base 10 WU/h		
Total 354.0 WU X 42.00 SGD/h	1,486.80	
Total of Labour		1,486.80
Total Of Extras		235.00
Paint Work Time Base 10 WU/h		
Labour Cost 141.0 WU X 42.00 SGD/h	592.20	
Material Cost	247.32	
Total Paint Including Material		839.52
Repair Cost Excludes GST		20,432.32
GST (+7.0%)		1,430.26
Repair Cost Included GST		21,862.58

Comments

* - USER SUPPLIED DATA
 NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

Sng Ah Tee Motor Pte Ltd
Blk 3 Pioneer Road North, #01-18,
628457

Finalise

Insurer Reference:
Repairer Reference: YP44T-OD CHINA
Date calculated: 03/08/2020 7:13 PM

Full Report
Registration: YP44T
Printed: 03/08/2020 7:14 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	SNG AH TEE	Currency:	SGD
Claim Reference:		Date of Incident:	11/02/20
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer:	FUSO
Model:	CANTER (FB/FE/FG)
Sub Model:	BASE MODEL
Model Sheet Number:	32 87 01
Registration:	YP44T
VIN number:	
Odometer:	

Model Specs

FROM 10/2015	AIR CONDITIONING	3.0 LTR 96 KW	5 SPEED GEARBOX
FRT LEAF SPRING	ABS	GWR 3.5T	REAR WHEEL DRIVE
SINGLE CAB	LOADING PLATFORM	TWO COAT METALLIC	PREPARE OFF VEHICLE


Vehicle Condition

Vehicle Status

Pre-Accident Damage:
Date of Inspection:

Damage Areas

All ☐
Underbody ☐



Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	RENEW RIGHT FRONT WHEELHOUSE CLOSING	19.0		79.80
NO NUMBER	RENEW FRONT BUMPER	11.0		46.20
	INCLUDES: R + R NECESSARY ATTACHED PARTS			
NO NUMBER	R + R RADIATOR GRILLE	12.0		50.40
NO NUMBER	R + R L/F REPEATER LAMP	4.0		16.80
NO NUMBER	R + R R/F REPEATER LAMP	4.0		16.80
NO NUMBER	RENEW FRONT MANUFACTURER BADGE	3.0		12.60
NO NUMBER	R + R WINDSCREEN	25.0		105.00
	INCLUDES: COWL GRILLE, WIPER ARM AND WIPER LINKAGE REMOVE AND REFIT.			
NO NUMBER	R + R L/F STEP	6.0		25.20
NO NUMBER	R + R R/F STEP BOARD	2.0		8.40
NO NUMBER	R + R REAR WING COVER	2.0		8.40
NO NUMBER	DETACH + REFIT HEADLINING	2.0		8.40
NO NUMBER	R + R AERIAL	2.0		8.40
NO NUMBER	RENEW L/F DOOR	69.0		289.80
	INCLUDES: R + R DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY			
NO NUMBER	RENEW R/A-PILLAR	46.0		193.20
NO NUMBER	RENEW R/F DOOR	18.0		75.60
	INCLUDES: R + R DOOR, CONVERT ATTACHED PARTS, RENEW IF NECESSARY			
NO NUMBER	R + R R/F SEAT	2.0		8.40
NO NUMBER	R + R INSTRUMENT PANEL	25.0		105.00
NO NUMBER	R + R STEERING COLUMN ASSY	10.0		42.00
NO NUMBER	R + R R/SUPPORTING JOINT	2.0		8.40
NO NUMBER	R + R COMPLETE AIR FILTER INSERT	3.0		12.60
NO NUMBER	R + R ENGINE OIL PAN	14.0		58.80
NO NUMBER	R + R MANUAL GEARBOX	30.0		126.00
NO NUMBER	R + R GEARBOX HOUSING	26.0		109.20
NO NUMBER	DETACH + REFIT RADIATOR	4.0		16.80
NO NUMBER	R + R RADIATOR OVERFLOW TANK	2.0		8.40
NO NUMBER	R + R CONDENSER	8.0		33.60
NO NUMBER	REMOVE AND REFIT CONDENSOR/DRYER HOSE	1.0		4.20
NO NUMBER	R + R AIR CON COMPRESSOR/DRYER PIPE	5.0		21.00
NO NUMBER	DRAIN + REFILL AIR CONDITIONING	5.0		21.00
NO NUMBER	DRAIN-REFILL COOLENT LIQUID	8.0		33.60
NO NUMBER	DETACH + REFIT EXHAUST SYSTEM	3.0		12.60
NO NUMBER	R + R FRONT EXHAUST PIPE	5.0		21.00
NO NUMBER	R + R CTR EXHAUST PIPE	2.0		8.40
NO NUMBER	R + R EXHAUST	4.0		16.80
NO NUMBER	RENEW FUEL TANK	11.0		46.20
NO NUMBER	R + R CLUTCH MASTER CYLINDER	4.0		16.80
NO NUMBER	R + R LEFT FRONT SHOCK ABSORBER	5.0		21.00
NO NUMBER	R + R RIGHT FRONT SHOCK ABSORBER	5.0		21.00
NO NUMBER	R + R L/F CONTROL ARM	12.0		50.40
NO NUMBER	R + R R/F STEERING KNUCKLE	12.0		50.40
NO NUMBER	DETACH + REFIT L/FR BRAKE CALIPER	1.0		4.20
NO NUMBER	DETACH + REFIT R/FR BRAKE CALIPER	1.0		4.20
NO NUMBER	R + R L/F SPRING	7.0		29.40

Code	Description	WU	Price SGD
NO NUMBER	R + R R/F SPRING	7.0	29.40
NO NUMBER	R + R FRONT AXLE MEMBER	10.0	42.00
NO NUMBER	R + R L/F WHEEL	1.0	4.20
NO NUMBER	R + R R/F WHEEL	1.0	4.20
NO NUMBER	R + R AND BALANCE L/F TYRE	6.0	25.20
NO NUMBER	R + R AND BALANCE R/F TYRE	6.0	25.20
NO NUMBER	R + R REAR PROP SHAFT	2.0	8.40
NO NUMBER	ADJUST HEADLAMPS	2.0	8.40
2227	LEFT A-PILLAR REPAIR	25.0*	105.00
Labour Cost		Hrs	WU
Panel / Mechanical Labour		50.20	502.0
Total of Labour			2,108.40

Paint

Paint Work		SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU	Price SGD
	FRONT BUMPER NEW PART PAINTING	11.0	
	R/F CORNER PANEL NEW PART PAINTING	8.0	
	LEFT FRONT DOOR NEW PART PAINTING	15.0	
	RIGHT FRONT DOOR NEW PART PAINTING	15.0	
	RIGHT A-PILLAR NEW PART PAINTING	8.0	
	R/F WHEELARCH PANEL SURFACE PAINT	4.0	
	R/F WHEEL NEW PART PAINTING	9.0	
	L/F BUMPER CORNER NEW PART PAINT K1N	4.0	
	R/F BUMPER CORNER NEW PART PAINT K1N	4.0	
	FRONT GRILLE NEW PART PAINT K1N	10.0	
	L/F STEP NEW PART PAINT K1N	4.0	
	R/F STEP NEW PART PAINT K1N	4.0	
	LEFT A-PILLAR REPAIR PAINTING <50%	7.0	
	L/F CORNER PANEL SURFACE PAINT	4.0	
	R/F W-HOUSE RR REINF SURFACE PAINT	4.0	

Paint Material Per Part

Code	Description	Price SGD
0281	FRONT BUMPER NEW PART PAINTING	24.77
0888	R/F CORNER PANEL NEW PART PAINTING	9.29
1481	LEFT FRONT DOOR NEW PART PAINTING	39.22
1482	RIGHT FRONT DOOR NEW PART PAINTING	39.22
2228	RIGHT A-PILLAR NEW PART PAINTING	2.20
4242	R/F WHEELARCH PANEL SURFACE PAINT	2.49
7202	R/F WHEEL NEW PART PAINTING	15.48
0289	L/F BUMPER CORNER NEW PART PAINT K1N	6.74
0290	R/F BUMPER CORNER NEW PART PAINT K1N	6.74
0410	FRONT GRILLE NEW PART PAINT K1N	38.22
2205	L/F STEP NEW PART PAINT K1N	6.74
2206	R/F STEP NEW PART PAINT K1N	6.74
2227	LEFT A-PILLAR REPAIR PAINTING <50%	1.29
0887	L/F CORNER PANEL SURFACE PAINT	4.48
4236	R/F W-HOUSE RR REINF SURFACE PAINT	3.98

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		111.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.80	8.0	33.60
Total	10 WU/h	14.40	144.0

Material Cost - Paint

	Price SGD
New Part Painting	130.18
New Part Painting - Plastic K1N	65.18
Repair Painting	1.29
Surface-/Blend Paint	10.95
Material-constant Metal Preparation	28.60
Material-constant Plastic	12.70
Total	248.90

Spare Parts

				prices as at 2015-06-01
Code	Description	Part Number	Part Source	Price SGD
0257 ✓	FRONT NUMBER PLATE	NO NUMBER	Original	15.00 ✓
0281 ✓	FRONT BUMPER	MC978515	Original	550.00 ✓
0283 ✓	L/F BUMPER BRACKET	MK617973	Original	110.00 ✓
0284 ✓	R/F BUMPER BRACKET	MK617974	Original	110.00 ✓
0289 ✓	L/F BUMPER CORNER	MK617983	Original	190.00 ✓
0290 ✓	R/F BUMPER CORNER	MK617989	Original	190.00 ✓
0320 ✓	R/COVER BRACKET	MK580695	Original	9.00 ✓
0410 ✓	FRONT GRILLE	MC975208	Original	530.00 ✓
0413 ✓	CLIP 8X5	MK676916	Original	25.00 ✓
0414 ✓	CLIP FASTENING	MC939286	Original	25.00 ✓
0431 ✓	FRONT MANUFACT BADGE	MK546616	Original	40.00 ✓
0435 ✓	L/BADGE	MK676977		0.00 ✓
0436 ✓	R/BADGE	MK676978		0.00 ✓
0561 ✓	LEFT HEADLAMP ASSY	MK580525	Original	320.00 ✓
0562 ✓	RIGHT HEADLAMP ASSY	MK580526	Original	320.00 ✓
0677 ✓	L/F INDICATOR	MK581219	Original	160.00 ✓
0678 ✓	R/F INDICATOR	MK581220	Original	160.00 ✓
0717 ✓	L/POSITION LAMP	MK580529	Original	110.00 ✓
0718 ✓	R/POSITION LAMP	MK580530	Original	110.00 ✓
0735 ✓	AERIAL	MK645932	Original	50.00 ✓
0888 ✓	R/F CORNER PANEL	MC976411	Original	260.00 ✓
1401 ✓	WINDSCREEN	MK403591	Original	700.00 ✓
1410 ✓	WINDSCREEN SEAL	MK435031	Original	220.00 ✓
1411 ✓	WINDSCREEN BOND KIT	Z2156507		0.00 ✓
1453 ✓	L/F WIPER ARM	ML259169	Original	80.00 ✓
1454 ✓	R/F WIPER ARM	ML259169	Original	80.00 ✓
1457 ✓	L/F WIPER BLADE	MK581040	Original	40.00 ✓
1458 ✓	R/F WIPER BLADE	MK581040	Original	40.00 ✓
1481 ✓	LEFT FRONT DOOR	MK702223	Original	1,000.00 ✓
1482 ✓	RIGHT FRONT DOOR	MK702224	Original	1,000.00 ✓
1510 ✓	R/F DOOR FRAME SEAL	MK403140	Original	220.00 ✓
1520 ✓	R/F DOOR WINDOW	MK580872	Original	280.00 ✓
1578 ✓	R/INN DOOR LOCK	MK434990	Original	190.00 ✓
1598 ✓	R/F WINDOW CHANNEL	MK580533	Original	160.00 ✓

Code	Description	Part Number	Part Source	Price SGD
1626 ✓	R/F OUT WINDOW SEAL	MK580489	Original	22.00 ✓
1712 ✓	R/F DOOR TRIM	MK580882	Original	350.00 ✓
1738 ✓	R/DOOR MIRROR ASSY	MK486111	Original	65.00 ✓
1740 ✓	R/DOOR MIRROR ARM	MK547647	Original	220.00 ✓
2205 ✓	L/F STEP	MK677506	Original	310.00 ✓
2206 ✓	R/F STEP	MK677507	Original	310.00 ✓
2228 ✓	RIGHT A-PILLAR	MK704924	Original	780.00 ✓
2446 ✓	R/WING TRIM	MK403146	Original	40.00 ✓
4057 ✓	FUEL TANK	ML280148	Original	550.00 ✓
4059 ✓	FRT TANK STRAP	MK473712	Original	80.00 ✓
4060 ✓	REAR TANK STRAP	MK473712	Original	80.00 ✓
4069 ✓	FRONT TANK CARRIER	MK473711	Original	450.00 ✓
4070 ✓	REAR TANK CARRIER	MK473711	Original	450.00 ✓
4242 ✓	R/F WHEELARCH PANEL	MK997121	Original (A)	150.00 ✓
4466 ✓	CONDENSER CPL	ML272230	Original	830.00 ✓
4498 ✓	CONDENSER/TANK HOSE	MK574799	Original	90.00 ✓
4500 ✓	COMPRESSOR PIPE	MK574768	Original	300.00 ✓
4942 ✓	R/UPP A-PILLAR TRIM	MK405508	Original	70.00 ✓
6775 ✓	EXPANSION TANK	ME402056	Original	100.00 ✓
7082 ✓	R/F STEERING KNUCKLE	MK527621	Original	1,300.00 ✓
7088 ✓	R/F SHOCK ABSORBER	MK459972	Original	150.00 ✓
7118 ✓	R/F OUT WHEEL BRG	MH043169	Original (A)	40.00 ✓
7124 ✓	R/F INN WHEEL BRG	MH043168	Original	76.00 ✓
7132 ✓	R/F WHEEL HUB	MK527014	Original	380.00 ✓
7202 ✓	R/F WHEEL	ML106452	Original	200.00 ✓
7227 ✓	L/F TYRE	195/75 R 16 C .. R	Original	126.00 ✓
7228 ✓	R/F TYRE	195/75 R 16 C .. R	Original	180.00 ✓
7310 ✓	DRAG LINK	MK590510	Original (A)	300.00 ✓
7312 ✓	R/TIE ROD BALL JOINT	MK997629	Original	110.00 ✓
7359 ✓	STEERING COLUMN CPL	MK569670	OEM	780.00 ✓
7411 ✓	STEERING WHEEL TRIM	MK569669	Original (A)	190.00 ✓
8065 ✓	ENGINE SUMP	QC000459	Original	550.00 ✓
8815 ✓	FRONT EXHAUST PIPE	ML281652	Original	770.00 ✓
8818 ✓	CTR EXHAUST PIPE	ME557102	Original	350.00 ✓
8823 ✓	SILENCER	ME558120	Original	800.00 ✓
8863 ✓	GEARBOX HOUSING	ME530592	Original	1,330.00 ✓
8967 ✓	CLUTCH MASTER CYL	ME507832	Original (A)	105.00 ✓
1001 ✓	FRT SIDE MIRROR	TOP COVER RH	Original	25.00 ✓
1007 ✓	R/CORNER PANEL	RUBBER SEAL	Original	25.00 ✓
1009 ✓	L/DOOR	@ DOOR	Original	200.00 ✓
1010 ✓	WEATHERSTRIPE			
1010 ✓	R/DOOR	@DOOR	Original	200.00 ✓
1010 ✓	WEATHERSTRIPE			
1011 ✓	R/F DOOR GLASS	QUARTER GARNISH	Original	22.00 ✓
1012 ✓	L/F DOOR AIR	VENT	Original	28.00 ✓
1013 ✓	R/F DOOR AIR	VENT	Original	28.00 ✓
1014 ✓	VACUUM TANK	.	Original	130.00 ✓
1015 ✓	VACUUM TANK	BRACKET	Original	20.00 ✓
1016 ✓	AIRCON BRACKET	.	Original	500.00 ✓
1018 ✓	R/F LOWER ARM	ASSY	Original	1,400.00 ✓
1020 ✓	R/F TOP ARM	ASSY	Original	1,100.00 ✓
1022 ✓	STEERING BOX ASSY	.	Original	900.00 ✓
1023 ✓	STEERING LOWER	JOINT	Original	340.00 ✓
1024 ✓	SPEED GEAR BOX	PTO COVER	Original	45.00 ✓
1029 ✓	R/F BUMPER INN BRKT	.	Original (A)	60.00 ✓
1030 ✓	STEERING COUPLING	.	Original (A)	95.00 ✓

Code	Description	Part Number	Part Source	Price SGD
1031	FUSE BOX ASSY (A)	MK543399	Original C/A	2,000.00
f: OEM Parts				0.00
n: Non-OEM Parts				27,396.00
u: Used parts				
Savings				
Subtotal				27,396.00
Total				27,396.00

Extras

Code	Description	Price SGD
1002	FRT ERP BRACKET	15.00*
1003	R/F DOOR ROC STICKER	20.00*
1004	L/F DOOR ROC STICKER	20.00*
1025	GEAR BOX FLUID 4LITRE	80.00*
1026	ENGINE OIL 7 LITRE	100.00*
1027	COOLANT .	20.00*
1032	REAR BUMPER STEP -	400.00*
1033	RR DECK WOODEN BEAM X3 -\$450/PC	1,350.00*
1034	RR CANOPY RUN CHANNL X2 - \$380/PC	760.00*
1035	RR DECK FLOOR PANEL	1,300.00*
1036	LIFT UP RR DECK -	500.00*
1037	REFILL AIRCON GAS	50.00*
1038	TO DO DIAGNOSE & RESET FAULT	200.00*
Total Extras		4,815.00

Final Calculation

	SGD	SGD
Parts	27,396.00	
Total Parts		27,396.00
Labour Time Base 10 WU/h		
Total 502.0 WU X 42.00 SGD/h	2,108.40	
Total of Labour		2,108.40
Total Of Extras		4,815.00
Paint Work Time Base 10 WU/h		
Labour Cost 144.0 WU X 42.00 SGD/h	604.80	
Material Cost	248.90	
Total Paint Including Material		853.70
Repair Cost Excludes GST		35,173.10
GST (+7.0%)		2,462.12
Repair Cost Included GST		37,635.22
Deductions (Excludes GST)		
Repair Cost Discount (+20.00%)	-7,034.62	
Total Of Deductions (Excludes GST)		-7,034.62
Grand Total Excludes GST		28,138.48
GST (+7.0%)		1,969.69
Grand Total Included GST		30,108.17

Comments

* - USER SUPPLIED DATA

NN - NO MANUFACTURERS CODE EXISTS

) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.