

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO : 67038511
REFERENCE : 028/IC/TCAC/CCR/2020
DATE : 21-FEB-2020

LONPAC INSURANCE BHD
300 BEACH RD
#17-04/07 THE CONCOURSE
S(199555)
TEL : 62507388
FAX : 62962706
MOTOR CLAIMS DEPT

OWNER'S NAME : WEE AIK TAT
ADDRESS : 131 THOMSON RIDGE

S(574713)
TELEPHONE NO : 64552236/98184288

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 2100503282-02
VEHICLE NO : SLL7336E
MODEL CODE : JDRNRRZT32EWA-----
MODEL/YEAR : X-TRAIL 2.0L ALL MODE 4X4I
ENGINE NO : MR20969030B
CHASSIS NO : JN1JANT32Z0003020
MILEAGE : 38295 KM
DATE IN : 21/02/2020
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : SHAWN CHUA CHU RONG
ACCIDENT DATE : 21/02/2020

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLL7336E

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	BY01P	**COMPLETE POLISHING & WAXING OF VEHICLE INCLUDE VACUUM INTERIOR**	100.00	
2	CONI	PERFORM VEHICLE ELECTRONIC SYSTEM DIAGNOSIS, INTERROGATION & REPROGRAM MODULE WITH CONSULT	240.00	
3	FHI	FOCUS & ADJUST H/LAMP, RESET HORIZONTAL & VERTICAL ALIGNMENT TO FACTORY SPECIFICATION	48.00	
4	IBS	PERFORM NISSAN COMPUTERISED DIAGNOSIS, ALIGN VEH LEVEL, CALIBRATION OF RADAR SENSOR AND ROAD TEST	330.00	
5	NPI	SUPPLY & INSTALL NUMBER PLATE & HOLDER INCLUDING PARTS	60.00	
6	RCI	REPLACE REVERSE CAMERA, FINISHER MOUNTING, ALIGNMENT, SETTING & FUNCTION TEST	120.00	
7	RPI	PERFORM RUST PROOFING & TREATMENT FOR AFFECTED PANEL	240.00	
8	RSI	REPLACE REVERSE SENSOR, NECESSARY ADJUSTMENT & FUNCTION TEST	55.00	
9	SEALI	APPLY SEALANT TO ALL AFFECTED PANEL JOINTS & RESEAL NECESSARY AREA	300.00	
10	ZZ/001	REPLACE FRONT BUMPER, GRILLE, RIGHT HEADLAMP, FRONT CAMERA, TOW HOOK COVER, LOWER CHROME MOULDING, HOOD		
11	ZZ/002	HOOD CENTRE SEAL ETC REPAIR PANELS	1950.00	
12	ZZ/003	REPLACE REAR BUMPER, CENTRE FINISHER, REFLECTORS, REAR UPPER PANEL, REINFORCEMENT & STAYS, TAILGATE,		
13	ZZ/004	ETC REPAIR PANELS	1950.00	
14	ZZ/005	REPLACE TAILGATE GLASS TO FACILITATE REPAIR	250.00	
15	ZZ/006	INSTALL SOLAR FILM ON TAILGATE GLASS TO FACILITATE REPAIR	144.00	
16	ZZ/007	TRANSFER TAILGATE COMPONENTS TO FACILITATE REPAIR	120.00	
17	ZZ/008	RESPRAY FRONT BUMPER, HOOD, REAR BUMPER IN 2 COLORS, REAR UPPER PANEL, TAILGATE ETC	2000.00	

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLL7336E

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
18	ZZ/009	QC, RETUNE & CONSULT CHECK		
19	ZZ/10	COMPLIMENTARY WASH & VACUUM		
TOTAL LABOUR CHARGES			7907.00	

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLL7336E

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
			NETT	LIST	S/NETT REMARKS
1	X-TRAIL EMBLEM	84895-4CLOA	110.00		
2	REAR NISSAN EMBLEM	84890-4CLOA	64.90		
3	WEATHERSTRIP	90830-4CC0B	140.80		
4	TAILGATE CENTRE FINISHER	90810-4CE0A	145.20		
5	TAILGATE GLASS	90300-4CC0A	1386.00		
6	TAILGATE	9001A-4CC5C	4380.00		
7	REAR RIGHT BUMPER BRACKET	85220-4CE0A	38.90		
8	REAR LEFT BUMPER BRACKET	85221-4CE0A	38.80		
9	REAR RIGHT REINFORCEMENT STAY	H5210-4CCMA	195.60		
10	REAR LEFT REINFORCEMENT STAY	H5211-4CCMA	195.60		
11	REAR REINFORCEMENT	85032-4CC0A	596.20		
12	REAR BUMPER CENTRE FINISHER	85070-1KA0A	117.50		
13	REAR W/SCREEN SEALANT	SEALANT - 4			80.00
14	REVERSE SENSOR(J11 & T32)	SENSOR-TE5140			360.00
15	REAR BUMPER	85022-4CE0H	693.10		
16	REAR LUGGAGE PLATE	84992-4CE0A	68.80		
17	REAR UPPER PANEL	79110-4CC0A	447.50		
18	FRONT EMBLEM CAMERA	284F1-4BA0A	1125.00		
19	FRONT NISSAN EMBLEM	62890-4BA0A	64.90		
20	HOOD CENTRE SEAL	65810-4CLOA	17.20		
21	HOOD	F510M-4CCMA	995.60		
22	CLIP (\$1.50 EA X 8)	01553-10501	10.40		
23	GRILLE	62310-4CE1B	411.20		
24	FRONT LEFT REINFORCEMENT STAY	62211-4CLOA	96.90		
25	FRONT RIGHT REINFORCEMENT STAY	62210-4CL1A	96.90		

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLL7336E

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
26	FRONT REINFORCEMENT	62030-4CLOA	507.00			
27	ENERGY ABSORBER	62090-4CE0A	326.30			
28	LOWER GRILLE	62254-4CE0A	223.30			
29	RIGHT FOG LAMP FINISHER	62256-4BA0B	87.70			
30	LEFT FOG LAMP FINISHER	62257-4BA0B	87.70			
31	TOW HOOK COVER	622A0-4CLOA	22.00			
32	FRONT BUMPER LOWER CHROME MOULDING	62072-4BA0A	171.30			
33	FRONT BUMPER	62022-4CE0H	594.10			
34	RIGHT HEADLAMP	26010-4CA6D	2576.00			
SUB TOTAL			16032.40	0.00	440.00	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			3206.48	0.00	0.00	
GRAND TOTAL			12825.92	0.00	440.00	
OVERALL TOTAL			13265.92			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

TC AUTOCLINIC PTE LTD
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLL7336E

TOTAL LABOUR CHARGES 7907.00
TOTAL SPARE PARTS CHARGES 13265.92

GRAND TOTAL 21172.92 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the
 affected vehicle. Should we require further labour
 charges & spare parts in the process of repairs, we
 shall inform you accordingly.