

12345678

ASS. REC. BY:

Insured: Marcus Manmen

REF:

EA120003084/Ugd3⁰²

Special Instruction:

From (Person):

Pauline Soh

of

EAI

Date/Time:

24/2/2020@10-16am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SMC 5606A

Insured:

GY 7673Y

at Workshop no/

Fuskeh Auto

Tel:

6746 5405

of

1 Kaki Bukit Ave 6 # 01-46 Autobay

Policy No.:

Claim No.:

CDMFG20000331

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/02/2020

CA / REV / REP. / REV 24 HRS

1up1

H.O.D. Endorsement:

Date/Time:

10:21am @ 24/2/2020

Person Contacted:

Shi Ying

Vehicle IN / OUT

Date/Time

Action/Instruction

1st/initial / T

SMC 5606A-X

GY 7673Y-X

24/2/20 @ 11am informed Etko, we are pending estimate from repairer.
09/3/20 @ 4.15pm revised to Pauline Soh via Manmen.

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SMC 5606A
 at Workshop m/s ST.
 of _____
 Insured: 6476734
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: 80k.
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT

N/S	O/S

Veh No: SMC 5606A Yr Regn: 7, 18
 Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or CAI
 Make: Subaru Forester c.c. 1995
 Colour: Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 26196 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JF1SJ5K65J6111505
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 225/60R17
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front R/Bal. 6 mm Rear R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 21/2/20 D.O.I. 24/2/20
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Rear
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction
28/2/20 4/5 5000 confirmed with Aler. (see 11760.20, 70%)

RECEIVED 10 MAR 2020

Date/Time, File Pass to? : Preli. Report
 : Final Report
 1) 10/3 turner
 Date/Time, File Return to?

Days Of Repair: 4
 Resurvey No. of Trip: 2

Survey Fee:
 Transportation: 350
) S + RS) 11
) Photos
) Others
 TOTAL 361

Report Format: MEM-70
 Lump Sum / I.B.I: (\$) 5000

Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Invs (\$)
 : Weekend (\$)

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 09 Mar 2020

Preliminary Advice

Insured Vehicle No	: GY7673Y		
TP Vehicle No	: SMC5606A	Accident Date	: 21/02/2020
Make	: SUBARU FORESTER	Assignment Date	: 24/02/2020
Date of Inspection	: 24/02/2020	Est. Duration of Repair	: 4.00
Inspection At	: FASTECH AUTO PTE LTD (HQ) 1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,760.20
Revised Amount	:S\$	6,256.56
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,256.56
Lump Sum Repair	:S\$	5,000.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :

Nivitha (LKK Auto)

From: ERGO Insurance Pte. Ltd. (Claims Department) <claims@ergo.com.sg>
Sent: Monday, 24 February 2020 10:16 AM
To: Ong Shiyong; Admin-D (LKKAuto (admin-d@lkkauto.com)); Admin A (admin-a@lkkauto.com); Mei Kwan (LKKAuto (Meikwan@lkkauto.com))
Cc: Jason; Lina Pang; Ivy Yong; Zheng Hanyang; Phoebe Xie
Subject: RE: Claims ref no. (P) CDMFG20000331 REQUEST FOR PRE-REPAIR INSPECTION FOR SMC 5606A DOA: 21.02.2020

Date Classification : Confidential, C3

**** NOTE: Please create case, input our Claim ref no. and upload ALL survey related documents into Merimen. Payment invoices shall be ignored for cases that are not submitted via Merimen.**

Hi LKK,

Please conduct this survey request.
(Note: Survey vehicle only, LOD will be handled by Ergo)

Kindly inform us if you are not able to attend it.

Thank you.

Warmest Regards,
Pauline Soh
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five
Singapore 038985
DID : +65 6829 9194
pauline.soh@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: Ong Shiyong <shiyong.ong@fastechauto.com.sg>
Sent: Monday, 24 February 2020 10:14 am
To: ERGO Insurance Pte. Ltd. (Claims Department) <claims@ergo.com.sg>
Cc: Jason <Jason@fastechauto.com.sg>; Lina Pang <Lina.pang@fastechauto.com.sg>; Ivy Yong <ivy.yong@ergo.com.sg>; Zheng Hanyang <hanyang.zheng@ergo.com.sg>; Phoebe Xie <phoebe.xie@ergo.com.sg>

Shiau Chan (LKKAuto)

From: Do-Not-Reply <do-not-reply@merimen.com>
Sent: Tuesday, 25 February 2020 11:00 AM
To: do-not-reply@merimen.com
Cc: SUR
Subject: TP VEHICLE SMC 5606A (YOUR REF: CDMFG20000331)

This mail is associated with :

***SMC5606A**

[GY7673Y]

TP

HENG KIM GUAN, TAVERN

Feb 21 2020 8:00AM

Fastech Auto Pte Ltd

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SMC 5606A on 24/02/2020.

We are pending for estimate from repairer.

Thanks & Regards,

Shiau Chan (Ms)
LKK Auto Consultants Pte Ltd
Tel: 6256 3561

This is an auto-generated email. Do not reply to this email.

Sent by : SHIAU CHAN (LKK Auto Consultants Pte Ltd)

BUSINESS SPACE FOR LEASE

- CHEAP PRICE
- LOWRENT

CALL 6377 8000



maple tree
Industrial
Your Preferred Real Estate Partner

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

1960 Chevrolet Corvette, 350cc Chevy Small Block V8.



1960 Corvette Convertible, Soft
And Hard Tops, V8, Muncie
Gearbox, Rare RHD.
Direct Owner StanAd

KA-HUP
VALUE FOR MONEY
VALUE FOR TIME
A PEACE OF MIND
HOTLINE: 6741 9997

Post an Ad Advertiser Login Ways of Selling

Browse by Category

Sort by Date Posted 20 results/page

18 vehicles

Forester

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Forester		Any	Any	2018	Any	Any	Any	Available
	Subaru	Forester 2.0i-L Sunroof	\$82,500	\$9,040 /yr	07-Jul-2018	1,995 cc	53,000 km	SUV	Available
	1 Owner, Motor Image (Agent) Unit With 5 Years Unlimited Mileage Warranty On Engine. Full Agent Service Records From Day 1. Lowest... Bavarian Marques Pte Ltd Posted: 21-Feb-2020 Tags: 2018 Subaru Forester, 2018 subaru forester, Subaru Forester, subaru forester, Subaru, Forester, forester, Used Subaru								
	Subaru	Forester 2.0i-L Sunroof	\$86,888	\$9,070 /yr	19-Dec-2018	1,995 cc	30,000 km	SUV	Available
	100% Accident Free, Tip Top Driving Condition, Pristine Condition In The Interior And Exterior, Still Under Warranty, Fully Maintained By... Posted: 21-Feb-2020 Tags: 2018 Subaru Forester, 2018 subaru forester, Subaru Forester, subaru forester, Subaru, Forester, forester, Used Subaru								
	Subaru	Forester 2.0i-L Sunroof	\$84,800	\$9,180 /yr	21-Aug-2018	1,995 cc	22,000 km	SUV	Available
	Flexible Bank, In House Loan And Full Loan Available! 1 Owner Only, Accident Free, Agent Maintained With Existing Agent Warranty, Sm... SKL Automobile Pte Ltd Posted: 20-Feb-2020 Tags: 2018 Subaru Forester, 2018 subaru forester, Subaru Forester, subaru forester, Subaru, Forester, forester, Used Subaru								
	Subaru	Forester 2.0i-L Sunroof	\$82,800	\$9,190 /yr	30-May-2018	1,995 cc	38,456 km	SUV	Available
	Latest Addition~! Agent Maintained With Existing Agent Warranty, 1 Owner, Quiet And Responsive Drive Feel, Spacious Cabin, Like New... Posted: 19-Feb-2020 Tags: 2018 Subaru Forester, 2018 subaru forester, Subaru Forester, subaru forester, Subaru, Forester, forester, Used Subaru								
		Stainless Steel Window Chrome Moulding							
	Subaru Forester 2010 changed to Stainless Steel Window Chrome Moulding for Sale in Town! More info about this product								
	Subaru	Forester 2.0i-L Sunroof	\$80,800	\$8,840 /yr	07-Jul-2018	1,995 cc	25,000 km	SUV	Available
	1 Careful Owner! Agent Warranty Till Jul 2023! Showroom Condition! 100% Loan Approval, Loan Up To 100%! Bank/In-House Loan Ava... Golden Charter Pte Ltd Posted: 16-Feb-2020 Tags: 2018 Subaru Forester, 2018 subaru forester, Subaru Forester, subaru forester, Subaru, Forester, forester, Used Subaru								
	Subaru	Forester 2.0i-L Sunroof	\$84,800	\$9,150 /yr	01-Sep-2018	1,995 cc	24,000 km	SUV	Available
	1 Owner, Low Mileage! Fully Agent Serviced, Under Agent Warranty! Original Paintwork! Road Tax Till End Aug 20! Flexible Loan Packag... Posted: 17-Feb-2020 Tags: 2018 Subaru Forester, 2018 subaru forester, Subaru Forester, subaru forester, Subaru, Forester, forester, Used Subaru								
	Subaru	Forester 2.0i-L Sunroof	\$79,000	\$9,010 /yr	28-Feb-2018	1,995 cc	35,500 km	SUV	Available
	Loan Interest At 2.28%. Soundproof Done For 4 Doors And Trunk. Upgraded To Focal And Hezt Speakers With Alpine Amp And Pioneer... Compare								

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	455F
Vehicle Details	
Vehicle No.:	SMC5606A
Vehicle to be Exported:	No
Intended Deregistration Date:	21 Feb 2020
Vehicle Make:	SUBARU
Vehicle Model:	FORESTER 2.0I-L CVT AWD SR
Primary Colour:	Black
Manufacturing Year:	2018
Engine No.:	FB20YE28557
Chassis No.:	JF1SJ5KC5JG111505
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$13,462.00
Original Registration Date:	10 Jul 2018
First Registration Date:	10 Jul 2018
Transfer Count:	0
Actual ARF Paid:	\$13,462.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	09 Jul 2028
PARF Rebate Amount:	\$10,096.00
Intended COE Rebate Details	
COE Expiry Date:	09 Jul 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$33,900.00
COE Rebate Amount:	\$28,416.00
Total Rebate Amount:	\$38,512.00

The information contained herein is correct as at 21 Feb 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/02/2020 15:02
Date Of Accident	21/02/2020 08:00
Exact Location Of Accident	BEDOK NORTH AVENUE 3 TOWARDS PIE(TUAS) SLIP ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMC5606A
Insured/Policyholder	
Name Of Registered Owner	HENG KIM GUAN, TAVERN
NRIC No	SXXXX455F
Email Address	TAVERN_HENG@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-94526477
Alternative Phone No	OFFICE-94526477
Vehicle Particulars	
Manufacturer	SUBARU
Model	FORESTER-2.0 I-L CVT AWD SR (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	ERGO INSURANCE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	DMPG19005561
Cover Note Number	10/07/2019 - 09/07/2020

Driver

Name of Driver	HENG KIM GUAN, TAVERN
NRIC No	SXXXX455F
Date Of Birth	08/11/1983
Occupation	INDOOR
Date Of Driving Pass	23/09/2003
Driving Experience	16 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-94526477
Fax Number	
Contact Number	OFFICE-94526477
EEmail Address	TAVERN_HENG@HOTMAIL.COM

Address	BLK 110 LENGKONG TIGA #06-239
Postcode	S410110
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
Insurance Company of Driver's Own Vehicle	-

General information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	AFTER RAIN
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO REPORT ATTACHED.


Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GY7673Y
Vehicle Make/Model/Colour	NA
Details Of Properties	NA
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	NA
NRIC/Passport Number	
Contact Number	NA
Address	NA
Postcode	NA
Insurance Company Name	
Nature Of Damage	NA
No. Of Passenger (Including Driver)	

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


On 21.02.2020 at 8am, I was travelling along Bobb North Avenue 3
Towards PIE (Tuar) Slip Road. In front the vehicle slow down and stopped.
I follow suddenly vehicle B hit on my vehicle.

DECLARATION

✓We declare the foregoing particulars are true in every respect.



Policyholder's Signature
Date & Time:



Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Not Authorized
LKK

24/2/20
1/5 @ 5000 /
4 Days.

FASTECH AUTO PTE LTD
BLK1 KAKI BUKIT AVE 6
#01-46,48,50 AUTOBAY
SINGAPORE 417883

VEHICLE NO: SMC 5606A

QTY	PARTICULAR			
1 PCS	TAILGATE		R	\$2,850.20 X
1 PCS	TAILGATE REAR LOGO	88.00	RM	\$145.00
1 PCS	TAILGATE 'SUBARU' EMBLEM	72.00	RM	\$92.00
1 PCS	TAILGATE 'AWD' EMBLEM	72.00	ALL	\$85.00
1 PCS	TAILGATE 'FORESTER' EMBLEM	75.00	RM	\$105.00
1 PCS	TAILGATE 'SPORT' EMBLEM	70.00	RM	\$102.00
1 PCS	TAILGATE WEATHERSTRIP		11	\$288.00 X
1 PCS	TAILGATE INNER LOCK		11	\$450.00 X
1 PCS	TAILGATE INNER TRIM BOARD		11	\$788.00 X
1 PCS	REAR WINDSCREEN MOULDING		11	\$125.00 X
1 PCS	REAR BUMPER	980.20	DD/DE	\$1,050.00
1 PCS	REAR BUMPER LOWER SKIRTING	1150.00	CR	\$1,200.00
2 PCS	REAR BUMPER REFLECTORS @\$95.00	65.00	OL/CR	\$190.00
1 PCS	REAR BUMPER REINFORCEMENT	460.50	BE	\$715.00
2 PCS	REAR BUMPER SIDE RETAINERS @\$65.00		11	\$130.00 X
1 SET	REAR BUMPER CLIPS		RM	\$50.00
1 PCS	REAR END PANEL		DD	\$350.00
1 PCS	REAR END PANEL TOP GARNISH		11	\$895.00 X
2 PCS	TAILLAMPS @\$850.00		11	\$1,700.00 X
1 PCS	REAR EXHAUST	688.00	DD	\$1,220.00
2 PCS	REAR EXHAUST MOUNTINGS @\$60.00		11	\$120.00 X
				\$12,350.20
	S.NETT			
1 SET	REAR BUMPER REVERSE SENSOR		Shorled	\$280.00 200
1 PCS	REAR BUMPER TOP PLATE		BE	\$600.00 580
1 PCS	REAR EXHAUST CHROME		BE	\$120.00 80
1 PCS	REAR WINDSCREEN SEALANT		NA	\$50.00 X
1 PCS	REAR END PANEL SEALANT		RM	\$50.00
	LABOUR CHARGES			
	TO CHECK WIRING			\$80.00 30
	TO DISMANTLE & REPLACING REVERSE SENSOR			\$80.00 30
	TO DISMANTLE & REFIX REAR WINDSCREEN		11	\$150.00 X
	TO TRANSFER TAILGATE MECHANISM		11	\$100.00 X
	TO DISMANTLE & REFIX CUSHION UPHOLSTREY			\$120.00 80
	TO SPRAY RUST PROOFING			\$100.00 30
	TO DISMANTLE & REPLACING REAR EXHAUST			\$100.00 60
	LABOUR FOR PANEL BEATING & REPLACING PARTS			\$1,080.00 800
	TO PUTTY & SPRAY PAINTING			\$1,500.00 1000
	TOTAL			\$16,760.20

(202)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be identified and is subject to final approval from Insurers Company

Acknowledged by Repairer
Signature:
Date:

4120.7
3296.58
6288.58

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20003084/UQD3N2
Date: 12/03/2020

REFERENCE

Handling Insurer:	ERGO Insurance Pte. Ltd.	Policy No:	
Claimant Vehicle No :	SMC5606A	Insured Vehicle No :	GY7673Y
Date of Loss:	21/02/2020	Nature of Claim:	TP
		Claim No:	CDMFG20000331

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMC5606A	Engine No:	FB20YE28557
Make & Model:	SUBARU FORESTER, 2.0 I-L CVT AWD SR (A)	Chassis No:	JF1SJ5KC5JG111505
Reg. Date:	10/07/2018 (Man. Year: 2018)	Odometer:	26196 km
Colour:	Grey		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,750.20	4,206.56	9,543.64	69.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,310.00	2,050.00	1,260.00	38.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,060.20	6,256.56	10,803.64	63.33
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	17,060.20	5,000.00	12,060.20	70.69
+ GST 7.00/7.00% (S\$)	1,194.21	350.00	844.21	70.69
Nett Amount (S\$)	18,254.41	5,350.00	12,904.41	70.69

INSPECTION

Date of Assignment:	24/02/2020	
Date Inspected:	24/02/2020	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 12 Mar 2020)

Parts: M1-SUV SUBARU FORESTER 2.0 I-L CVT AWD SR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMC5606A)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Repair	2,850.20 F	*- FL
2	1		*TAILGATE REAR LOGO	Necessary	145.00 F	*88.00 FL
3	1		*TAILGATE SUBARU EMBLEM	Necessary	92.00 F	*72.00 FL
4	1		*TAILGATE AWD EMBLEM	Necessary	85.00 F	*72.00 FL
5	1		*TAILGATE FORESTER EMBLEM	Necessary	105.00 F	*75.00 FL
6	1		*TAILGATE SPORT EMBLEM	Necessary	102.00 F	*70.00 FL
7	1		*TAILGATE WEATHERSTRIP	Not Necessary	288.00 F	*- FL
8	1		*TAILGATE INNER LOCK	Not Necessary	450.00 F	*- FL
9	1		*TAILGATE INNER TRIM BOARD	Not Necessary	788.00 F	*- FL
10	1		*REAR WINDSCREEN MOULDING	Not Necessary	125.00 F	*- FL
11	1		*REAR BUMPER	Dented/Deformed	1,050.00 F	*980.20 FL
12	1		*REAR BUMPER LOWER SKIRTING	Cracked	1,200.00 F	*1,150.00 FL
13	1		*REAR BUMPER REFLECTORS	O/s Cracked	190.00 F	*65.00 FL
14	1		*REAR BUMPER REINFORCEMENT	Bent	715.00 F	*460.50 FL
15	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	130.00 F	*- FL
16	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
17	1		*REAR END PANEL	Dented	350.00 F	*350.00 FL
18	1		*REAR END PANEL TOP GARNISH	Not Necessary	895.00 F	*- FL
19	2		*TAILLAMPS	Not Necessary	1,700.00 F	*- FL
20	1		*REAR EXHAUST	Dented	1,220.00 F	*688.00 FL
21	2		*REAR EXHAUST MOUNTINGS	Not Necessary	120.00 F	*- FL
22	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
23	1		*REAR BUMPER TOP PLATE	Bent	600.00 FS	*580.00 FS
24	1		*REAR EXHAUST CHROME	Bent	120.00 FS	*80.00 FS
25	1		*REAR WINDSCREEN SEALANT	Not Necessary	50.00 FS	*- FS
26	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	13,750.20	5,030.70
- List Item Discount on L Items 0.00/20.00% (S\$)	0.00	824.14
Total Parts (S\$)	13,750.20	4,206.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING REVERSE SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	0.00
4	TO TRANSFER TAILGATE MECHANISM	New	100.00	0.00
5	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
6	TO SPRAY RUST PROOFING	New	100.00	30.00
7	TO DISMANTLE & REPLACING REAR EXHAUST	New	100.00	60.00
8	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,080.00	800.00
9	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,000.00
Gross Labour Cost (S\$)			3,310.00	2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >