

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20003096/ABA3Q2

Date: 30/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900107102

Claimant
Vehicle No : SLS6912L **Insured Vehicle No :** SMM2007X

Date of Loss: 20/02/2020 Nature of Claim: TP Claim No: 3227531568SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLS6912L		
Make & Model:	TOYOTA C-HR HYBRID, 1.8 S CVT (A)	Engine No:	2ZR8126060
Reg. Date:	30/09/2017 (Man. Year: 2017)	Chassis No:	ZYX102046469
Colour:	White	Odometer:	86904 km
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,125.38	3,331.07	14,794.31	81.62
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,040.00	1,210.00	5,830.00	82.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,165.38	4,541.07	20,624.31	81.96
Approved Total (Overridden) (S\$)		3,600.00		
(S\$)	25,165.38	3,600.00	21,565.38	85.69
+ GST 7.00/7.00% (S\$)	1,761.58	252.00	1,509.58	85.69
Nett Amount (S\$)	26,926.96	3,852.00	23,074.96	85.69
+ Loss of Use (5.0 x S\$80.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		4,259.45		
Global Sum Settlement (S\$)		4,250.00		

INSPECTION

Date of Assignment: 21/02/2020

Date Inspected: 02/03/2020 Inspected At:

Dynamic Autowork Pte. Ltd (HQ)
8 Kaki Bukit Ave 4, #08-09 Premier @
Kaki Bukit
Singapore 415875

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	1,080.60 FL	*- FL
2	1		*FRONT BUMPER SIDE RETAINER	Not Necessary	107.40 FL	*- FL
3	1		*FRONT DOOR LOWER PROTECTOR RH	Cut	265.10 FL	*265.10 FL
4	1		*FRONT FENDER RH	Repair	578.60 FL	*- FL
5	1		*FRONT FENDER ARCED GARNISH RH	Not Necessary	180.80 FL	*- FL
6	1		*FRONT FENDER COWLING RH	Not Necessary	156.40 FL	*- FL
7	1		*FRONT WHEEL RIM RH	Cut	1,185.23 FS	*500.00 FS
8	1		*FRONT ABS SENSOR RH	Not Necessary	480.20 FL	*- FL
9	1		*FRONT KNUCKLE ARM RH	Not Necessary	450.30 FL	*- FL
10	1		*FRONT KNUCKLE BEARING RH	Not Necessary	199.50 FL	*- FL
11	1		*FRONT WHEEL HUP RH	Not Necessary	367.70 FL	*- FL
12	1		*FRONT SHOCK ABSORBER RH	Not Necessary	530.60 FL	*- FL
13	1		*FRONT LOWER ARM RH	Not Necessary	548.70 FL	*- FL
14	1		*SIDE MIRROR RH	Not Necessary	1,441.90 FL	*- FL
15	1		*FRONT DOOR RH	Dented	1,295.10 FL	*1,295.10 FL
16	1		*FRONT DOOR OUTER RH	Not Necessary	175.40 FL	*- FL
17	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	325.10 FL	*- FL
18	1		*FRONT DOOR INNER LOCK RH	Not Necessary	589.10 FL	*- FL
19	1		*FRONT DOOR LOCK CATCH RH	Not Necessary	24.20 FL	*- FL
20	1		*FRONT DOOR INNER TRIM BOARD RH	Not Necessary	1,097.10 FL	*- FL
21	1		*FRONT DOOR POWER WINDOW MOTOR RH	Not Necessary	779.10 FL	*- FL
22	1		*FRONT DOOR SPEAKER RH	Not Necessary	436.60 FL	*- FL
23	1		*FRONT DOOR REGULATOR RH	Not Necessary	248.50 FL	*- FL
24	1		*SIDE SKIRT RH	Cut	609.70 FL	*609.70 FL
25	1		*REAR DOOR RH	Dented	1,279.80 FL	*1,279.80 FL
26	1		*REAR DOOR LOWER GARNISH PROTECTOR RH	Cut	258.40 FL	*258.40 FL
27	1		*REAR DOOR OUTER MOULDING RH	Not Necessary	167.30 FL	*- FL
28	2		*REAR DOOR HINGE RH	Not Necessary	97.80 FL	*- FL
29	1		*REAR DOOR CHECKER RH	Not Necessary	106.70 FL	*- FL
30	1		*REAR DOOR WEATHERSTRIP RH	Not Necessary	319.40 FL	*- FL
31	1		*REAR DOOR INNER LOCK RH	Not Necessary	568.70 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
32	1		*REAR DOOR LOCK CATCH RH	Not Necessary	25.30 FL	*- FL
33	1		*REAR DOOR INNER TRIM BOARD RH	Not Necessary	976.40 FL	*- FL
34	1		*REAR DOOR POWER WINDOW MOTOR RH	Not Necessary	752.30 FL	*- FL
35	1		*REAR DOOR SPEAKER RH	Not Necessary	214.70 FL	*- FL
36	1		*REAR FENDER APCED GARNISH RH	Not Necessary	194.60 FL	*- FL
37	1		*REAR WHEEL RIM RH	Not Necessary	1,580.30 FL	*- FL
38	1		*REAR ABS SENSOR RH	Not Necessary	256.40 FL	*- FL
39	1		*REAR LOWER ARM RH	Not Necessary	542.30 FL	*- FL
40	1		*REAR UPPER ARM RH	Not Necessary	625.40 FL	*- FL
41	1		*REAR SWING ARM RH	Not Necessary	594.70 FL	*- FL
42	1		*REAR SHOCK ABSORBER RH	Not Necessary	530.60 FL	*- FL
43	1		*REAR LINKAGE RH	Not Necessary	101.40 FL	*- FL
44	1		*SET FRONT BUMPER CLIP	Not Necessary	50.00 FS	*- FS
45	1		*SET FRONT FENDER COWLING CLIP	Not Necessary	50.00 FS	*- FS
46	1		*SET FRONT FENDER ARCED GARNISH CLIP LH	Not Necessary	50.00 FS	*- FS
47	1		*FRONT WHEEL TYRE RH	Not Necessary	450.00 FS	*- FS
48	1		*SIDE SKIRT RH CLIP	Necessary	80.00 FS	*30.00 FS
49	1		*SET FRONT DOOR OUTER MOULDING CLIP RH	Not Necessary	50.00 FS	*- FS
50	1		*SET FRONT DOOR TRIM BOARD CLIP	Not Necessary	50.00 FS	*- FS
51	1		*SET SIDE SKIRT CLIP RH	Repeated	80.00 FS	*- FS
52	1		*SET REAR DOOR LOWER GARNISH PROTECTOR CLIP RH	Necessary	50.00 FS	*20.00 FS
53	1		*SET REAR DOOR TRIM BOARD CLIP	Not Necessary	80.00 FS	*- FS
54	1		*SET REAR FENDER ARCED GARNISH CLIP RH	Not Necessary	50.00 FS	*- FS
55	1		*BRAKE OIL	Not Necessary	30.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	23,415.43	4,258.10
- List Item Discount on L Items 25.00/25.00% (\$\$)	5,290.05	927.03
Total Parts (\$\$)	18,125.38	3,331.07

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PANEL BEAT ,REMOVE AND REPLACE PARTS	New	1,800.00	500.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	400.00
3	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	350.00	0.00
4	TUFF COAT	New	250.00	40.00
5	CONDUCT WATER LEAKAGE TEST	New	100.00	0.00
6	WIRING CHECK	New	180.00	30.00
7	REMOVE AND REFIX FRONT UNDERCARRIAGE	New	650.00	0.00
8	REMOVE AND REFIX POWER STEERING RACK AND PINION	New	350.00	0.00
9	REMOVE & REFIX AUDIO SPEAKER	New	100.00	0.00
10	RESET ABS LIGHT	New	350.00	0.00
11	TRANFER FRONT DOOR MECHANISM	New	80.00	80.00
12	TRANFER REAR DOOR MECHANISM	New	80.00	80.00
13	REMOVE AND REFIX REAR UNDERCARRIAGE	New	650.00	0.00
14	FOUR WHEEL ALIGNMENT	New	120.00	80.00
15	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
Gross Labour Cost (\$\$)			7,040.00	1,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >