



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

NOT Authorised

date

2/5 to 4/100/?
S day:

Date: 24/02/2020

Car Number: SJL6926H

Model: HONDA CIVIC

Damaged Area: (Rear Portion)

Repairer Estimation Cost of Repair:

Supplementary may be included during the cost of repair:

Parts / Material:

1	Rear Bumper	678.60
2	Rear Bumper Retainer @ \$48.20	
3	Rear Bumper Bracket @ \$45.60	
4	Rear Bumper Reinforcement	
5	Rear Bumper Clips	50.00
6	BootLid	695.70
7	Bootlid Badge	38.50
8	Bootlid Badge (TYPE R)	
9	Bootlid Lamp @ \$336.20	
10	Bootlid Lamp Clips	
11	Bootlid Inner lock	
12	Bootlid Catch	
13	Bootlid weather Strip	188.20
14	Rear Taillamp @ \$513.70	329.50
15	Rear End Panel	387.30
16	Rear End Panel Top Garnish	
17	Rear End Panel Top Garnish Clips	
18	Rear Fender @ \$876.30	
19	Rear Fender Inner Shield @ \$394.20	
20	Rear Fender Inner Shield Clips	
21	Rear Exhaust Pipe Mounting @ \$48.40	
22	Rear Exhaust Heat Shield	
23	Spare Tyre Panel	
24	Spare Tyre Top Trim	
25	Spare Tyre Top Board	

De/to	\$	860.00	
17	\$	96.40	X
17	\$	91.20	X
25	\$	286.20	X
25	\$	60.00	
20/300	\$	852.00	
25	\$	98.00	
25	\$	82.00	
17	\$	672.40	X
17	\$	30.00	X
25	\$	213.60	
17	\$	65.00	X
25	\$	275.00	
0/500	\$	1,027.40	120
20/300	\$	567.40	
25	\$	195.20	
17	\$	60.00	X
17	\$	1,752.60	X
17	\$	788.40	X
17	\$	60.00	X
17	\$	96.80	X
25	\$	145.00	X
25	\$	997.40	X
17	\$	195.80	X
17	\$	256.30	X

Parts:	\$	9,824.10
Less Parts 20%:	\$	1,964.82
Total Parts:	\$	7,859.28

2877.60
202
230208

Special Net Items:

16f	Rear Bumper Diffuser (Accessories)	
	Rear Exhaust End Pipe (Accessories)	
	Reverse Sensor	
	Rear Windscreen Glass Inner Seal	
	Rear Windscreen Glass Sealant	
	Rear Number Plate With Garnish	
	Rear Exhaust Gum	
	Rear End Panel Sealant	

De/to	\$	1,250.00	600
500	\$	1,750.00	X
500	\$	250.00	200
17	\$	120.00	X
17	\$	80.00	X
17	\$	80.00	X
17	\$	120.00	X
25	\$	80.00	40

Total S/N Parts:	\$	3,730.00
------------------	----	----------

Labour :

To Putty, Spray Paint on Rear Affected Accident Areas	\$ 1,200.00	900
To Remove & Renew Rear Affected Accident Areas	\$ 1,400.00	800
To Transfer All Bootlid Components to Facilitate Repairs	\$ 150.00	60
To Transfer All Bootlid Interior Components to Facilitate Repairs <i>upholstery</i>	\$ 150.00	80
To Check & Re-Connect all electrical wiring	\$ 50.00	20
To Re-position & Install Reverse Sensor	\$ 150.00	50
To Remove & Install Rear Windscreen Glass	\$ 120.00	X
To Conduct Water Leakage Test	\$ 150.00	X
To Re-Programme & Reset Diagnostic	\$ 250.00	X
To Rust Proof Affected Areas	\$ 100.00	80
Total Labour :		\$ 3,720.00

TOTAL PARTS : \$ 7,859.28
TOTAL SPECIAL NET ITEM: \$ 3,730.00
TOTAL LABOUR : \$ 3,720.00
TOTAL REPAIR COST : \$ 15,309.28

P-2302.08
S.N- 840.00
L- 1990.00

5132.08
203
4105.66

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: