



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

Tel: 9450 7920

zoomautowerks@gmail.com

Car Number: SLC1331E

Model : LEXUS

Damaged Area: (Front Portion)

Repairer Estimation Cost of Repair :

Supplementary may be included during the cost of repair :

Date: 24/02/2020

Parts / Material :

- 1 Front Bumper 961.12
- 2 Front Bumper Fog Lamp @ \$420.00
- 3 Front Bumper Garnish @ \$114.60
- 4 Front Bumper Lower Centre Grille 263.50
- 5 Front Bumper Reinforcement
- 6 Front Bumper Sponge 245.20
- 7 Front Bumper Retainer @ \$96.60
- 8 Front Bumper Bracket @ 107.40
- 9 Front Bumper Lower Engine Cover
- 10 Front Bumper Tow Garnish 22.30
- 11 Front Bumper Headlamp Nozzle @ \$98.00
- 12 Front Number Plate Base Garnish
- 13 Front Bumper Clips 50.00
- 14 Front Bumper Sensor Wire
- 15 Front Bumper Sensor (ORI - 1 Set) 315.02
- 16 Front Bumper Sensor Ring (ORI - 1 Set)
- 17 Front Bumper Centre Grille Chrome
- 18 Front Radiator Grille
- 19 Front Radiator Grille Logo
- 20 Front Radiator Grille Clips
- 21 Front Headlamp HID/LED @ \$2786.40
- 22 Front Fender
- 23 Front Fender Inner Shield @ \$296.40
- 24 Front Fender Inner Shield Clips
- 25 Front Support Panel

DO/R	\$	1,986.70	
11	\$	840.00	X
11	\$	229.20	X
Torn	\$	326.40	
11	\$	786.40	X
Torn	\$	328.70	
11	\$	193.20	X
11	\$	214.80	X
11	\$	482.40	X
Re	\$	58.20	
11	\$	196.00	X
Torn	\$	78.20	
11	\$	80.00	
11	\$	794.20	X
slush	\$	1,908.40	INC
11	\$	284.20	X
scr	\$	386.70	
ole	\$	586.70	
11	\$	176.20	X
11	\$	60.00	X
11	\$	5,572.80	INC
11		Repair	X
11	\$	592.80	X
11	\$	120.00	X
11		Repair	X

Parts : \$ 16,282.20

Less Parts 10% : \$ 1,628.22

Total Parts : \$ 14,653.98

7-5895.64
102
5125.62

Special Net Items :

Front Number Plate W/Garnish

Radiator Coolant

Best	\$	80.00	40
11	\$	80.00	X
Total S/N Parts :	\$	160.00	

Labour :

To Remove, Repair & Renew Affected Accident Areas	\$	1,200.00	380
To Putty, Spray Paint on Affected Accident Areas	\$	1,200.00	400
To Check & Re-Connect all electrical wiring	\$	50.00	20
To Remove, Install & Conduct Radiator Pressure Leakage Test	\$	11 200.00	X
To Remove, Install AC Condenser & Top Up Gas	\$	11 200.00	X
To Conduct Wheel Alignment	\$	11 200.00	X
To Conduct Diagnostic & Reset Engine Mangement	\$	450.00	
To Re-position Front Sensor & Angle Sensor	\$	250.00	50
To Rust Proof Affected Areas	\$	11 150.00	X
Total Labour :	\$	3,900.00	

TOTAL PARTS :	\$ 14,653.98
TOTAL SPECIAL NET ITEM :	\$ 160.00
TOTAL LABOUR :	\$ 3,900.00
TOTAL REPAIR COST :	\$ 18,713.98

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 5125.62
S.V - 40.00
L - 850.00

6015.62
202

4812.49