

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 30892

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/TP/0211/2020/NS
Date	:	27-Feb-20

Vehicle NOT IN workshop. Please arrange for survey.

Your insured veh no : GBB 9888 L

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Soo Choo Beng
Address	:	113 Prince Charles Crescent #03-31 Singapore 159023
Telephone	:	(HP) +65 91854151
Type of Claim	:	Third Party Claims
Policy No.	:	1800096590
Vehicle No	:	SMD 5529 J
Model Code	:	Audi Q2 1.0 TFSI S Tronic
Model / Year	:	24/8/2018
Engine No	:	CHZ 850665
Chassis No	:	WAUZZZGA7JA080891
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	22-Feb-20
Place of Accident	:	U-turn At Dunearn Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMD 5529 J

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N	\$ 280.00	
2	To remove and transfer rear lid's convenience lock system, wire harness and tail lights and rear wiper assy.	S/N	\$ 480.00	
3	To renew rear windscreen for rear lid renewal.	S/N	\$ 480.00	
4	To install solar film for rear windscreen.	S/N	\$ 400.00	
5	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	S/N	\$ 480.00	
SUB TOTAL LABOUR CHARGES		:	<u>\$ 2,120.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMD 5529 J

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
6	To dismantle and renew rear bumper and rear lid. To cut out and weld end panelling. Re-organise rear crash management components. Reinstall all parts removed.	\$ 4,800.00	
7	To respray rear bumper, rear lid, hinges, end panelling and spare wheel housing.	\$ 4,500.00	
8	To renew lhs rear exhaust silence. To align to position.	S/N \$ 480.00	
9	To carry out diagnostic check.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		: \$ 12,092.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMD 5529 J

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remarks
1	REAR BUMPER	\$ 1,108.00	
2	REAR BUMPER FIXING PARTS	\$ 73.00	
3	REAR BUMPER SPOILER	\$ 268.00	
4	REAR LIGHT REFLECTOR - LH	\$ 28.00	
5	TAIL LIGHT - LH	\$ 1,245.00	
6	TAIL LIGHT TRIM - LH	\$ 28.00	
7	REAR BUMPER CARRIER	\$ 517.00	
8	REAR BUMPER HOLDING STRAP - LH / RH	2 \$ 24.00	
9	REAR BUMPER GUIDE SECTION - LH / RH	2 \$ 102.00	
10	REAR PARKING AID SENSOR - OUTER / INNER	2 TBC	
11	REAR PARKING AID SEAL RING	4 \$ 14.00	
12	REAR WHEEL COVER - LH / RH	2 \$ 320.00	
13	REAR LID	\$ 2,221.00	
14	REAR LID HINGE	2 \$ 280.00	
15	REAR LID ATTACHMENT PARTS	\$ 113.00	
16	REAR LID LOCK STRIKER	\$ 274.00	
17	REAR LID FLAP GASKET	\$ 112.00	
18	REAR LID LOCK STRIKER	\$ 232.00	
19	BONNET LOCK COVER	\$ 12.00	
20	PACKING ADHESIVE	\$ 18.00	
SUB TOTAL SPARE PARTS CHARGES		: \$ 6,989.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMD 5529 J

S/N	Parts Description	<u>Damaged Parts & Prices</u>	
		S/Nett	Remarks
21	AUDI EMBLEM	\$ 117.00	
22	Q2 INSCRIPTION	\$ 90.00	
23	TFSI INSCRIPTION	\$ 90.00	
24	SPOILER FIXING PARTS	\$ 125.00	
25	REAR WINDSCREEN SEALANT	\$ 734.00	
26	PRIMER	\$ 19.00	
27	CROSS PANEL REINFORCEMENT	\$ 691.00	
28	REAR CROSS PANEL	\$ 231.00	
29	REAR SILENCER	\$ 667.00	
30	REAR SILENCER DUAL CLIP	\$ 55.00	
31	EXHAUST SYSTEM RETAINER	2 \$ 77.00	
32	REAR NO PLATE	S/N \$ 40.00	
33	ACRYLIC SEALANT	S/N \$ 180.00	
34	CAVITY WAX	S/N \$ 140.00	
35	STONE CHIP	S/N \$ 180.00	
36	REAR WINDSCRREN SEALANT	S/N \$ 200.00	
37	SUNDRIES	\$ 400.00	
TOTAL SPARE PARTS CHARGES		: \$ 11,025.00	
TOTAL LABOUR CHARGES		: \$ 12,092.00	
GRAND TOTAL		: \$ 23,117.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant