

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

**WIP : 30892**

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/TP/0211/2020/NS  
**Date** : 27-Feb-20

**Vehicle NOT IN workshop. Please arrange for survey.**

**Your insured veh no : GBB 9888 L**

### **AIG Asia Pacific Insurance Pte Ltd**

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr Soo Choo Beng  
**Address** : 113 Prince Charles Crescent  
#03-31  
Singapore 159023  
**Telephone** : (HP) +65 91854151  
**Type of Claim** : Third Party Claims  
**Policy No.** : 1800096590  
**Vehicle No** : **SMD 5529 J**  
**Model Code** : Audi Q2 1.0 TFSI S Tronic  
**Model / Year** : 24/8/2018  
**Engine No** : CHZ 850665  
**Chassis No** : WAUZZZGA7JA080891  
**Mileage** : -  
**Date In** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 22-Feb-20  
**Place of Accident** : U-turn At Dunearn Road

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

## Estimated Labour Charges for Accident Vehicle. SMD 5529 ]

| S/n                             | Nature of Jobs                                                                                                                 |        | Estimated Charges         | Surveyor's Recommendations |
|---------------------------------|--------------------------------------------------------------------------------------------------------------------------------|--------|---------------------------|----------------------------|
| 1                               | To remove and transfer rear parking aid. Check function and renew according to damage.                                         | S/N \$ | 280.00 /                  |                            |
| 2                               | To remove and transfer rear lid's convenience lock system, wire harness and tail lights and rear wiper assy.                   | S/N \$ | 480.00 /                  |                            |
| 3                               | To renew rear windscreen for rear lid renewal.                                                                                 | S/N \$ | 480.00 /                  |                            |
| 4                               | To install solar film for rear windscreen.                                                                                     | S/N \$ | 400.00 ?                  | (prink SA)                 |
| 5                               | To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment. | S/N \$ | 480.00 /                  | 420 ✓                      |
| <b>SUB TOTAL LABOUR CHARGES</b> |                                                                                                                                | :      | <u><u>\$ 2,120.00</u></u> |                            |

## Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

Telefax

### Estimated Labour Charges for Accident Vehicle. SMD 5529 I

| S/n                         | Nature of Jobs                                                                                                                                                 | Estimated Charges     | Surveyor's Recommendations |
|-----------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------|----------------------------|
| 6                           | To dismantle and renew rear bumper and rear lid. To cut out and weld end panelling. Re-organise rear crash management components. Reinstall all parts removed. | \$ 4,800.00           | <del>1000</del> 2500 ✓     |
| 7                           | To respray rear bumper, rear lid, hinges, end panelling and spare wheel housing.                                                                               | \$ 4,500.00           | <del>1100</del> 1650 ✓     |
| 8                           | To renew lhs rear exhaust silence. To align to position.                                                                                                       | S/N \$ 480.00         | X                          |
| 9                           | To carry out diagnostic check.                                                                                                                                 | S/N \$ 192.00         | ✓                          |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                                | <b>: \$ 12,092.00</b> |                            |

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel: 6366 2323 Fax: 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SMD 5529 J

| S/N | Parts Description                                            | Damaged Parts & Prices |               |
|-----|--------------------------------------------------------------|------------------------|---------------|
|     |                                                              | S/Nett                 | Remarks       |
| 1   | REAR BUMPER ✓ <i>DD</i>                                      | \$ 1,108.00            | 886.40 ✓      |
| 2   | REAR BUMPER FIXING PARTS <del>-----</del> <i>MC</i> × NN     | \$ 73.00               |               |
| 3   | REAR BUMPER SPOILER ✓ <i>BR</i>                              | \$ 268.00              | 214.00 ✓      |
| 4   | REAR LIGHT REFLECTOR - LH ? × NN                             | \$ 28.00               |               |
| 5   | TAIL LIGHT - LH ✓ <i>CT</i>                                  | \$ 1,245.00            | 996.00 ✓      |
| 6   | TAIL LIGHT TRIM - LH ✓ <i>MC</i>                             | \$ 28.00               | 22.16 ✓       |
| 7   | REAR BUMPER CARRIER ? × NN                                   | \$ 517.00              |               |
| 8   | REAR BUMPER HOLDING STRAP - LH / RH ? × NN                   | \$ 24.00               |               |
| 9   | REAR BUMPER GUIDE SECTION - LH / RH ? × NN2                  | \$ 102.00              |               |
| 10  | REAR PARKING AID SENSOR - OUTER / INNER ? × NN               | TBC                    |               |
| 11  | REAR PARKING AID SEAL RING <del>-----</del> <i>MC</i> × NN 4 | \$ 14.00               |               |
| 12  | REAR WHEEL COVER - LH / RH ✓ <i>MC</i> 2                     | \$ 320.00              | 256.00 ✓      |
| 13  | REAR LID ✓ <i>DD</i>                                         | \$ 2,221.00            | 1776.80 ✓     |
| 14  | REAR LID HINGE × NN 2                                        | \$ 280.00              |               |
| 15  | REAR LID ATTACHMENT PARTS <del>-----</del> <i>MC</i> × NN    | \$ 113.00              |               |
| 16  | REAR LID LOCK STRIKER × NN                                   | \$ 274.00              |               |
| 17  | REAR LID FLAP GASKET × NN                                    | \$ 112.00              |               |
| 18  | REAR LID LOCK STRIKER × NN                                   | \$ 232.00              |               |
| 19  | BONNET LOCK COVER × NN                                       | \$ 12.00               |               |
| 20  | PACKING ADHESIVE ✓ <i>MC</i>                                 | \$ 18.00               | 13.24 ✓ 14.24 |

**SUB TOTAL SPARE PARTS CHARGES : \$ 6,989.00**

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

## Material List for Accident Vehicle Regn No. SMD 5529 1

| S/N                              | Parts Description                              | Damaged Parts & Prices |          |
|----------------------------------|------------------------------------------------|------------------------|----------|
|                                  |                                                | S/Nett                 | Remarks  |
| 21                               | AUDI EMBLEM / <i>nc</i>                        | \$ 117.00              | 93.20 ✓  |
| 22                               | Q2 INSCRIPTION / <i>nc</i>                     | \$ 90.00               | 71.76 ✓  |
| 23                               | TFSI INSCRIPTION / <i>nc</i>                   | \$ 90.00               | 71.76 ✓  |
| 24                               | SPOILER FIXING PARTS ? X NN                    | \$ 125.00              |          |
| 25                               | REAR WINDSCREEN <del>SEALANT</del> / <i>nc</i> | \$ 734.00              | 586.80 ✓ |
| 26                               | PRIMER / <i>nc</i>                             | \$ 19.00               | 14.80 ✓  |
| 27                               | CROSS PANEL REINFORCEMENT ? X NN               | \$ 691.00              |          |
| 28                               | REAR CROSS PANEL ? BT ✓                        | \$ 231.00              | 184.40 ✓ |
| 29                               | REAR SILENCER X NN                             | \$ 667.00              |          |
| 30                               | REAR SILENCER DUAL CLIP X NN                   | \$ 55.00               |          |
| 31                               | EXHAUST SYSTEM RETAINER X NN 2                 | \$ 77.00               |          |
| 32                               | REAR NO PLATE X NN S/N                         | \$ 40.00               |          |
| 33                               | ACRYLIC SEALANT ? NEC ✓ S/N                    | \$ 180.00              | ✓        |
| 34                               | CAVITY WAX ? ✓ NEC S/N                         | \$ 140.00              | ✓        |
| 35                               | STONE CHIP ? NEC ✓ S/N                         | \$ 180.00              | ✓        |
| 36                               | REAR WINDSCRREN SEALANT / <i>nc</i> S/N        | \$ 200.00              | ✓        |
| 37                               | SUNDRIES ? NEC ✓                               | \$ 400.00              | 4.96 ✓   |
| <b>TOTAL SPARE PARTS CHARGES</b> |                                                | <b>: \$ 11,025.00</b>  |          |
| <b>TOTAL LABOUR CHARGES</b>      |                                                | <b>: \$ 12,092.00</b>  |          |
| <b>GRAND TOTAL</b>               |                                                | <b>: \$ 23,117.00</b>  |          |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved  
Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

Name : Steve (LKK) WIL ML  
Surveyed Date : 28/2/20, 11.00a  
Authorised Date : 7-5 dys  
Excess Cost : P/P  
Liability :  
Remarks : Ny Bally

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant