

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20003113/UKA3Q2
Date: 29/04/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900024445-01
Claimant
Vehicle No : SLA8606C **Insured Vehicle No :** SJP7880C
Date of Loss: 22/02/2020 Nature of Claim: TP Claim No: 8280380319SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLA8606C**
Make & Model: MERCEDES-BENZ CLA180, 1.6 (R18 BI) (A) Engine No: 27091030880124
Reg. Date: 21/03/2016 (Man. Year: 2015) Chassis No: WDD1173422N323575
Colour: Grey Odometer: 68495 km
Engine Capacity: 1595 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|---|-------------------|-------------------|-------------------|---------------|
| Parts | 3,906.90 | 0.00 | 3,906.90 | 100.00 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,800.00 | 520.00 | 1,280.00 | 71.11 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Nett Amount (S\$) | 5,706.90 | 520.00 | 5,186.90 | 90.89 |
| + Car Rental (2.0 x S\$100.00/day) (S\$) | | 200.00 | | |
| + Doc/Search Fee (S\$) | | 2.00 | | |
| Nett Liability (S\$) | | 722.00 | | |

INSPECTION

Date of Assignment: 26/02/2020
Date Inspected: 26/02/2020 Inspected At: Hup Motor Trading & Service (HQ)
Blk 9004 Tampines Street 93, #01-120
Singapore 528838
Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA**Manager:** Khanchna Pothuraj*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---------------------------------|---------------|-------------|--------|
| 1 | 1 | | *FRONT BUMPER | Repair | 1,410.00 FN | *- FN |
| 2 | 20 | | *FRONT BUMPER CLIPS | Not Necessary | 180.00 FN | *- FN |
| 3 | 1 | | *FRONT BUMPER O/S SIDE RETAINER | Not Necessary | 35.00 FN | *- FN |
| 4 | 8 | | *FRONT BUMPER RIVETS | Not Necessary | 72.00 FN | *- FN |
| 5 | 1 | | *FRONT BUMPER O/S DAMPER | Not Necessary | 34.00 FN | *- FN |
| 6 | 1 | | *O/S HEAD LAMP ASSY | Not Necessary | 2,610.00 FN | *- FN |

F=Franchise part. N=NettItemDisc.

| | | |
|---|-----------------|-------------|
| Sub Total (S\$) | 4,341.00 | 0.00 |
| - Nett Item Discount on N Items 10.00/10.00% (S\$) | 434.10 | 0.00 |
| Total Parts (S\$) | 3,906.90 | 0.00 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|--|----------|-------------------------------|-----------------|
| Labour Items | | | | |
| 1 | TO WIRING CHECK UP & DIAGNOSE & RE-SET HEADLIGHT SENSOR | New | 150.00 | 20.00 |
| 2 | LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS ,TO JACK ,STRAIGHTEN & KNOCKING OUT FRONT BUMPER REINFORCEMENT & NECESSARY PARTS ,TO WELD ,RENEW & ALIGN ABOVE PARTS | New | 750.00 | 250.00 |
| 3 | TO PUTTY & RESPRAY PAINTING ON ALL AFECTED ACCIDENT PARTS | New | 900.00 | 250.00 |
| | | | Gross Labour Cost (\$) | 520.00 |
| | | | 1,800.00 | 1,800.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >