

哈 汽 車 貿 易 服 務

HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TP 2984/02/20 Your Ref: _____ Date: 24th FEB 2020

MR SOM CHIN KHOON
30, Upper Serangoon View,
#07-39, Singapore 534208

Estimate cost of repair to MERCEDE BENZ CLA 180 (A) 1.6 Saloon - SLA 8606 C

1 pc front bumper REPAIR		\$ 1,410.00	Nett X
20 pcs front bumper clips NN	© \$ 9.00 N	180.00	" X
1 pc front bumper o/s side retainer NN		35.00	" X
8 pcs front bumper rivets NN	© \$ 9.00 N	72.00	" X
1 pc front bumper o/s damper NN		34.00	" X
1 pc o/s head lamp assy NN		2,610.00	" X
		<u>\$ 4,341.00</u>	Nett
	Less 10%	\$ 434.10	
		<u>\$ 3,906.90</u>	

To wiring check up & diagnose & re-set headlight sensor. 150.00 ✓ 20

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out front bumper reinforcement & necessary parts, to weld, renew & align above parts. 750.00 ✓ 250

To putty & respray painting on all affected accident parts. 900.00 ✓ 250

\$ 5,706.90
=====

Dollars : Five Thousand Seven Hundred Six Dollars And Cents Ninety Only.

HUP MOTOR TRADING & SERVICE

.....
.....
.....

P/P \$ 520 (2 DAYS)

MARCUS