

22/03/2002

GAI

ASS. REC. BY:

REF: CS/AG1 20003124/AY f327 Special Instruction:

ok

Surveyor: Adnan

ASSIGNMENT (Office)

From (Person): Shum Wong of AG1 Date/Time: 26.2.2020 4.51p.m

Estimated Cost: Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No: EP 57T Insured: PC 6436G

at Workshop m/s Xin Yun Auto Tel: 98391555

of Block B #05-23 Premier @ Kaki Bukit M14

Policy No: Claim No: CLMOMVC000003810

Sum Insured: Excess:

Make of Veh: D.O.A. 20.2.2020
(Client's Record)

CA / REV / REP. / REV 24 HRS "W" 26.2.2020 H.O.D. Endorsement:

Date/Time: 26/2/2020 11.19am Person Contacted: xin yi Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	EP 57T - X
	PC 6436G - X

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

EPS7T.

Yr Regn: 2008, Oct.

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Attis

C.C. 1598

Colour

White

A/C: Insured / Std / NI / NA

Sp. Reading

377390

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MR053ZEE1061217&0

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/65 R15

R:

185/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake.

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

26/02/20

Survey held at

Xin Yun.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP Budget Direct.

45 \$1000/- (Red \$10598-88, 91%)

MV:

PV:

Nett:

RECEIVED 20 MAR 2020

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

20/3/20 Typist

Days Of Repair: 3

Resurvey No. of Trip: 3

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

3 + P&S \$

Phone

Other:

Total

300

300

Period Format:

Lump Sum / L&L / F&F

\$1000/-

Nivitha (LKK Auto)

From: Motor Claims <motorclaims@sg.gaig.com>
Sent: Monday, 24 February 2020 4:51 PM
To: kwongloong@populuslaw.com.sg; 'SUR'; Nivitha (LKK Auto)
Cc: Ngian, Kelvyna
Subject: RE: Our Ref:CLMOMVC000003810, ACCIDENT INVOLVING EP 57T AND PC 6436G NEAR SHELL STATION AT PAYA LEBAR/CISCO CENTRE ON 20 FEBRUARY 2020 AT 1730 HOURS [Populus ref: KL/20/0012/PIPD (Leow Hua Ann)]
Attachments: Notification of Accident + PRI.pdf

Without Prejudice

Dear Kwong Loong,

Noted on your request. We will survey on a without prejudice basis.

Aside to LKK,

Please accept assignment for TP survey. Thank you.

Thank you.

Regards

Shery Wong, Executive, Claims | P. +65 68046077 | F. +65 62353354 | shery.wong@sg.gaig.com



Claims | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190



A+ (Superior)
Affirmed August 17, 2018

Moody's
A1 (Good)
Published December 2018

Standard & Poor's
A+ (Strong)
Affirmed February 23, 2018

For more information on our financial ratings, visit GAIG.com/FinancialStrength.

From: kwongloong@populuslaw.com.sg <kwongloong@populuslaw.com.sg>
Sent: 24 February 2020 4:44 PM
To: Motor Claims <motorclaims@sg.gaig.com>; naaz@a-pac.sg; patrick.soo@a-pac.sg; edna.lee@a-pac.sg
Cc: Ngian, Kelvyna <kelvyna.ngian@sg.gaig.com>; 'Xin Yun Auto' <xinyunauto1@gmail.com>
Subject: [External] RE: Our Ref:CLMOMVC000003810, ACCIDENT INVOLVING EP 57T AND PC 6436G NEAR SHELL STATION AT PAYA LEBAR/CISCO CENTRE ON 20 FEBRUARY 2020 AT 1730 HOURS [Populus ref: KL/20/0012/PIPD (Leow Hua Ann)]
Importance: High

WITHOUT PREJUDICE

Dear Shery

Our telephone conversation just now refers. Our client is willing to consider one of your nominees, LKK Auto Consultants, as the SJE. Kindly confirm whether at this stage, it is still possible for parties to agree on LKK Auto Consultants as the SJE.

This email is without prejudice to my client's right to appoint their own surveyor, in the event that LKK Auto Consultants is no longer available as parties' SJE and you are instead insisting on A-PAC.

Please let us hear from you urgently. Tks.

Best Regards,

Kwong Loong
Associate
Advocate and Solicitor (Singapore)



Populus Law Corporation
Havelock II, 2 Havelock Road, #05-14
Singapore 059763

Mobile: +65 9389 1547 | Tel: +65 6909 3436 | Fax: +65 6909 3447

From: Motor Claims <motorclaims@sg.gaig.com>

Sent: Monday, 24 February 2020 3:53 PM

To: kwongloong@populuslaw.com.sg; naaz@a-pac.sg; patrick.soo@a-pac.sg; edna.lee@a-pac.sg

Cc: Ngian, Kelvyna <kelvyna.ngian@sg.gaig.com>

Subject: Re: Our Ref:CLMOMVC000003810, ACCIDENT INVOLVING EP 57T AND PC 6436G NEAR SHELL STATION AT PAYA LEBAR/CISCO CENTRE ON 20 FEBRUARY 2020 AT 1730 HOURS [Populus ref: KL/20/0012/PIPD (Leow Hua Ann)]

Without Prejudice

Dear Kwong Loong,

As there is no agreement to the surveyors proposed by both parties we will appoint Apac to conduct PRI on a without prejudice basis.

Aside to Apac,

Please accept assignment for TP survey. Thank you.

Thank you.

Regards

Shery Wong, Executive, Claims | P. +65 68046077 | F. +65 62353354 | shery.wong@sg.gaig.com



Claims | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190



A+ (Superior)
Affirmed August 17, 2018

Moody's
A1 (Good)
Published December 2018

Standard & Poor's
A+ (Strong)
Affirmed February 23, 2018

For more information on our financial ratings, visit GAIG.com/FinancialStrength.

From: Kwong Loong Ng <kwongloong@populuslaw.com.sg>

Sent: 24 February 2020 10:15 AM

To: Motor Claims <motorclaims@sg.gaig.com>

Subject: [External] Re: Our Ref: CLMOMVC000003810, ACCIDENT INVOLVING EP 57T AND PC 6436G NEAR SHELL STATION AT PAYA LEBAR/CISCO CENTRE ON 20 FEBRUARY 2020 AT 1730 HOURS [Populus ref: KL/20/0012/PIPD (Leow Hua Ann)]

WITHOUT PREJUDICE

Dear Sheryl

1. We do not agree with your proposed surveyors as the Single Joint Expert (SJE).
2. Our proposed surveyors as the SJE are:
 - a. Dave Chang Sincere Appraisal Services
 - b. Ng Kong Beng, Patrick Carlink Consultancy
 - c. Andrew How Prominent Appraiser Services Pte Ltd
 - d. Gan Song Sing, Roger ROG Associates
 - e. Dennis Yap Pal's Appraiser Pte Ltd
 - f. Michael Yap Mc-Coy Appraiser Pte Ltd
 - g. Nicky Seah Absolute Appraisal Services
 - h. William Ng Allied Auto Appraisal
 - i. Foo Phillip Precision Appraisal Services
 - j. Ronald Ng Precision Appraisal Services
 - k. Lee Kok Weng Lee Automobile Appraisals Services
3. If there is no agreement on the SJE, please see to the Pre-Repair Inspection (PRI) soonest possible.

Kwong Loong
(sent from my smartphone. Apologies for any formatting errors)

Show quoted text

On Mon, Feb 24, 2020, 09:40 Motor Claims <motorclaims@sg.gaig.com> wrote:

Without Prejudice

Dear Sirs,

Moving forward please email us at MotorClaims@sg.gaig.com for motor related matters

We append the following list of our panel surveyors:-

1. AJAX Adjusters & Surveyors Pte Ltd
2. A-PAC Adjusters & Surveyors Pte. Ltd.
3. Priority Services
4. RT Appraisal Pte Ltd
5. LKK Auto Consultants


Kindly let us know which SJE is selected and furnish the estimates for the survey to be carried out.

Regards

Shery Wong, Executive, Claims | P. +65 68046077 | F. +65 62353354 | shery.wong@sg.gaig.com



Claims | 3 Temasek Avenue #16-01 Centennial Tower Singapore 039190



For more information on our financial ratings, visit GAIG.com/FinancialStrength.

From: kwongloong@populuslaw.com.sg <kwongloong@populuslaw.com.sg>
Sent: 22 February 2020 10:22 AM
To: General.Claims@sg.gaig.com; Puan, Mui Hong <muihong.puan@sg.gaig.com>

Cc: 'Xin Yun Auto' <xinyunauto1@gmail.com>

Subject: [External] Notification of accident and request for pre-repair inspection - ACCIDENT INVOLVING EP 57T AND PC 6436G NEAR SHELL STATION AT PAYA LEBAR/CISCO CENTRE ON 20 FEBRUARY 2020 AT 1730 HOURS [Populus ref: KL/20/0012/PIPD (Leow Hua Ann)]

Dear Sirs

Please refer to the attached. Please see to the pre-repair inspection soonest possible.

Thank you!

Best Regards,

Kwong Loong

Associate

Advocate and Solicitor (Singapore)



Populus Law Corporation

Havelock II, 2 Havelock Road, #05-14

Singapore 059763

Mobile: +65 9389 1547 | Tel: +65 6909 3436 | Fax: +65 6909 3447

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.



Havelock II, 2 Havelock Road
#05-14, Singapore 059763
Tel +65 6909 3436
Fax +65 6909 3447
www.populuslaw.com.sg

Our Ref : KL/20/0012/PIPD (Leow Hua Ann)

Your Ref: vehicle number **PC 6436G**

Date: 22 February 2020

Great American Insurance Company (Singapore)
3 Temasek Avenue
#16-01 Centennial Tower
Singapore 039190
Attention: Motor Claims Department

BY EMAIL: General.Claims@sg.gaiq.com
MuiHong.Puan@sg.gaiq.com
BY FAX: 6235 2626

Dear Sirs

ACCIDENT INVOLVING EP 57T AND PC 6436G NEAR SHELL STATION AT PAYA LEBAR/CISCO CENTRE ON 20 FEBRUARY 2020 AT 1730 HOURS

(Notice to third party insurer to conduct pre-repair inspection within 2 working days pursuant to paragraphs 2.2 and 2.3 of the Pre-Action Protocol for NIMA cases (Appendix C to the State Courts Practice Directions))

We act for **Leow Hua Ann** who has appointed the undermentioned workshop to repair his vehicle number EP 57T.

Please be informed that the said vehicle can be inspected at:

Name: **XIN YUN AUTO PTE LTD**
Address: Block 8 #05-23 Premier @ Kaki Bukit Avenue 4
Singapore 415875
Contact person: Ms Zhang Yi Xin
Telephone: 9839 1555

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully,

Populus Law Corporation
Cc: client (email)

To insurer's surveyor:
Please initial here after completion of pre-repair inspection. Thank you.

Insurer's surveyor: _____
(Name and signature)
Date: _____

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/02/2020 19:03
Date Of Accident	20/02/2020 17:30
Exact Location Of Accident	NEAR SHELL PAYE LEBAR /CISCO CENTRE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	EP57T
Insured/Policyholder	
Name Of Registered Owner	LEOW HUA ANN
NRIC No	SXXXX804J
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-93827765
Alternative Phone No	OTHERS-93827765

Vehicle Particulars

Manufacturer	TOYOTA
Model	COROLLA ALTIS 1.6 AUTO
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5096076555-02
Cover Note Number	

Driver

Name of Driver	LEOW HUA ANN
NRIC No	SXXXX804J
Date Of Birth	06/04/1974
Occupation	INDOOR
Date Of Driving Pass	26/09/1995
Driving Experience	24 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93827765
Fax Number	
Contact Number	OTHERS-93827765
Email Address	NOEMAIL

Address	BLK 275A #03-252 COMPASSVALE LINK ASPELLA
Postcode	541275
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : GRAB PASSENGER
	GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER ATTACHED;

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PC6436G
Vehicle Make/Model/Colour	AN / NV350 MICROBUS 2.5 4DR 5AT ABS
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:


Driver's Signature
(if driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vacbk@vacom.com.sg
Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

21 FEB 2020

Accident Sketch Plan

SKETCH PLAN




DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


my vehicle was stationary and waiting to move at traffic light while vehicle B PC 6436G moved out and hit my vehicle from rear right behind

The other vehicle didn't stop after hit my vehicle. I follow & stop him.


DECLARATION

We declare the foregoing particulars are true in every respect


Policyholder's Signature
Date & Time:


Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC KAKI BUKIT (VAC)
23 Kaki Bukit Ave 4 #02-02
Singapore 415933
Tel: 67416697 Fax: 67492305
Email: vacb@vicom.com.sg


Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

21 FEB 2020



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

TP Budget Direct

Frome

M12053ZEE106121720

EP57T Toyota Altis

No	Qty	Parts Description	Estimated Parts Price
1	1	Rear bumper assy <i>De-hand</i>	\$ 1,200.00 <i>459</i>
2	1	Rear bumper left bracket	\$ 105.00 <i>+</i>
3	1	Rear bumper right bracket <i>Ne ne</i>	\$ 105.00 <i>+</i>
4	1	Rear bumper left retainer	\$ 85.00 <i>+</i>
5	1	Rear bumper right retainer <i>Ne</i>	\$ 85.00 <i>58</i>
6	1	Rear bumper tow cover <i>Ne Ne</i>	\$ 95.00 <i>+</i>
7	1	Rear bumper top chrome garnish <i>Ne Ne</i>	\$ 255.00 <i>+</i>
8	1	Rear bumper lower spoiler	\$ 190.00 <i>+</i>
9	1	Rear left bumper reflector	\$ 105.00 <i>+</i>
10	1	Rear right bumper reflector <i>Ne Ne</i>	\$ 105.00 <i>+</i>
11	1	Rear right fender assy	\$ 650.00 <i>+</i>
12	1	Rear right fender side protector	\$ 195.00 <i>+</i>
13	1	Rear right side shock absorber assy <i>Ne</i>	\$ 650.00 <i>+</i>
14	1	Rear right side wheel hub bearing <i>Ne</i>	\$ 480.00 <i>+</i>
15	1	Rear right side speed sensor cable	\$ 105.00 <i>+</i>
16	1	Rear fender inner garnish	\$ 350.00 <i>+</i>
17	1	Rear fender inner cowl	\$ 250.00 <i>+</i>
18	1	Rear fender air duct <i>Ne Ne</i>	\$ 80.00 <i>+</i>
19	1	Rear tailgate assy	\$ 1,500.00 <i>+</i>
20	1	Rear tailgate lock mechanism	\$ 280.00 <i>+</i>
21	1	Rear tailgate outer garnish	\$ 250.00 <i>+</i>
22	1	Rear tailgate no plate lamp <i>Ne Ne</i>	\$ 88.60 <i>+</i>
23	1	Rear tailgate right taillamp <i>859</i>	\$ 420.00 <i>+</i>
24	1	Rear right taillamp <i>ut</i>	\$ 680.00 <i>342</i>
25	2	Rear tailgate damper <i>644.25</i>	\$ 285.00 <i>+</i>
26	1	Rear end lower panel <i>Ne Ne</i>	\$ 850.00 <i>+</i>
27	1	Rear end lower panel top garnish <i>Ne Ne</i>	\$ 180.00 <i>+</i>
			\$ 9,623.60
Less 20%			\$ 1,924.72
<i>25</i>			\$ 7,698.88



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

EP57T Toyota Altis

No	Qty	Parts Description	Estimated Parts Price
<u>Special Nett Items</u>			
1	10	Rear bumper clips <i>Neu</i>	\$ 80.00 30
2	6	Rear end lower panel top garnish clips	\$ 80.00 +
3	1	Rear end lower panel sealant	\$ 120.00 +
4	8	Rear tailgate inner trim board clips	\$ 80.00 +
5	6	Rear tailgate outer garnish clips <i>Neu</i>	\$ 50.00 +
10	2	Rear bumper reverse sensor <i>Neu</i>	\$ 250.00 +
11	1	Rear no plate with garnish	\$ 80.00 x
			<hr/>
			\$ 740.00
Total parts			\$ 8,438.88



Xin Yun Auto Private Limited

辛运汽车服务有限公司

Tel: 6634 0858 Email: xinyunauto1@gmail.com

Blk 8 Kaki Bukit Avenue 4 #05-23 Premier Singapore 415875

EP57T Toyota Altis

No	Description	Labour Charges
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$ 1,200.00 ²⁵⁰
2	To putty and spray painting rear and rear right damaged portion.	\$ 1,000.00 ²⁵⁰
3	To check rear lighting and wiring	\$ 80.00 ³⁰
4	To balance rear right wheel	\$ 60.00 +
5	To conduct wheel alignment.	\$ 120.00 +
6	To remove and install rear right undercarriage parts	\$ 350.00 +
7	To remove and install rear inner garnish and facilitate the repair	\$ 150.00 +
8	To remove and install rear exhaust muffler assy.	\$ 100.00 +
9	To remove and install rear bumper reverse sensor	\$ 100.00 ⁵⁰
Total labour :		\$ 3,160.00

Total parts : 8,438.88
Total labour : 3,160.00
Total repair cost : 11,598.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lim.
L/S 26/02/20
03 Days

Total: 1254.25

L/S: 1000



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

GREAT AMERICAN INSURANCE COMPANY

Ref : CS/GAI20003124/Ayf3e2

3 TEMASEK AVENUE
#16-01 CENTENNIAL TOWER
SINGAPORE 039190

Date : 30-03-2020



Code : GAI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PC 6436G	Veh. Inspected	EP 57T
Policy No.		Coverage (\$)	0.00
Claim No.	CLMOMVC000003810	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	24/02/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	MR053ZEE106121720	Colour	WHITE
Odometer	377390	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	WEST LAKE	6 mm
L/H Front Tyre	195/65 R15	WEST LAKE	6 mm
R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm
L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	20/02/2020	Inspection Date	26/02/2020
Survey held at	BLK 8 #05-23 PREMIER @ KAKI BUKIT AVE 4		
Repairer	XIN YUN AUTO PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. EP 57T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER ASSY	DEFORMED	1,200.00	459.00
1	REAR BUMPER LEFT BRACKET	NOT NECESSARY	105.00	-
1	REAR BUMPER RIGHT BRACKET	NOT NECESSARY	105.00	-
1	REAR BUMPER LEFT RETAINER	NOT NECESSARY	85.00	-
1	REAR BUMPER RIGHT RETAINER	NECESSARY	85.00	58.00
1	REAR BUMPER TOW COVER	NOT NECESSARY	95.00	-
1	REAR BUMPER TOP CHROME GARNISH	NOT NECESSARY	255.00	-
1	REAR BUMPER LOWER SPOILER	NOT NECESSARY	190.00	-
1	REAR LEFT BUMPER REFLECTOR	NOT NECESSARY	105.00	-
1	REAR RIGHT BUMPER REFLECTOR	NOT NECESSARY	105.00	-
1	REAR RIGHT FENDER ASSY	NOT NECESSARY	650.00	-
1	REAR RIGHT FENDER SIDE PROTECTOR	NOT NECESSARY	195.00	-
1	REAR RIGHT SIDE SHOCK ABSORBER ASSY	NOT NECESSARY	650.00	-
1	REAR RIGHT SIDE WHEEL HUB BEARING	NOT NECESSARY	480.00	-
1	REAR RIGHT SIDE SPEED SENSOR CABLE	NOT NECESSARY	105.00	-
1	REAR FENDER INNER GARNISH	NOT NECESSARY	350.00	-
1	REAR FENDER INNER COWLING	NOT NECESSARY	250.00	-
1	REAR FENDER AIR DUCT	NOT NECESSARY	80.00	-
1	REAR TAILGATE ASSY	NOT NECESSARY	1,500.00	-
1	REAR TAILGATE LOCK MECHANISM	NOT NECESSARY	280.00	-
1	REAR TAILGATE OUTER GARNISH	NOT NECESSARY	250.00	-
1	REAR TAILGATE NO PLATE LAMP	NOT NECESSARY	88.60	-
1	REAR TAILGATE RIGHT TAILLAMP	NOT NECESSARY	420.00	-
1	REAR RIGHT TAILLAMP	CUT	680.00	342.00
2	REAR TAILGATE DAMPER	NOT NECESSARY	285.00	-
1	REAR END LOWER PANEL	NOT NECESSARY	850.00	-
1	REAR END LOWER PANEL TOP GARNISH	NOT NECESSARY	180.00	-
	LESS 20% DISCOUNT		-1,924.72	-
	LESS 25% DISCOUNT		-	-214.75
			7,698.88	644.25

Report Ref No. CS/GAI20003124/Ayf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
10	REAR BUMPER CLIPS (SN)	NECESSARY	80.00	30.00
6	REAR END LOWER PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	80.00	-
1	REAR END LOWER PANEL SEALANT (SN)	NOT NECESSARY	120.00	-
8	REAR TAILGATE INNER TRIM BOARD CLIPS (SN)	NOT NECESSARY	80.00	-
6	REAR TAILGATE OUTER GARNISH CLIPS (SN)	NOT NECESSARY	50.00	-
2	REAR BUMPER REVERSE SENSOR (SN)	NOT NECESSARY	250.00	-
1	REAR NO PLATE WITH GARNISH (SN)	NOT NECESSARY	80.00	-
			740.00	30.00
	LABOUR			
	LABOUR FOR PANEL BEATING,CUT,WELD,STRAIGHTEN FRONT AFFECTED AREA AND REPLACE FRONT DAMAGED PARTS.		1,200.00	250.00
	TO PUTTY AND SPRAY PAINTING REAR AND REAR RIGHT DAMAGED PORTION.		1,000.00	250.00
	TO CHECK REAR LIGHTING AND WIRING.		80.00	30.00
	TO BALANCE REAR RIGHT WHEEL.	NOT NECESSARY	60.00	-
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	TO REMOVE AND INSTALL REAR RIGHT UNDERCARRIAGE PARTS.	NOT NECESSARY	350.00	-
	TO REMOVE AND INSTALL REAR INNER GARNISH AND FACILITATE THE REPAIR.	NOT NECESSARY	150.00	-
	TO REMOVE AND INSTALL REAR EXHAUST MUFFLER ASSY.	NOT NECESSARY	100.00	-
	TO REMOVE AND INSTALL REAR BUMPER REVERSE SENSOR.		100.00	50.00
			3,160.00	580.00
GRAND TOTAL			11,598.88	1,254.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,000.00

Report Ref No. CS/GAI20003124/Ayf3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.