

SOMPO

Vehicle number	SLT9700G
Make / Model	TOYOTA HARRIER
Chassis number	ZSU600083968
Accident date	23/2/20
Reference	2002-44

Qty Particulars Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	TAILGATE	1224.80 1749.27 <i>bt</i>
2	TAILGATE HINGE	279.22 <i>x R</i>
2	TAILGATE ABSORBER	862.86 <i>x nn</i>
1	TAILGATE INNER TRIM	568.50 860.32 <i>nn</i>
1	TAILGATE OUTER GARNISH	402.26 <i>x nn</i>
1	TAILGATE LOGO	87. 96.12 <i>nn</i>
1	TAILGATE GLASS MOULDING	191.20 231.50 <i>nn</i>
2	TAILGATE LAMP	nn RH-X 1035.92 LH-20 422.80
1	TAILGATE LOCK	385.90 681.20 ? <i>bt</i>
1	TAILGATE LOCK STIKER	121.50 <i>R</i>
1	REAR BUMPER	1304.33 <i>de</i>
2	REAR BUMPER RETAINER	RH x 200.80 LH- <i>nn</i>
1	REAR BUMPER BRACKET	76.48 <i>Rnn</i>
1	REAR BUMPER LOWER GARNISH	396.10 457.68 <i>ant</i>
2	REAR BUMPER REFLECTOR	RH x 171.60 LH- <i>Rnn</i>
1	END PANEL	860.76 <i>R</i>
1	END PANEL TOP GARNISH	443.28 <i>x nn</i>
2	TAILLAMP	nn RH-X 1343.90 LH- <i>nn</i> 480.60
1	SPARE TYRE TOP BOARD	587.77 <i>x</i>
1	SPARE TYER COVER	438.61 <i>x</i>
1	FLOOR PANEL	915.86 <i>x</i>
1	EXHAUST SILENCER	690.35 <i>x</i>
2	EXHAUST MOUNTING	85.68 <i>x</i>
		13897.27
Less 25%		3474.32
		10422.95
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
1	REAR NUMBER PLATE	80.00 <i>x nn</i>
1 SET	RAER BUMPER CLIP	40.00 <i>30 nn</i>
1 SET	TAILGATE INNER TRIM CLIP	60.00 <i>20 nn</i>
1 SET	END PANEL INNER TRIM CLIP	60.00 <i>x nn</i>
1	REAR SAFETY BAR (AFTER MARKET)	1200.00 <i>x nn</i>
1 SET	REVERSE SENSOR	800.00 <i>200 nn</i>
Subtotal		2240.00
Balance C/F		12662.95

5061.23

3795.92

250.

LABOUR AND MISCELLANEOUS CHARGES

	Balance B/F	12662.95	
	CHECK WIRING AND LIGHTNING SYSTEM	60.00	30
2	REMOVE AND REFIT REAR WINDSCREEN	150.00	120
3	REMOVE AND RENEW REAR REVERSE SENSOR	200.00	30
4	REMOVE, REFIT REAR LINING, TRIM AND GARNISH	200.00	60
5	REMOVE AND RENEW REAR EXHAUST ASSY	200.00	X
6	REMOVE AND REFIT FUEL TANK	150.00	X
7	TRANSFER PARTS, ATTACHMENT FROM OLD TAILGATE TO NEW	200.00	60
8	PANEL BEATING ON AFFECTED AREAS	1600.00	700
9	SPRAY PAINTING ON AFFECTED AREAS	1600.00	700
10	APPLY ANTI RUST ON AFFECTED AREAS	150.00	30
	Subtotal	4510.00	1730
	Grand total	17172.95	

Supp - 184.42.
 3795.92.
 250
 1730
 5960.34
 1/44 4750
 5 days.


 28/2/2020

Taufik 97495799
 WP
 25/2/20 @ 1215
 Lump sum
 Resurvey after repair
 5 days
 Taufik @ Melaka

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: