

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5813Y**AAD2002-143***Not Notified**Recovery Bk paint*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

24 FEB 2020**SHD 5813Y**

JTDKB3FU303076860

TOYOTA

PRIUS

19.2.2020

AIG

22/11/2018

	PART
1	REAR BUMPER
1	REAR BUMPER RE-INFORCEMENT
1	REAR BUMPER TOWING COVER
1	GUARD, REAR BUMPER, CENTER
1	REAR BUMPER SIDE RETAINER LH
1	REAR BUMPER SIDE RETAINER RH
1	REAR TAILGATE
1	REAR TAILGATE OUTER GARNISH
1	REAR TAILGATE WEATHERSTRIP
1	PANEL SUB-ASSY, BODY LOWER BACK
1	TAILLAMP LOWER RH
1	TAILLAMP UPPER RH
1	REAR BUMPER SIDE RH
1	REAR BUMPER SIDE LH
1	TAILLAMP LOWER LH
1	TAILLAMP UPPER LH
1	COVER, DECK TRIM, REAR
1	COVER, FLOOR UNDER, NO 1
1	COVER, FLOOR UNDER, NO 2
1	COVER, REAR FLOOR

	LIST
\$	<i>n</i> 442.60 <i>X</i>
\$	SVC 332.70 <i>X</i>
\$	<i>sn</i> 15.40 <i>X</i>
\$	<i>sn</i> 576.30 ✓
\$	<i>sn</i> 116.50
\$	<i>sn</i> 117.70
\$	<i>n</i> 1,147.80
\$	<i>sn</i> 925.60
\$	<i>sn</i> 372.30
\$	<i>sn</i> 650.30
\$	<i>sn</i> 502.00 <i>X</i>
\$	<i>sn</i> 451.80
\$	<i>sn</i> 123.70
\$	<i>sn</i> 123.70
\$	<i>sn</i> 502.00
\$	<i>sn</i> 443.30
\$	<i>sn</i> 126.70
\$	<i>sn</i> 175.10
\$	<i>sn</i> 241.90
\$	<i>sn</i> 229.90

TOTAL	\$	7,617.30
25%	\$	1,904.33
	\$	5,712.98

Special Nett

Trans-cab Auto Services Pte Ltd**AAD2002-143**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5813Y

1SET	PARKING AID	\$	52	700.00	}	X
1SET	REAR BUMPER CLIP	\$	11	66.00		
1	REAR TAILGATE TOYOTA LOGO	\$	11	47.00		
1	REAR TAILGATE WORDING 'PRIUS'	\$	11	52.90		
1	REAR TAILGATE WORDING 'HYBRID'	\$	11	53.50		
1	REAR TAILGATE STICKER 'TRANS-CAB'	\$	11	80.00		
1	REAR TAILGATE STICKER '6555-3333'	\$	11	80.00		
1	REAR BUMPER PROTECTOR	\$	11	100.00		
1	REAR WHEEL RIM	\$	52	1,879.40		
1	REAR TYRE 195/65/15	\$	11	350.00		
1	REAR WHEEL RIM COVER	\$	52	211.50		
1	REAR RH BUMPER RETAINER CLIP	\$	11	35.00		
1	REAR LH BUMPER RETAINER CLIP	\$	11	35.00		
TOTAL		\$		3,690.30		

TOTAL PARTS \$ 9,403.28**LABOUR**

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ 170.00 X

To transfer of Rear Bumper fittings, attachments and perform water seepage test.

\$ 170.00 X

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ 170.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 6,000.00 2201

To check steering geometry and computer wheel alignment

\$ 220.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 X

Trans-cab Auto Services Pte Ltd**AAD2002-143**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 5813Y

To Rust-Proofing Of The Affected Areas.	\$	170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	X
To Check Electrical Lighting Concerned.	\$	170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	100%
TOTAL	\$	14,170.00	
Over All Total	\$	23,573.28	

(PART-BY-PART) Repair Days~~20 Days~~

1 1/2 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: