



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2007631
INV Date 12/11/2020
Reference CC6/CTI20003138/Uda3q2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. SGH 9488S
Insured Veh. GBH 6495A
Claim No. SNM20D201075/C02
Policy No. DMCVSN1824711901
Accident Date 23/02/2020
Inspection Date 25/02/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI20003138/Uda3q2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 12-11-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 6495A	Veh. Inspected	SGH 9488S
Policy No.	DMCVSN1824711901	Coverage (\$)	0.00
Claim No.	SNM20D201075/C02	Excess (\$)	0.00
Assign From		Assign Date	25/02/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA ACCORD (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2006
Chassis No.	CL73201366	Colour	BLACK
Odometer	224613	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/45ZR17	WEST LAKE	6 mm
L/H Front Tyre	215/45ZR17	WEST LAKE	6 mm
R/H Rear Tyre	215/45ZR17	WEST LAKE	6 mm
L/H Rear Tyre	215/45ZR17	WEST LAKE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	23/02/2020	Inspection Date	25/02/2020
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGH 9488S

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT BUMPER	DEFORMED / TORN	1,520.00	1,050.00
1	FRONT BUMPER SIDE RETAINER N/S	CRACKED	85.50	48.50
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	420.20	-
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT BUMPER FOG LAMP COVER N/S	NOT NECESSARY	165.00	-
1	FRONT BUMPER FOG LAMP N/S	NOT NECESSARY	350.50	-
1	HEADLAMP N/S	HOLDER CRACKED	2,250.00	1,100.20
1	HEADLAMP BRACKET N/S	NOT NECESSARY	125.00	-
1	FRONT FENDER N/S	TO REPAIR SEE LABOUR	715.00	-
1	FRONT FENDER INNER SHIELD N/S	TORN	288.00	215.30
1	SET FRONT FENDER INNER SHIELD CLIPS N/S	NECESSARY	50.00	50.00
1	FRONT GRILLE	CRACKED	366.50	366.50
1	FRONT GRILLE TOP	NOT NECESSARY	389.20	-
1	FRONT GRILLE LOGO	NOT NECESSARY	45.00	-
1	FRONT SUPPORT PANEL TOP GARNISH	NOT NECESSARY	311.20	-
	LESS 20% DISCOUNT		-	-576.10
			7,131.10	2,304.40
	<u>LABOUR</u>			
	TO CHECK WIRING.		50.00	20.00
	TO SPRAY RUST PROOFING.	NOT NECESSARY	50.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER N/S.		580.00	300.00
	TO PUTTY & SPRAY PAINTING.		680.00	400.00
			-	-
			-	-
			-	-
			1,360.00	720.00
	GRAND TOTAL		8,491.10	3,024.40



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,400.00
---	--	--	----------

Report Ref No. CC6/CTI20003138/Uda3q2

A handwritten signature in black ink, appearing to read 'Chua'.

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGH 9488S

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGH 9488S

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGH 9488S

RE-INSPECTION

