Adjuster Report Page 1 of 5

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20003143/UVD3E2

Date: 17/06/2020

**REFERENCE** 

China Taiping Insurance (Singapore) Handling Insurer:

Policy No:

DMPCSN30714419022

Claimant Vehicle SFH7678K

22/02/2020

Pte. Ltd.

**Insured Vehicle** No:

SFY3644U

No: Date of Loss:

Nature of Claim: TP

Claim

SNM20D200956 No:

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SFH7678K

Make & Model: NISSAN SYLPHY, 1.6 (A) Engine No: HR16928783C

Reg. Date: 18/07/2018 (Man. Year: 2018) Chassis No: MNTBBAB17Z0032460

Colour: Silver Odometer: 5102 km

Engine Capacity: 1598 cc Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

Steering (Serviceable): Yes Footbrake (Serviceable): General Condition: Yes

Pre-accident Condition: Handbrake (Serviceable): Yes Engine Modification:

**CONDITION OF TYRES** 

195/60 R16 Front Tyre Size: 195/60 R16 Rear Tyre Size: Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm Front Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,841.44	1,668.00	173.44	9.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,060.00	1,250.00	810.00	39.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,901.44	2,918.00	983.44	25.21
+ GST 7.00/7.00% (S\$)	273.10	204.26	68.84	25.21
Nett Amount (S\$)	4,174.54	3,122.26	1,052.28	25.21

INSPECTION

Date of Assignment: 27/02/2020

Date Inspected: 26/02/2020 Inspected At: Autolution Industrial Pte Ltd (HQ)

19 UBI ROAD 4

Singapore 408623

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: VERON CHEN Adjuster Report Page 2 of 5

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 5

THE VEHICLE HAS NOT SEND IN FOR REPAIRS.

(REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$173.44 NETT) Adjuster Report Page 4 of 5

## **REPAIR DETAILS**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Jun 2020)

Parts: 143 NISSAN SYLPHY 1.6 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SFH7678K)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

## **Recommended Parts**

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*SUNDRIES	* Check	50.00 FS	*- FS
2	1	*R/R DOOR TAPE	Necessary	13.00 FN	*13.00 FN
3	1	*R/R DOOR TAPE	Necessary	26.00 FN	*26.00 FN
4	1	*R/R DOOR TAPE	Necessary	26.00 FN	*26.00 FN
5	1	*REAR DOOR RH	Badly Dented	1,015.60 FN	*1,015.60 FN
6	1	*R/F DOOR OUTER HANDLE INNER BRACKET	* Check	55.90 FN	*- FN
7	1	*R/F DOOR OUTER HANDLE	* Check	98.40 FN	*- FN
8	1	*R/F DOOR TAPE	Necessary	19.50 FN	*19.50 FN
9	1	*R/F DOOR TAPE	Necessary	28.40 FN	*28.40 FN
10	1	*FRONT DOOR RH	Badly Dented / Cracked	956.50 FN	*956.50 FN
F=Fra	anchise	part. S=SpcNett. N=NettItemDisc.			
			Sub Total (S\$)	2,289.30	2,085.00
	- Nett Item Discount on N Items 20.00/20.00% (S\$)			447.86	417.00
			Total Parts (S\$)	1,841.44	1,668.00

Report was unsubmitted during this print-out.

Adjuster Report Page 5 of 5

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

#### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOR CHARGES TO REPAIR RH CENTRE PILLAR AND RENEW BOTH RH DOORS	New	900.00	390.00
2	CHARGES TO SPRAY PAINTING SAME	New	800.00	500.00
3	REMOVE AND INSTALL BOTH RH DOOR MECHANISM @ \$80.00 PER DOOR	New	160.00	160.00
4	APPLY SEALANT TO BOTH RH DOORS @ \$100.00 PER DOOR	New	200.00	200.00
	Gross Labour Cost (S\$)		2,060.00	1,250.00
	Report was unsubmitted during t	his print-out.		

< END OF ESTIMATES >