

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 30339

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0197/2020/NS
Date : 21-Feb-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Loo Ting Loy
Address : Blk 572 Ang Mo Kio Ave 3
#06-3363
Singapore 560572
Telephone : HP +65 90481280
Type of Claim : Own Damage Claims
Policy No. : 2100357443-06
Vehicle No : **SKL 5499 T**
Model Code : Audi A3 SPORTSBACK 1.4 TF
Model / Year : Nov-13
Engine No : CXS 011591
Chassis No : WAUZZZ8V4EA013172
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 19-Feb-20
Place of Accident : Straits View

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKL 5499 T

| S/N | Nature of Jobs | Estimated Charges | Surveyor's Recommendations |
|-----------------------------|--|-------------------------------|----------------------------|
| 1 | To remove and transfer rear parking aid. Check function and renew according to damage. | S/N \$ 280.00 ✓ | |
| 2 | To dismantle and renew rear bumper. To repair rhs rear fender. Re-organise crash management components. Reinstall all parts removed. | \$ 1,400.00 500 ✓ | |
| 3 | To respray rear bumper and rhs rear fender. | \$ 2,000.00 1100 ✓ | |
| 4 | To carry out diagnostic check. | S/N \$ 192.00 ✓ | |
| TOTAL LABOUR CHARGES | | : <u>\$ 3,872.00</u> | |

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Reqn No. SKL 5499 T

| S/N | Parts Description | Damage Parts & Prices | | Remarks |
|----------------------------------|--|-----------------------|--------------------|---------|
| | | S/NETT | | |
| 1 | REAR BUMPER <i>reformed</i> | \$ | 1,761.00 | ✓ |
| 2 | REAR BUMPER FIXING PARTS <i>all n</i> | \$ | 182.00 | + |
| 3 | REAR BUMPER LOCKING MECHANISM - LH / RH <i>new</i> | \$ | 26.00 | + |
| 4 | REAR BUMPER SPOILER <i>all n</i> | \$ | 223.00 | + |
| 5 | REAR BUMPER GUIDE SECTION - RH <i>all n</i> | \$ | 63.00 | + |
| 6 | LED TAIL LIGHT - RH <i>all n</i> | \$ | 826.00 | + |
| 7 | SUNDRIES <i>?</i> | \$ | 200.00 | ? |
| TOTAL SPARE PARTS CHARGES | | : | \$ 3,281.00 | |
| TOTAL LABOUR CHARGES | | : | \$ 3,872.00 | |
| GRAND TOTAL | | : | \$ 7,153.00 | |

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adnan
Surveyed Date : 25/02/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant