

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE FOR SJK522J

No.	Qty	List Items		
1	1	Front bumper	\$	1,078.20 <i>de 65+</i>
2	1	Front bumper RH fog lamp cover	\$	58.00 <i>de</i>
3	1	Front bumper RH side retainer	\$	49.80 <i>de</i>
4	1	Front bumper inner foam	\$	127.20 <i>? cre ✓</i>
5	1	Front bumper inner reinforcement	\$	355.60 <i>? de ✓</i>
6	1 set	Front bumper clips	\$	40.00 <i>30 na</i>
7	1	RH headlamp	\$	650.30 <i>auto 523.30</i>
8	1	Front grille	\$	335.60 <i>ena</i>
9	1	Front grille centre logo	\$	68.70 <i>re</i>
10	1	Front bonnet	\$	627.10 <i>Rx</i>
11	1	Front support panel	\$	855.90 <i>Rx</i>
12	1	Front RH fender	\$	706.80 <i>bt 606.10</i>
13	1 set	Front fender under shield clips	\$	40.00 <i>2 na</i>
14	1	Washer tank	\$	112.60 <i>de</i>
15	1	Washer tank motor	\$	92.30 <i>? dis ✓</i>
16	1	Front RH shock absorber	\$	433.40 <i>? 385 bt ✓</i>
17	1	Front RH lower arm	\$	454.60 <i>? 365.20 bt ✓</i>
18	1	Front RH knuckle arm	\$	168.50 <i>? bt ✓</i>
19	1	Front RH wheel hub & bearing	\$	196.50 <i>? bt ✓</i>
20	1	Front RH drive shaft	\$	1,340.60 <i>? bt 1220.10</i>
21	1	Front stabilizer bar	\$	156.20 <i>X</i>
22	1	Front stabilizer bar RH link rod	\$	112.30 <i>X</i>
23	1	Steering rack & pinion	\$	2,453.60 <i>X</i>
			\$	10,513.80 <i>5371.50</i>
Less 25%			\$	2,628.45
Total :			\$	7,885.35 <i>4028.62</i>

Special Nett Items

24	1	Front RH sport rim	\$	500.00 <i>300 dd ✓</i>
25	1	Front RH tyre	\$	220.00 <i>176 cut 80% ✓</i>
Total :			\$	720.00 <i>476</i>

Labour

1	Labour Charges for remove/refit, cutting/welding and replacement of damages.		\$	700.00 <i>600</i>
2	To putty and spray Spray Paintings charges.		\$	1,000.00 <i>700</i>
3	To check wirings and lighhtings.		\$	40.00 <i>30</i>
4	To remove, refit air con condenser, radiator etc., including refill air con gas.		\$	140.00 <i>X</i>
5	To remove, refit front RH under carriages.		\$	280.00 <i>150 ✓ plus</i>
6	To conduct computerise wheel alignment test.		\$	80.00 <i>nei ✓</i>

To supply and apply anti rust treatment

	\$	90.00	30
Total :	\$	2,330.00	1590

Total Parts and Labour : \$ 10,935.35

4028.62

476

1590

6094.62

415\$4900

7 ~~6~~ days

[Signature]
21/2/2020

Taufik

97495749

~~97495749~~

67418434

WP' 25/2/20 24pm

Lumpsum

Resurvey after repair

taufik@kkauto.com

sure@kkauto.com

06 days - 7 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: