

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-AO

To: **AIG Asia Pacific Insurance Pte Ltd**

Accident Date : 06.02.2020

L&K Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

24.02.2020

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost Of Repair To "Toyota Wish" Reg. No. SJW1965U Claiming Against Your Insured Reg. No. SGL2109L			
1pc	Rear Bumper / <i>cc</i>		520.00 <i>451.9</i>
1pc	Rear Bumper Clips / <i>mc</i>	3.80	38.00 /
1pc	Rear Bumper Top Retainer <i>X SNN</i>		83.00 X
2pcs	Rear Bumper Brackets <i>X</i>	91.90	183.80 X
1pc	Tailgate / <i>Buc</i>		1,495.00 <i>1217.85</i>
1pc	Tailgate Glass Moulding Top /		52.00 /
2pcs	Tailgate Glass Moulding Sides / <i>mc</i>	49.00	98.00 /
1pc	Tailgate Glass Moulding Lower /		55.00 /
1pc	Tailgate Emblem /		69.20 /
5pcs	Tailgate Outer Chrome Clips <i>X NN</i>	3.50	17.50 X
1pc	Tailgate Badge Valve Matic /		37.20 /
15pcs	Tailgate Inner Trim Board Clips / <i>mc</i>	3.90	58.50 /
	Less 25%		2,707.20 <i>2077.65</i>
			676.80
			2,030.40
	Rear Bumper Reverse Sensor / <i>DM</i>		200 280.00 SN
	Tailgate Glass Sealant /		50 50.00 SN
	Tailgate Glass Sealer / <i>mc</i>		50 30.00 SN
	Tailgate Glass Fastener /		50 50.00 SN
	To Conduct Electrical Check, Replace Reverse Sensor, Module, Rewiring etc.	<i>250</i>	<i>MNX</i> 30.00
	To Dismantle / Refit Tailgate Fittings / Ancillary Accessories		<i>60</i> 150.00
	To Dismantle / Refit Tailgate Glass		<i>100</i> 160.00
	To Apply Rust Proofing / Reseal Tuff Coating Treatment to Respray / Replaced / Repair Panel		<i>NNX</i> 60.00
	Labour Charge - Panel Beating, Repairing Of End Panel, Rear Floor Panel and Parts Replacement		<i>400</i> 700.00
	To Respray Affected Areas	<i>960</i>	<i>400</i> 750.00
	<i>4 Days.</i> <i>Unprim repair</i> <i>After repair photos</i>		
	<i>Quo Qiap</i> <i>8288 028 2</i> <i>25/2/2020</i>		
		Total :	4,290.40
		<i>2768.23</i>	
		<i>20% = 2000</i>	