

Woon Meng Motor Pte Ltd

Office : 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Workshop: 50 Bukit Batok St 23, #01-06 Midview Building, Singapore 659578

Tel: 6316 1131 HP: 9730 2017 Fax: 6316 7050

42, Sungei Kadut Ave, Singapore 729666 Tel : 63268523

(Email Address : woonmeng @singnet.com.sg)

Co Reg No. 200603678M

GST Reg No. 20-0603678M

Estimate

TP CLAIM

To : India International Insurance Pte Ltd
Motor Claims Dept

Date : 24 Feb 2020

Dear Sirs :

Fax : 6

RE : ESTIMATE COST FOR TOYOTA CAMRY 2.5 A - SLK8823P ACCIDENT INVOLVING SLK8823P & SH8774E ON 21/02/2020

<u>ITEMS</u>	<u>DESCRIPTION</u>	<u>QTY</u>	<u>PRICE</u>
1	Rear bumper <i>de</i>	1pc	\$ 659.30
2	Rear bumper retainer @\$104.8ea <i>na</i>	2pcs	\$ 209.60
3	Rear bumper reflector @\$88.6ea <i>cr</i>	<i>1pc</i> 2pcs	\$ 177.20
4	Rear sensor @\$417.2ea <i>na</i>	4pcs	\$ 1,668.80
5	Clips @\$1.5ea <i>na</i>	10pcs	\$ 15.00
6	Rear bumper reinforcement <i>bt</i>	1pc	\$ 397.60
7	Rear bumper lower garnish <i>scr</i>	1pc	\$ 183.70
8	Rear end panel <i>bt</i>	1pc	\$ 657.60
9	Rear end panel top garnish <i>de</i>	1pc	\$ 304.80
10	Rear rubber <i>na</i>	1pc	\$ 302.00
11	Rear spare tyre panel <i>blue</i>	1pc	\$ 848.50
12	Rear spare tyre panel top trim <i>X</i>	1pc	\$ 382.10
13	Rear lamp @\$424.5ea <i>X</i>	4pc 2pcs	\$ 849.00
14	Rear lamp panel @\$121.8ea <i>? LH?/RH-X</i>	<i>1pc</i> 2pcs	\$ 243.60
15	Rear bootlid <i>bt</i>	1pc	\$ 1,121.60
16	Rear bootlid inner trim <i>X</i>	1pc	\$ 383.20
17	Rear bootlid hinge @\$131.8ea <i>X</i>	2pcs	\$ 263.60
18	Rear bootlid lock <i>bt</i>	1pc	\$ 391.80
19	Camry <i>na</i>	1pc	\$ 48.60
20	2.5 <i>na</i>	1pc	\$ 38.60
21	Emblem <i>na X</i>	1pc	\$ 66.80
Sum Carried Forward			\$ 9,213.00

Sum Carried Forward			\$	9,213.00
22	Rear bootlid chorme @\$138.9ea X	3pcs	\$	416.70
23	Rear mudguard @\$1072.5ea h4-bt	1pc 2pcs	\$	2,145.00
24	Rear mudguard inner garnish @\$425ea de	2pcs	\$	850.00
25	Rear mudguard air grille n/s de	1pc	\$	135.20
			\$	12,759.90
Less 25%			\$	(3,189.97)
			\$	9,569.93
26	Rear Windscreen sealant	2pcs	\$	40.00

Labour Charge & Misc

To remove, repair, replace & install damaged parts.	}	\$	1,600.00 1300
To R & R sensor wiring	}	\$	80.00 60
To R & R light wiring		\$	60.00 30
To R & R camera.		\$	150.00 60
To R & R rear windscreen glass		\$	150.00 120
To R & R rear passenger seat.		\$	180.00 80
To putty & spray painting.		\$	1,400.00 1200
Towing fee + ERP (2times)		\$	80.00 70
Total		\$	13,309.93

All prices quoted are subjected to 7% GST.

This is a computer generated document. No signature is required.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: