

27/03/2021

ASS. REC. BY:

REF:

C3/A1920003157/Nqd3

Special Instruction:

Survey:

Ndz

ASSIGNMENT (Office)

merimen

From (Person):

Chin Lee Ying

of

A19

Date/Time: 25/2/2020 @ 10:29am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FBJ 9402M

Insured:

at Workshop m/s

Bike production

Tel: 1900023135

of

610 Serangoon Road

Policy No:

1900023135

Claim No:

757336085955

Sum Insured:

Excess:

TBA \$0

Make of Veh:

(Client's Record)

D.O.A. 21/02/2020

CA / (REV) /

REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

10:37am @ 25/2/2020

Person Contacted:

Mr. Kwan

Vehicle IN/OUT

Date/Time

Action/Instruction

Johny! ✓

FBJ9402M-C3/A1920003092/d93

D.O.A. 21/2/2020

22/2/20 @ 11:06am revert to Victor via Merimen. (pending COR from repairer).

09/3/20 @ 3:12pm 2nd revert to Victor via Merimen. (repairer able to repair at \$566500)

23/2/20 @ 11:38am 3rd revert to Victor via Merimen. (Supplementary \$684)

LS \$6500, 3 DAYS (Red \$6207, 49%)

ASS. REC. BY:

REF: AIG

N42

ASSIGNMENT

From: _____ Date: 26/2/2020

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBJ 9402M

at Workshop m/s Bike Production

of GIO Seagrass Road

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: TBA

(Client's Record)

Make of Veh: Afternoon

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 10K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: FBJ 9402M Yr Regn: 9 JAN / 2015

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA CB400X C.C. 399

Colour: RED A/C: Insured / Std / NI / NA

Sp. Reading: 80,976 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: NC471005269

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 120/70 R17

R: 160/60 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. - mm L/Bal. - mm

D.O.A. 21/2/2020 D.O.I. 26/2/2020

Survey held at BIKE PRODUCTION

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

AIG L/S

Date / Time	Action / Instruction
	SOE Rebate \$2,200.00
	Repair Limit \$7K
	Repair Estimate (excl. check items & supplementary) \$6K

Date/Time, File Pass to?

☐

Prel. Report

12/04 Typist

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + R\$ SI

Photos

Others

TOTAL

Report Format: MER-OD

Lump Sum / LBL (\$) 6500

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Inve (\$)

☐

Weekend (\$)

INSURANCE AND GIA, Re: RE: NEW OD CLAIM - FBJ9402M

From: Chin, Lee-Ying
To: 'assignments', Nivitha (LKK Auto)
Cc: Lim, Kok-Chong
Sent: 2/25/2020 10:29:00 AM

Attachments:  IMG_20200224_043226.jpg  FBJ9402M QWS.pdf  WhatsApp Image 2020-02-22 at 11.24.22 (1).jpeg  WhatsApp Image 2020-02-22 at 11.24.22.jpeg

Hi LKK,

Kindly assist to survey.

Thanks.

Best Regards

Lee Ying, Chin

AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.

78 Shenton Way #08-16 Singapore 079120

Tel +(65) 6419 1947

Lee-Ying.Chin@aig.com | www.aig.sg

From: Sbk E [mailto:sbk5643e@yahoo.com]

Sent: Tuesday, February 25, 2020 10:00 AM

To: AIG SGP, Claims-Survey

Subject: [EXTERNAL] RE: INSURANCE AND GIA, Re: RE: NEW OD CLAIM - FBJ9402M

This message is from an external sender; be cautious with links and attachments.

Regards,

Kwan S. H.

Director

Bike Production Pte Ltd

On Monday, February 24, 2020, 08:44:34 AM GMT+8, AIG SGP, Claims-Survey <aigsgp_claimssurvey@aig.com> wrote:

Hi Mr. Kwan,

Please attach GIA report.

Thanks.

AIG Claims Survey

-----Original Message-----

From: Sbk E [mailto:sbk5643e@yahoo.com]

Sent: Saturday, February 22, 2020 11:28 AM

To: AIG SGP, Claims-Survey

Subject: [EXTERNAL] RE: NEW OD CLAIM - FBJ9402M

This message is from an external sender; be cautious with links and attachments.

Dear Sir,

Please arrange PRI for own damage claim. Thanks.

Regards,

Kwan S. H.

Director

Bike Production Pte Ltd

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chan, Yoke Shi

Date: 23 Mar 2020

Preliminary Advice

Vehicle No	: FBJ9402M	Accident Date	: 21/02/2020
Make	: HONDA CB400	Policy No.	: 1900023135
Assignment Date	: 25/02/2020	Excess	: S\$500.00
Date of Inspection	: 26/02/2020	Est. Duration of Repair	: 3.00
Inspection At	: BIKE PRODUCTION PTE LTD (HQ) 610 SERANGOON ROAD SINGAPORE 218216		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion, n/s & o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,704.00	(ESTIMATE \$12,023.00 + SUPPLEMENTARY \$684.00)
Revised Amount	:S\$	8,163.50	
Check Items (Estimated)	:S\$	1,066.50	
Total	:S\$	9,230.00	

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	10,000.00
COE / PARF Rebate	:S\$	2,220.00
Salvage Value	:S\$	
Margin for Repair	:S\$	7,780.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : REPAIRER ABLE TO REPAIR THE MOTORBIKE AT REPAIR COST \$6,500.00 ON LUMP SUM BASIS.

Shiau Chan (LKKAUTO)

From: Ng, Thaddaeus-HC <Thaddaeus-HC.Ng@aig.com>
Sent: Friday, 13 March 2020 6:59 PM
To: Shiau Chan (LKKAUTO); Yvonne Wong (LKK Auto)
Cc: SUR; Fong, Andy-SY
Subject: RE: PENDING MANDATE APPROVAL - FBJ 9402M, FBL 532U & FBJ 8060Y Damaged TBA

Hi,

Mandate send and to update below mentioned.

FBJ 9402M – No photo show parts damaged as below or require to advise

- Front Wheel Axle (Damaged Photo or Require)
- Front Right Fork Assy (Damaged Photo or Require)
- Front Sport Rim (Damaged Photo or Require)
- Rear Right Side Case (Sales Agreement TBC)

FBJ 8060Y – Damaged parts vs after repair & Decals

- Front Sport Rim (New & Damaged Photo TBC)
- Decals Front Fairing & Rear Box LH self-fix not for claim

FBL 532U – Carbon Sticker

- Carbon Sticker self-fix for claim

To arrange resurvey for check, supplementary & after repair. Net loss repair for all bike to be alert.

Thanks

Regards,
Thaddaeus Ng

AIG
Motor Claims Surveyor
Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Hp +(65) 8876 5433
Thaddaeus-HC.Ng@AIG.com | www.AIG.com.sg

From: Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>
Sent: Friday, March 13, 2020 5:47 PM
To: Ng, Thaddaeus-HC <Thaddaeus-HC.Ng@aig.com>
Cc: SUR <sur@lkkauto.com>
Subject: [EXTERNAL] PENDING MANDATE APPROVAL

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chan, Yoke Shi

Date: 09 Mar 2020

Preliminary Advice

Vehicle No	: FBJ9402M	Accident Date	: 21/02/2020
Make	: HONDA CB400	Policy No.	: 1900023135
Assignment Date	: 25/02/2020	Excess	: S\$500.00
Date of Inspection	: 26/02/2020	Est. Duration of Repair	: 3.00
Inspection At	: BIKE PRODUCTION PTE LTD (HQ) 610 SERANGOON ROAD SINGAPORE 218216		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion, n/s & o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,023.00
Revised Amount	:S\$	7,479.50
Check Items (Estimated)	:S\$	1,066.50
Total	:S\$	8,546.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	10,000.00
COE / PARF Rebate	:S\$	2,220.00
Salvage Value	:S\$	
Margin for Repair	:S\$	7,780.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : REPAIRER ABLE TO REPAIR THE MOTORBIKE AT REPAIR COST \$6,500.00 ON LUMP SUM BASIS.

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #08-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chan, Yoke Shi

Date: 27 Feb 2020

Preliminary Advice

Vehicle No	: FBJ9402M	Accident Date	: 21/02/2020
Make	: HONDA CB400	Policy No.	: 1900023135
Assignment Date	: 25/02/2020	Excess	: S\$500.00
Date of Inspection	: 26/02/2020	Est. Duration of Repair	: 3.00
Inspection At	: BIKE PRODUCTION PTE LTD (HQ) 610 SERANGOON ROAD SINGAPORE 218216		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion, n/s & o/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,023.00
Revised Amount	:S\$	7,479.50
Check Items (Estimated)	:S\$	1,066.50
Total	:S\$	8,546.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	10,000.00
COE / PARF Rebate	:S\$	2,220.00
Salvage Value	:S\$	
Margin for Repair	:S\$	7,780.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : PENDING REPAIR COST FROM REPAIRER.

BIKE PRODUCTION PTE. LTD.

610, Serangoon Road Singapore 218216

Tel: 6392 2555 Fax: 6297 5400

TAX INVOICE

Co. Registration No. 200007407G

GST Reg. No: 200007407G

GST Inclusive

No: 6259

Name: AIG ASIA PACIFIC INSURANCE LTD Date: 1/3/20

Address: 78 SERANGOON WAY #02-16 S(079120)

I/C No: _____ Occupation: _____ DOB: _____

Tel: _____ Driving Licence: _____

Particulars		Amount
Reg. No: <u>FB39402M</u>	Selling Price	<u>6420</u>
Make & Model: <u>HONDA 400X MANUAL</u>	+ Insurance	<u>0</u>
Engine No: <u>NC47E1005292</u>	+ Retention	<u>0</u>
Chassis No: <u>NC471005269</u>	TOTAL PRICE	<u>6420</u>
Insurance Type: <input type="checkbox"/> Comprehensive <input type="checkbox"/> Third Party Fire Theft <input type="checkbox"/> Third Party Only		
Colour: <u>Lumpsum</u>	Downpayment	<u>6500</u>
<u>REPAIR</u>	LESS EXCESS	<u>500</u>
Loan Amount _____	Interest rates _____ p.a.	<u>6000</u>
Terms: (_____	Monthly Instalments of \$ <u>71.65</u>	<u>420</u>
N/R: _____	TEL: _____	<u>6420</u>
GTR: _____	TEL: _____	
COE NO: _____	TR	

Note:

- Above prices do not include ERP IU.
- Deposit is not refundable.
- Balance amount must be cleared within 3 days of the invoice date. Deposit will be forfeited if the buyer fails to clear the full balance amount within the stated period.
- Title to the above-mentioned goods will not be handed to the buyer until the full amount and/or changes are paid
- All cheque payments are to be crossed and made payable to **Bike Production Pte Ltd**. If cheque dishonoured, the buyer has to pay **Bike Production Pte Ltd** by cash and a service charge of S\$30.00 plus prevailing GST.
- Bike Production Pte Ltd** will have fullrights to repossess the above-mentioned goods without notice in case of default in payment.
- The buyer shall inspect the above-mentioned goods immediately on notification that goods are due and ready for collection. The buyer shall give notice in writing to the seller of any matter or thing by reason whereof he alleges that the goods are not in acceptable conditions. If the buyer fails to give notice, the above-mentioned goods shall be deemed to be in accordance with the contract and the buyer shall be bound to accept and pay for the same accordingly.
- For hire purchase, no alteration of the hire-purchase agreement and its terms, including down payment and installment period, is allowed once the hire-purchase agreement is made. In the event of cancellation, the buyer shall compensate **Bike Production Pte Ltd** 20% of the total price plus prevailing GST and the deposit shall be forfeited.
- For hire purchase, a Singaporean guarantor between 21 year & 60 year of age and with a different residential address from the buyer is required before the collection of the above-mentioned goods. The guarantor shall not be an undischarged bankrupt and is subject to financial approval.
- I confirm that the information I have provided is my personal data and, where it is not my personal data, that I have the consent of the owner of such personal data to provide such information. By providing this information I understand and give my consent for **Bike Production Pte Ltd** to collect, use, store, transfer and / or disclose personal data about me or us and those whose personal data I or we have provided from sources other than myself or us for the purposes.

For Bike Production Pte Ltd

I accept the above terms and conditions

Jamaludin Bin Mohamed
Blk 682C Woodlands Drive 73
#11-247
Singapore 733682

Date: 29 Feb 2020

To: Mr Kwan Say Hwee
Bike Production Pte Ltd
610, Serangoon Road
Singapore 218216

Dear Sir,

**RE: ACKNOWLEDGEMENT OF THE ACCIDENT REPAIR AND COLLECTION
OF HONDA CB400X MANUAL VEHICLE NO.: FBJ9402M**

I, Jamaludin Bin Mohamed, NRIC No.: 020H, have inspected the repair done by Bike Production Pte Ltd and the repair is in accordance to the repair quotation and/or surveyor report.

I have collected the above-mentioned vehicle on 29/2/2020 at 6.30pm.

Thank you very much for your attention.

Yours faithfully,



Jamaludin Bin Mohamed

BIKE PRODUCTION PTE LTD
 610, Serangoon Road S(218216)
 Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 21 Feb 2020

ASSESSMENT FOR REPAIR: HONDA CB400X MANUAL - FBJ9402M

Chassis No.: NC471005269

Engine No.: NC47E1005292


<u>Qty</u>	<u>Description</u>	<u>Estimate</u>
1 pc	Front wheel axle	\$95.00 / SCR
2 pcs	Steering stem bearing @ \$45.00	\$90.00 X SVL
1 pc	Front brake disk	\$305.00 X SVL ?
1 pc	Front brake caliper	\$380.00 X SVL
1 pc	Front right fork assembly	\$1,105.00 / SCR
1 pc	Steering head crown	\$430.00 X SVL
1 pc	Steering stem underbracket	\$480.00 X SVL
1 pc	Windshield	\$205.00 / CLK
1 pc	Headlamp assembly	\$480.00 / CLK
1 pc	Headlamp bracket	\$335.00 ?
1 pc	Outer meter cover	\$175.00 ?
1 pc	Inner meter cover	\$175.00 ?
1 pc	Upper crash bar right	\$180.00 / SVL
1 pc	Upper crash bar left	\$180.00 / SVL
1 pc	Right balancer	\$95.00 / SCR
1 pc	Left view mirror	\$140.00 / SCR
1 pc	Right view mirror	\$140.00 / SCR
1 pc	handle bar	\$195.00 X SVL ?
1 pc	Brake lever	\$75.00 / SCR
1 pc	Right front signal	\$140.00 / SCR
1 pc	Left front signal	\$140.00 / BR
1 pc	Right body fairing	\$330.00 / SVL
1 pc	Left body fairing	\$330.00 / SVL
2 pcs	Honda wing decal @ \$45.00	\$90.00 / NGL
2 pcs	Mark X decal @ \$65.00	\$130.00 / NGL
1 pc	Engine cover assy right	\$395.00 / SVL
1 pc	Engine cover gasket	\$65.00 / NGL
1 pc	Lower aluminium plate	\$145.00 / SCR
1 pc	Brake pedal	\$105.00 / BR
1 pc	Front right footrest holder	\$195.00 / SCR
1 pc	Front right footrest	\$95.00 / SCR
1 pc	Exhaust assembly	\$1,800.00 / SCR
		6,555
		\$9,220.00
	Less discount 10%	\$922.00
		5,199.50
		\$8,298.00
	<u>Special nett items</u>	
3 pcs	Engine oil @ \$30.00	\$90.00 / NGL
1 pc	Front sport rim	\$200.00 X SVL
1 pc	Front number plate	\$20.00 / NGL
1 pc	Rear top case	\$450.00 / SVL
1 pc	Rear box bracket	\$220.00 X SVL



1 pc	Rear right side case	\$175.00	/scr
1)	Towing charges	\$90.00	X
2)	Replace, realign and adjust above damaged parts	\$800.00	200 400
3)	Remove, balancing and refit front wheel rim	\$150.00	XNN
4)	To remove/refit, replace (if damage) check and straighten front fork tubes	SD \$180.00	
5)	To knock, straighten chassis & body balancing	\$450.00	100 NN
6)	Spray painting	\$400.00	200
	Total Estimate	\$12,023.00	

Note: The above estimate is subjected to the prevailing GST of 7%

NAR LKK
26/2/2020 1430
LIS
3 DAYS
CHECK ITEM PHOTO
AFTER REPAIR PHOTO



For Bike Production Pte Ltd

7,479.50

5,983.60

6,000.00 LIS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Illegal modification(s) is allowed
- Elementary item(s) must be resurveyed and
- Subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

BIKE PRODUCTION PTE LTD

610, Serangoon Road S(218216)
Tel: 63922555, 62995177 Fax: 62975400
ROC/ GST Reg No.: 200007407G

Date: 21 Feb 2020

ASSESSMENT FOR REPAIR: HONDA CB400X MANUAL - FBJ9402M

Chassis No.: NC471005269
Engine No.: NC47E1005292

Qty	Description	Estimate
1 pc	Front wheel axle	\$95.00 / SC
2 pcs	• Steering stem bearing @ \$45.00	\$90.00 X SC / NPL
1 pc	• Front brake disk	\$305.00 X SC / NPL
1 pc	Front brake caliper	\$380.00 X SC / NPL
1 pc	Front right fork assembly	\$1,105.00 / SC
1 pc	Steering head crown	\$430.00 X SC / NPL
1 pc	• Steering stem underbracket	\$480.00 X SC / NPL
1 pc	Windshield	\$205.00 / CRK
1 pc	Headlamp assembly	\$480.00 / CRK
1 pc	• Headlamp bracket	\$335.00 ? / BT
1 pc	• Outer meter cover	\$175.00 ? / CRK
1 pc	• Inner meter cover	\$175.00 ? / CRK
1 pc	Upper crash bar right	\$180.00 / SC
1 pc	Upper crash bar left	\$180.00 / SC
1 pc	Right balancer	\$95.00 / SC
1 pc	Left view mirror	\$140.00 / SC
1 pc	Right view mirror	\$140.00 / SC
1 pc	• handle bar	\$195.00 X SC ? / BT
1 pc	Brake lever	\$75.00 / SC
1 pc	Right front signal	\$140.00 X SC / SC
1 pc	Left front signal	\$140.00 / BT
1 pc	Right body fairing	\$330.00 / SC
1 pc	Left body fairing	\$330.00 / SC
2 pcs	Honda wing decal @ \$45.00	40 \$90.00 / NPL
2 pcs	Mark X decal @ \$65.00	80 \$130.00 / NPL
1 pc	Engine cover assy right	\$395.00 / SC
1 pc	Engine cover gasket	\$65.00 / NPL
1 pc	Lower aluminium plate	\$145.00 / SC
1 pc	Brake pedal	\$105.00 / BT
1 pc	Front right footrest holder	\$195.00 / SC
1 pc	Front right footrest	\$95.00 / SC
1 pc	Exhaust assembly	\$1,800.00 / SC
		\$9,220.00
	Less discount 10%	\$922.00
		\$8,298.00
	Special nett items	
3 pcs	Engine oil @ \$30.00	\$90.00 / NPL
1 pc	Front sport rim	R \$200 \$700.00 X SC / NPL
1 pc	Front number plate	\$15 \$20.00 / NPL
1 pc	Rear top case	\$450.00 / SC
1 pc	Rear box bracket	\$220.00 X SC / NPL

1 pc

Rear right side case

1)

Towing charges

2)

Replace, realign and adjust above
damaged parts

3)

Remove, balancing and refit front
wheel rim

4)

To remove/refit, replace (if damage) check and
straighten front fork tubes

5)

To knock, straighten chassis & body
balancing

6)

Spray painting

Total Estimate

\$175.00 / scr

~~\$90.00~~ X

\$800.00 800 - 450

~~\$150.00~~ X NN

50 \$180.00

\$450.00 450 NN

\$400.00 200

\$12,023.00

Note: The above estimate is subjected to the prevailing GST of 7%

NAR LKK

26/2/2020 1430

U/S

3 DAYS

CHECK ITEM PHOTO)

AFTER REPAIR PHOTO)



For Bike Production Pte Ltd