

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 719U

21 FEB 2020

AAD2002-147

Not Authored

Resurvey B4 paint

P/P = \$4,318.30

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :
Date of Registration:

SHD 719U
VF1ABL15AUC283213
RENAULT
LATITUDE
20.2.2020
CHINA TAIPING
29/12/2017

PART		LIST	
1 FENDER PANEL REAR LH	\$	<i>B</i> 1,933.20	✓
1 FENDER PANEL INNER TRIM REAR LH	\$	<i>N</i> 671.45	X
1 WHEELARCH REAR LH	\$	<i>S</i> 181.60	X
1 BUMPER COVER REAR	\$	<i>B</i> 561.70	—
1 BUMPER LOWER REAR	\$	<i>S</i> 411.90	X
1 BUMPER BRACKET CTR REAR	\$	<i>S</i> 98.10	X
1 BUMPER BRACKET SIDE LH REAR	\$	<i>O</i> 82.10	✓
1 BUMPER RETAINER LH REAR	\$	<i>S</i> 54.20	X
1 BUMPER REFLECTOR LH	\$	<i>S</i> 16.60	} X
1 BUMPER BEAM REAR	\$	<i>N</i> 547.80	
1 BUMPER BEAM BRACKET LH REAR	\$	<i>N</i> 114.50	
1 TAILLAMP LH	\$	<i>S</i> 401.40	
1 TAILLAMP PANEL LH	\$	<i>N</i> 401.40	
1 AIR VENT	\$	<i>S</i> 59.40	
1 BOOT REFLECTOR LAMP LH	\$	<i>S</i> 277.70	
1 WHEEL HUB NUT	\$	<i>S</i> 41.80	
1 WHEEL HUB CAP	\$	<i>S</i> 30.50	
1 KNUCKLE HUB+ BEARING LH	\$	272.30	
1 REAR AXLE	\$	<i>S</i> 3,469.00	X
1 AXLE ARM LH	\$	<i>S</i> 69.50	X
1 REAR AXLE SPACER	\$	<i>S</i> 49.00	X
1 REAR AXLE ARM ROD	\$	<i>S</i> 69.50	X
1 LOWER ARM REAR LH	\$	543.50	X SVC
1 AXLE SPRING ARM LH	\$	<i>S</i> 220.60	X
1 ABSORBER REAR	\$	<i>S</i> 217.30	X
1 ABSORBER DUST COVER REAR	\$	<i>N</i> 47.10	X

Trans-cab Auto Services Pte Ltd

AAD2002-147

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 719U

1	ABSORBER MOUNTING REAR	\$	SL	49.40	}	
1	STABILIZER BAR REAR	\$	SL	427.90		
1	STABILIZER LINK REAR	\$	SL	55.20		
1	BRAKE CALIPER REAR LH	\$	SL	659.10		
1	BRAKE HOSE REAR LH	\$	SL	79.50		
1	SUBFRAME ARM REAR	\$	SL	198.33		
1	RODE- LONG REAR	\$	SL	120.16	}	
1	KNUCKLE ARM REAR LH L70Y	\$		472.10		X SVC
1	BRAKE DISC REAR LH L70Y	\$		266.50		X SVC
1	ABS SENSOR REAR LH L70Y	\$		190.50	X SVC	
1	DOOR PANEL REAR LH	\$	n	758.70	X	
1	ROCKER PANEL OUTER LH	\$	n	1,184.99	X	
1	FENDER INNER BOARD LH	\$	SL	561.40	X	
1	FENDER PANEL INNER REAR LH	\$	n	1,241.60	X	
TOTAL		\$		17,108.53		
10%		\$		1,710.85		
		\$		15,397.68		

Special Nett

1	FENDER INNER TRIM CLIP LH	\$	nn	28.00	X
1	TAILLAMP CLIP LH	\$	nn	5.00	X
1SET	FENDER WHEELARCH REAR LH CLIP	\$	nn	35.00	X
2	REAR WINDSCREEN SEALANT	\$	nn	120.00	40sn
1	WINDSCREEN MOULDING	\$	nn	160.00	X
1	REAR WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	30sn
1	REAR LEFT TYRE	\$	SL	300.00	X
1	REAR LEFT TYRE RIM	\$	nd	380.00	✓
1SET	PARKING AID	\$	SL	700.00	X
1SET	REAR BUMPER CLIP	\$	acc	66.00	✓
1SET	BUMPER BRACKET CTR CLIP	\$	nn	33.00	✓
1SET	BUMPER BRACKET SIDE CLIP LH RR	\$	nn	10.00	X
1SET	BUMPER RETAINER CLIP LH RR	\$	nn	20.00	X
1SET	BUMPER LOWER REAR RIVET	\$	nn	22.00	X

Trans-cab Auto Services Pte Ltd

AAD2002-147

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 719U

1SET BUMPER LOWER REAR CLIP	\$	<i>nn</i>	66.00	X
1 Rear Bumper Protector	\$	<i>nn</i>	100.00	X
1SET Rear licence plate with holder	\$	<i>nn</i>	80.00	X
1 REAR DOOR STICKER '6555-3333'	\$	<i>nn</i>	100.00	X
TOTAL	\$		2,325.00	

TOTAL PARTS	\$		17,722.68	
--------------------	-----------	--	------------------	--

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$		7,500.00	<i>600</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>nn</i>	380.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$		380.00	<i>100</i>
To check steering geometry and computer wheel alignment	\$		220.00	<i>60</i>
To transfer of rear windscreen glass to facilitate bodywork repair.	\$		170.00	<i>120</i>
To rust-proofing of the affected areas.	\$		170.00	<i>30</i>
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	X
To transfer of Rear bumper fittings, attachment and perform water seepage test.	\$	<i>nn</i>	170.00	X
To transfer of tire, rim and on wheel balancing.	\$		170.00	<i>20</i>

Trans-cab Auto Services Pte Ltd

AAD2002-147

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 719U

To Check Electrical Lighting Concerned.	\$	170.00	201
To reinstall rear bumper parking sensor.	\$	170.00	601
Putty and spray painting of the affected portion.	\$	7,500.00	4401
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	380.00	X NN
To dismantle and refit rear axle assy, remove and renewal of parts, final checking and testing.	\$	~ 380.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$	~ 170.00	X
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	~ 380.00	X
TOTAL	\$	18,480.00	
Over All Total	\$	36,202.68	

PART BY PART (REPAIR DAY)**25 DAYS**

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: