

振明摩托

CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883

Tel: 6747-4810 Fax: 6745-5018

cmmotors@singnet.com.sg

Our Ref: EST043/20/TP

Your Ref: TP claim against SHD8596D

24-Feb-20

MS First Capital Insurance Ltd

36 Robinson Road

#16-01 City House

Singapore 068877

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Estimated cost of repair to Motorcycle no: JRJ5764

Date of accident: 16-01-2020

Parts supply:

1 pc Handle bar <i>new</i>	S\$ 120.00 +
2 pcs Handle bar grip @\$20.00 <i>RH cut</i>	40.00 - 20
2 pcs Balancer @\$12.00 <i>LH cut</i>	24.00 ✓
2 pcs Side mirror @\$65.00 <i>LH cut</i>	130.00 - 65
1 pc Headlamp <i>cut</i>	65.00 ✓
1 pc Headlamp garnish <i>could</i>	95.00 ✓
1 pc Front visor <i>cut</i>	45.00 ✓
1 pc Front nose garnish <i>new</i>	65.00 +
2 pcs Front signal lamp @\$25.00 <i>2# new</i>	50.00 +
2 pcs Front side fairing @\$120.00 <i>LH cut</i>	240.00 - 120
2 pcs Front side fairing garnish @\$25.00 <i>new</i>	50.00 +
1 set Sticker <i>new</i>	75.00 - 50 (Sw)
2 pcs Front fork @\$180.00 <i>Bent</i>	360.00 ✓
1 pc Front fork centre bracket <i>Bent</i>	45.00 ✓
1 pc Front fork top bracket <i>Bent</i>	45.00 ✓
2 pc Front rim <i>Bent</i>	220.00 440 ✓
1 pc Front tyre (S/Nett) <i>new</i>	120.00 +
1 pc Front L/h ^{mirror} fairing garnish <i>could</i>	65.00 ✓
1 pc Footrest L/h rubber <i>cut</i>	15.00 ✓
1 pc Footrest bracket <i>new Bent</i>	35.00 ✓
1 pc Gear shift bracket <i>Bent</i>	85.00 ✓
1 pc Rear footrest L/h <i>new Bent</i>	35.00 ✓
1 pc Rear footrest L/h bracket <i>new</i>	25.00 ✓
1 pc Rear L/h side garnish <i>could</i>	65.00 ✓
1 pc Rear L/h signal lamp <i>new</i>	25.00 +
1 pc Rear mudflap <i>could</i>	35.00 ✓

1659

1493.10

2,394.00

Less 10%: (239.40)

S/Nett Items

1 pc Front no. plate (S/Nett) <i>new</i>	15.00 ✓
1 pc Front compartment box (S/Nett) <i>cut</i>	65.00 - 50
1 pc Rear no. plate (S/Nett) <i>could</i>	15.00 ✓
1 pc Rear box (S/Nett) <i>could</i>	280.00 - 200
1 pc Rear box bracket (S/Nett) <i>new</i>	85.00 +

280

振明摩托

CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883

Tel: 6747-4810 Fax: 6745-5018

cmmotors@singnet.com.sg

Re: Estimated cost of repair to Motorcycle no: JRJ5764

Date of accident: 16-01-2020

Parts supply:

Balance b/f:

S\$ 2,599.60

Labour charges:

To panel beating, welding, removing damaged parts and replacement of the new parts as mentioned above etc.

To towing charges (from Traffic Police Impound)

To respray affected part.

To check wirings.

470

S\$

450.00 200
50.00 40
350.00 200
30.00 ✓

3,479.60

total: 2243.10

h/s: 181c

040up.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: