

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20003166/EGA3Q2

Date: 15/09/2020

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D19MPC0001236
Claimant Vehicle No :	SJE680S	Insured Vehicle No :	SKB4247M
Date of Loss:	23/02/2020	Nature of Claim:	TP
		Claim No:	MPC2020D0000368

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJE680S	Engine No:	12725310B48B20B
Make & Model:	BMW 730LI, 2.0 LED NAV HUD SR (A)	Chassis No:	WBA7E02000G913455
Reg. Date:	27/07/2018 (Man. Year: 2018)	Odometer:	22089 km
Colour:	White		
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/45 R19	Rear Tyre Size:	245/45 R19
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,526.24	2,362.75	163.49	6.47
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	120.83	120.83	0.00	0.00
Paintwork Labour	218.97	218.97	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,877.04	2,713.55	163.49	5.68
Approved Total (Overridden) (\$\$)		2,150.00		
(\$\$)	2,877.04	2,150.00	727.04	25.27
+ GST 7.00/7.00% (\$\$)	201.39	150.50	50.89	25.27
Nett Amount (\$\$)	3,078.43	2,300.50	777.93	25.27
+ Car Rental (4.0 x S\$160.50/day) (\$\$)		642.00		
+ Doc/Search Fee (\$\$)		2.00		
Nett Liability (\$\$)		2,944.50		
Global Sum Settlement (\$\$)		2,900.00		

INSPECTION

Date of Assignment:	25/02/2020 Present Location:	Mova Automotive Pte Ltd (Bukit Merah)
Date Inspected:	24/03/2020 Inspected At:	Mova Automotive Pte Ltd (Bukit Merah)

Blk 1008, #01-04/06/08/94, Bukit
Merah Lane 3
Singapore 159722

Estimated Period of Repair: 3.0 days

Adjuster: CHEN TSUE YEE

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Aug 2020)
Parts:	143	BMW 730LI 2.0 LED NAV HUD SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJE680S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*L/INN U-SONIC SENDER	Shorted	250.00 FL	*250.00 FL
2	1	NA	*REAR BUMPER COVER	Dented	1,750.00 FL	*1,750.00 FL
3	1	NA	*REAR BUMPER COVER	Not Necessary	90.00 FL	*- FL
4	1	NA	*REAR BUMPER MOULDING	Not Necessary	84.20 FL	*- FL
5	1	NA	*RR BUMP CTR LWR MLDG	Broken	120.00 FL	*120.00 FL
6	1	NA	*RR BUMPER ADAPTER	Broken	95.00 FL	*95.00 FL
7	1	NA	*RR CTR BUMPER GUIDE	Broken	70.00 FL	*70.00 FL
8	1	NA	*RR CTR LWR DIFFUSER	Broken	160.00 FL	*160.00 FL
9	1	NA	*SUNDRY PARTS (NPA)	Not Necessary	0.00 FL	*- FS
10	1	NA	*fee audatex	Necessary	40.00 FL	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,659.20	2,485.00
- List Item Discount on L Items 5.00/5.00% (\$\$)	132.96	122.25
Total Parts (\$\$)	2,526.24	2,362.75

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Paintwork Labour				
1	Total Paint Labour	New	125.00	125.00
2	Total Paint Materials	New	93.97	93.97
Labour Items				
3	Total Panel/Mechanical Labour	New	120.83	120.83
Gross Labour Cost (\$\$)			339.80	339.80

Report was unsubmitted during this print-out.

< END OF ESTIMATES >