

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms: AIG Asia Pacific Insurance Pte Ltd

Date: 24/2/2020

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLP8734L

Chassis No: JM6BN22A8H0158199

MAKE / MODEL : Mazda 3 Sedan 1.5 AT

DATE OF ACCIDENT : 22/02/2020

YOUR INSURED VEHICLE NUMBER :SLW7803R

MILEAGE : 144629 km

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	Rear bumper <i>CRY</i>	1PC	\$ 1,129.00	\$ 1,129.00 ✓
2	Rear bumper reinforcement <i>?/PD</i>	1PC	\$ 564.20	\$ 564.20 ✓
				\$ 1,693.20 <i>1,693</i>
		10% DISCOUNT S\$:	\$ 169.32	<i>-20%</i>
			\$ 1,523.88	<i>1,354.4</i>
	S/Nett			
1	Reverse sensor <i>X SVC</i>		\$ 240.00	
2	Rear bumper clips <i>✓ Nec</i>		\$ 100.00	<i>30</i>
	Total		\$ 340.00	

LABOUR CHARGES

To labour charge for removing rear

- bumper out to facilitate repairs and replacement of damaged parts

\$ 600.00 *250*

- To respray rear bumper

\$ 600.00 *200*

LABOUR TOTAL S\$: \$ 1,200.00 *450.*

TOTAL S\$: \$ 2,723.88

7% GST \$ 190.67

GRAND TOTAL S\$: \$ 2,914.55

Repair day - 2 days

~~PP~~ L/S

before part photo

Sun Pn (Llc)

25/02/2020

Tp without prejudice.

P=1,354.4

N=30

L=450

1,834.4

-20%

1,467.52

L/S
\$1,450

2 days