

Lion City Rentals Pte Ltd
CARROS CENTER
60 JALAN LAM HUAT #04-01 S(737869)
Main +65 62524991

Ms: AIG Asia Pacific Insurance Pte Ltd

Date: 24/2/2020

Attn : MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO. SLP8734L

Chassis No: JM6BN22A8H0158199

MAKE / MODEL : Mazda 3 Sedan 1.5 AT

DATE OF ACCIDENT : 22/02/2020

YOUR INSURED VEHICLE NUMBER :SLW7803R

MILEAGE : 144629 km

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

	<u>PARTS DESCRIPTION</u>	<u>QTY</u>	<u>UNIT PRICE</u>	<u>LIST PRICE</u>
1	Rear bumper <i>CRY</i>	1PC	\$ 1,129.00	\$ 1,129.00
2	Rear bumper reinforcement <i>?</i>	1PC	\$ 564.20	\$ 564.20
				<u>\$ 1,693.20</u>
		10% DISCOUNT S\$:	\$ 169.32	<u>\$ 1,523.88</u>
	S/Nett			
1	Reverse sensor <i>X</i>			\$ 240.00
2	Rear bumper clips <i>Nec</i>			\$ 100.00 <i>30</i>
	Total			\$ 340.00

LABOUR CHARGES

	To labour charge for removing rear bumper out to facilitate repairs and replacement of damaged parts	\$ 600.00 <i>250</i>
2	To respray rear bumper	\$ 600.00 <i>200</i>
	LABOUR TOTAL S\$:	<u>\$ 1,200.00</u>
	TOTAL S\$:	\$ 2,723.88
	7% GST	\$ 190.67
	GRAND TOTAL S\$:	<u>\$ 2,914.55</u>

Repair day - 2 days

p/p

before paint photo.

Sun Pm (Llc)

25/02/2020

Tp without prejudice.