

JHAUTO TRADING

Blk 14 Defu Lane 10
 #01-398
 Singapore 539195
 H/P: 9771 8731
 Email: gjh-wjh@hotmail.com
 Business Registration : 53240776L

CASH SALE
 Invoice Date: 20/02/20
 Vehicle No: SKZ1749A
 Make/Model: Honda Vezel
 Chassis No:
 Mileage:

To: 3rd Party Claim

S/N	QUANTITY	PARTICULARS	UNIT PRICE	AMOUNT (\$\$)
01	01	Rear Bumper <i>crn /</i>		\$480.50
02	01	Rear Boot <i>bt /</i>		\$802.50
03	01	Rear Inner Panel <i>repair</i>		\$406.60
04	01	Rear Windscreen (Dark) <i>X</i> SVC		\$963.00
05	02	Windscreen Gums <i>nn /</i>		\$80.00
06		Windscreen Labour <i>nn /</i>	120	\$150.00
07	01	Rear Right Tail Lamp <i>X</i> SVC		\$385.20
08	02	Rear Bumper Retainer <i>X</i> SVC	\$40.60	\$81.20
09	01	Rear Boot Moulding <i>nn /</i>		\$135.70
10	1 Set	Reverse Sensor <i>X</i> SVC		\$180.00
11		Reverse Sensor Labour <i>nn /</i>	60	\$120.00
12		Rear Boot Lock <i>bt /</i>		\$245.00
13		Rear Bumper Plastic Garnish <i>X</i> SVC		\$385.00
14	02	Rear Boot Hinges <i>X</i> SVC	\$68.00	\$136.00
15		Windscreen Moulding <i>nn /</i>		\$117.70
16		Honda Emblem, Vezel Emblem <i>X</i> nn		\$120.00
17		Labour For Accident Area, Panel Re-alignment & Above Parts Installation	500	\$1800.00
18		Spray Painting For Accident Area	600	\$900.00
Total:				\$7488.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul

Hp 90010068

5 days

L/S

24/02/2020 @ 1150

Resy after repair