

# J-MART MOTOR PTE LTD

Block 5, Defu Lane 10, #01-578,  
 Defu Industrial Park C, Singapore 539186  
 Tel : 6343-0934 Fax : 6343-0921  
 Email : jmartauto@gmail.com  
 Registration No: 201400246D  
 GST Reg. No: 201400246D

22-Feb-20

cc61#(G20003171)/Kca3

Our ref : TP/4821/20

TPA16.

Lim Ee Ling Karen

Asher.

**RE : estimate cost for vehicle no : SKX 314M**

1 pc	rear rh fender	<i>Repair</i>	1840	\$	2,466.00	+
1 pc	rear bumper	<i>Belud</i>			1840.00	-
1 pc	rear bumper rh reflector	<i>new</i>	1656		76.00	+
1 pc	rh taillamp	<i>new</i>			980.00	+
					<u>5,362.00</u>	
			less 10%		536.20	
					<u>4825.80</u>	
Panel beating.			630		500.00	- <i>200</i>
Spray painting.					500.00	- <i>400</i>
Wiring.					30.00	-
					<u>5,855.80</u>	
			Plus 7% GST		409.91	
					<u>6,265.71</u>	

SD : Six thousand two hundred sixty-five & cents seventy-one only.

*Adrian Lj*  
 L/S 24/02/20  
 03 Days

*total: 2286*  
 L/S : 1.8K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date: