

J & H MOTOR

BLK 10 ANG MO KIO INDUSTRIAL PARK 2A #01-03
 ANG MO KIO AUTOPOINT SINGAPORE 568047
 TEL: 64835595 HP/96365090 FAX: 64835895
 Business Registration No: 51395200D
 GST Registration No: 51395200D
 EMAIL:shchua@taichengmotor.com

YOUR REF:DATE: **24.02.20****OUR REF:****AXA INSURANCE SINGAPORE PTE LTD****8 SHENTON WAY #24-01****AXA TOWER****SINGAPORE 068811****ATTN: THE MOTOR CLAIM DEPT****THIRD PARTY****Accident Along Road 1 Whampoa Drive Involving Vehicle GY4102Z****And YN9032D On 11.11.19****Cost of repair to damage vehicle GY4102Z claiming against your Insured YN9032D****Description (Netts)****QTY****Price**

front fender / BUL	1	\$ 760.80	578
front signal lamp / MIS	1	\$ 210.00	126.1
front headlamp / CAA	1	\$ 555.80	395.5
front headlamp panel X repair	1	\$ 490.30	X
front bumper / CAA	1	\$ 786.40	484.4
front fog lamp garnish / SER.	1	\$ 160.40	78.6
front bumper side retainer / RE	1	\$ 110.90	55.35
front bumper retainer top bracket	1	\$ 130.30	} 91.7
front bumper retainer lower bracket // BT	1	\$ 65.30	
		\$ 3,270.20	1809.65
	Parts Less 10%	\$ 327.02	
		\$ 2,943.18	1628.68

Special netts

front bumper fog lamp / CAA	\$ 292.70	232.2
-----------------------------	-----------	-------

Miscellaneous:

supply of clips / MCL	\$ 30.00	/
door side marking sticker /	\$ 28.00	/
door centre sticker /	\$ 80.00	20
door centre chrome moulding / MCL	\$ 70.00	20

98

Labour:

to remove accident affected wiring to facilitate repair		
removal of necessary parts to facilitate changing of fender		
change of headlamp panel	\$ 380.00	80.
to remove damaged parts, knocking, flattening rear		
panel fixing and align of parts	\$ 650.00	500
to respray of accident affected portion, mainly front door		
front headlamp panel, front panel, front fender, bumper etc.	\$ 900.00	700
to anti rust accident portioin	\$ 80.00	60.

Total: \$ 5,453.88 1340

Total Dollars Estimated: Five Thousand Four Hundred Fifty Three And Cent Eighty Eight Only.

J & H MOTOR
BLK 10 AMK AUTOPOINT
ANG MO KIO INDUSTRIAL
PARK 2A #01-03
SINGAPORE 568047
TEL: 6483 5595 FAX: 6483 5895

Mr. CHAN A/P 96265090

3298.88

20% : 2600

repair limit \$1500

5 Days.

Unpaid repair.

After repair photos.

Gao Qian - 82880282

25/2/2020.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: