

**MODERN AUTOMOTIVE PTE LTD**  
**BLK 3023A UBI ROAD 1 # 01-61**  
**SINGAPORE 408717**

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

**CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD**

3 Anson Road #16-00  
 Springleaf Tower  
 Singapore 079909  
 Tel: 6389 - 6111  
 Fax : 6224 - 7478 / 7175

**Quotation**  
 DATE : 24.02.2020  
 VEH NO : SKX1051P  
 MODEL : Toyota Vellfire  
 D O A : 22.02.2020  
 YR REF : SLE1100U

*Vic*

Attn : Motor Claim Dept (Pls arrange vehicle survey & check liability)

**RE : ESTIMATE FOR ACCIDENT REPAIR SKX1051P (TOYOTA VELLFIRE)**

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
<b>NO</b>	<b>LIST ITEMS</b>		
1	Front Wing Mirror - RH <i>Broken</i>	1	1,300.30 ✓
2	Front Wing Mirror Cover - RH <i>Missing</i>	1	181.00 ✓
			<hr/>
			\$ 1,481.30
	<i>Less 20% 25%</i>		(296.26)
			<hr/>
			\$ 1,185.04
			<hr/>
	<b>Total parts</b>		<b>\$ 1,185.04</b> <i>1185.04</i>

*1185.04*  
*111097*

**LABOUR CHARGE**

1	To renew above parts		\$ <del>200.00</del> <i>100</i>
2	To spray up fender, mirror	<i>A30</i>	\$ <del>400.00</del> <i>300</i>
3	To check wiring system		\$ <del>50.00</del> <i>30</i>
			<hr/>
	<b>Total Labour</b>		<b>\$ 650.00</b>
			<hr/>
	<b>Grand Total</b>		<b>\$ 1,835.04</b>

**GST will be reflected in the final bills**  
 the Repairer of the following:  
 • To resurvey before/alter spray painting  
 • To display damaged part(s) during resurvey  
**NOTE:**  
 • Parts prices are subject to confirmation  
 • **PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY**  
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*total 1540.97*  
*(P/P)*  
*02 days*