· Men 09/03/00/00.30am SJP7369M

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770

280, Kampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773 315, Alexandra Road Sime Darby Business Centre Singapore 159944 Fax. 64796601 (AfterSal 64796624 (Motorrad



GST REG. NO : M2 - 0020081 - X

2 5 FEB 2020

ESTIMATE

Estimate N Date Estim Prepared B	nated : 25/02/2020		Page No.	: 1 of	5
- ESTIMATE REPAIR FOR - Tan Kim Lan Blk 675C Yishun Avenue 4 #11-802		- ACCOUNT - 40000 Cash Sales - Service Singapore			
Singapore	763675				
REGN. NO.	CHASSIS NO. REGN. DA' WBA2A320307A00912 31/05/20			MIL O	EAGE
	DESCRIPTION To replace rear bumper & attac hments including the dented area caused by the accident	to knock out		850	VALUE 1,275.00
	To respray rear bumper			934	1,038.00
	To remove old PDC assembly, replace damaged preconnect to new bumper including conduct check proper function.				177.00
	To check electrical wiring systems and lightings at rear section for proper function.	the		13	70 177.00
	Sundries.			80 /	80.00
			Total Labour	1: —	2,747.00
	# REAR BUMPER PANEL PRIMED (PD / DT) RR BUMPER LH SIDE GUIDE X NN # REAR BUMPER CARRIER X NN SUPPORT X NN SET MOUNTS PDC SENSOR REAR / DECOUPING RING PDC TORQUE CONVERTER # ULTRASONIC SENSOR GLACIERSIL (DG/SL) ADHESIVE SET K6 X NN	X NN X NN X NN	OTY PRIC 1 1,045.45 1 61.35 1 460.40 1 45.55 1 60.70 2 5.10 2 370.00 1 53.05		VALUE 1,045.45 61.35 460.40 45.55 60.70 10.20 740.00 53.05
	(BOIOL) ABILLOIVE SET NO X ININ		Total Parts	. —	2,476.

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company Co. Reg. No. 197401559W GST Reg. No M2-0020081-x Toll-Free Number (1800-2255269)

303, Alexandra Road Sime Darby Performance Centre Singapore 159941 Fax. 64747770 280, Kampong Arang Road East Coast Centre Singapore 438180 Fax. 63449773

315, Alexandra Road Sime Darby Business Centre Singapore 159944 (AfterSales) (Motorrad) Fax. 64796601 64796624



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No.

: b1 54585

Date Estimated Prepared By

: 25/02/2020 : Han Kwan Yong Page No. : 2 of 5

REGN. NO.

CHASSIS NO.

REGN. DATE

MODEL

MILEAGE

SJP7369M

WBA2A320307A00912

31/05/2018

218i AT

0

LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured	
Date&Time	
Surveyor's Tel	Yes / No
RESURVEY PARTS PHOTO BY SURVEY	PML Yes / No
Surveyor's E-mail	,



2,747.00 Labour 1 2,476.70 Parts 0.00 Labour 2 0.00 Excess 365.66 Total GST @ 7%

Grand Total 5,589.36