

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHC 5745R - AXA

ROEL

\$12,594.00

5 Days.

2 Lp

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHC 5745R - ROEL
 VF1ABL15AUC281652
 RENAULT
 LATITUDE
 12.11.15
AXA

		PART	LIST	
1	1	BUMPER COVER REAR — Petrol	\$	852.66
2	1	BUMPER LOWER REAR — cl	\$	591.41
3	1	BUMPER BRACKET CTR REAR — cr	\$	87.29
4	1	BUMEP R BRACKET SIDE RH REAR — cr	\$	104.59
5	1	BUMEP R RETAINER RH REAR — cr	\$	34.61
6	1	BUMPER REFLECTOR RH X sun	\$	33.55
7	1	BUMEP R BRACKET SIDE LH REAR — cr	\$	104.59
8	1	BUMEP R RETAINER LH REAR — cr	\$	34.61
9	1	BUMPER REFLECTOR LH X sun	\$	33.55
10	1	BUMPER BEAM REAR — Det	\$	598.09
11	1	BUMPER BEAM BRACKET LH REAR — Det	\$	173.81
12	1	BUMPER BEAM BRACKET RH REAR — Det	\$	173.81
13	1	BOOT REAR — Det	\$	2,209.75
14	1	BOOT FINISHER (Moulding) X sun	\$	429.90
15	1	BOOT WHEATERSTRIP X sun	\$	248.50
16	1	BOOT REFLECTOR LAMP RH — cr	\$	379.50
17	1	BOOT REFLECTOR LAMP LH — cr	\$	379.50
18	1	BOOT BADGE 'RENAULT' — cr	\$	173.35
19	1	BOOT BADGE — cr	\$	173.35
20	1	BOOT STRUT (SPRING) V sun	\$	212.36
21	1	BOOT HINGE LH X sun	\$	282.96
22	1	BOOT HINGE RH X sun	\$	282.96
23	1	BOOT INNER TRIM X sun	\$	586.45
24	1	BOOT SWITCH X sun	\$	107.78
25	1	BOOT LOCK X sun	\$	155.90
26	1	BOOT LOCK CATCH X sun	\$	72.00
27	2	LICENCE PLATE LAMP X sun	\$	84.00
28	2	BOOT RUBBER PLUG X sun	\$	170.63
29	1	FENDER PANEL REAR LH X sun	\$	2,537.80
30	1	FENDER WHEELARCH REAR LH (Linner) X sun	\$	418.06
31	1	FENDER INNER TRIM LH X sun	\$	430.42
32	1	FENDER PANEL REAR RH X sun	\$	2,537.80

TRANS-CAB AUTO SERVICES PTE LTD**ROEL**

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHC 5745R - AXA

33	1	FENDER WHEELARCH REAR RH (Linner) <i>X succ</i>	\$	418.06
34	1	FENDER INNER TRIM RH <i>X succ</i>	\$	430.42
35	1	TAILLAMP RH <i>✓</i>	\$	425.04
36	1	TAILLAMP PANEL RH <i>X succ</i>	\$	759.00
37	1	TAILLAMP LH <i>✓</i>	\$	425.04
38	1	TAILLAMP PANEL LH <i>X succ</i>	\$	759.00
39	1	SPARE WHEEL PANEL (Luggage Floor Panel) <i>X ✓</i>	\$ <i>Am</i>	1,684.52
40	1	SPARE WHEEL PANEL TRIM <i>✓</i>	\$	470.93
41	1	OUTER PANEL REAR (End Panel) <i>✓</i>	\$	1,132.13
42	1	OUTER PANEL REAR (End Panel)TRIM <i>✓</i>	\$	311.20
43	1	EXHAUST REAR <i>X succ</i>	\$	5,760.00
44	1	EXHAUST CAP REAR <i>X succ</i>	\$	177.30

TOTAL \$ **27,448.17****10%** \$ **2,744.82**\$ **24,703.35** *9467.80***Specical Nett**

1	1SET	PARKING AID <i>✓</i>	\$	600.00
2	1SET	REAR BUMPER CLIP <i>✓</i>	\$	66.00
3	1SET	BUMPER BRACKET CTR CLIP <i>✓</i>	\$	33.00
4	1SET	BUMEP R BRACKET SIDE CLIP RH RR <i>✓</i>	\$	10.00
5	1SET	BUMEP R RETAINER RH CLIP RR <i>✓</i>	\$	20.00
6	1SET	BUMEP R BRACKET SIDE CLIP LH RR <i>✓</i>	\$	10.00
7	1SET	BUMEP R RETAINER CLIP LH RR <i>✓</i>	\$	20.00
8	1SET	BUMPER LOWER REAR RIVET <i>✓</i>	\$	22.00
9	1SET	BUMPER LOWER REAR CLIP <i>✓</i>	\$	66.00
10	1	EXHAUST MOUNTING REAR <i>X nn</i>	\$	17.82
11	1SET	BOOT FINISHER CLIP <i>✓</i>	\$	24.20
12	1	BOOT STICKER "Trans-cab" <i>✓</i>	\$	30.00
13	1	BOOT STICKER "6555-3333" <i>✓</i>	\$	30.00
14	1	BOOT INNER TRIM CLIP <i>✓</i>	\$	45.00
15	1SET	FENDER WHEELARCH REAR RH CLIP <i>X nn</i>	\$	35.00
16	1SET	FENDER WHEELARCH REAR LH CLIP <i>X nn</i>	\$	35.00
17	1	FENDER INNER TRIM CLIP LH <i>X nn</i>	\$	28.00
18	1	FENDER INNER TRIM CLIP LH <i>X nn</i>	\$	28.00
19	1	TAILLAMP CLIP RH <i>✓</i>	\$	5.00
20	1	TAILLAMP CLIP LH <i>✓</i>	\$	5.00
21	2	REAR WINDSCREEN SELANT <i>X nn</i>	\$	80.00
22	1	WINDSCREEN MOULDING <i>X nn</i>	\$	100.00

TRANS-CAB AUTO SERVICES PTE LTD
 NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346
 TEL NO.6287 6666 FAX NO.6366 8862
 CO/GST REG NO.201019626G
SHC 5745R - AXA

ROEL

23	1	REAR WINDSCREEN INNER SPONGE SEAL ✓ ₄₇	\$	100.00
24	1	SPARE TYRE RIM (ROUE 7J 16H 2547) X ₅₄	\$	385.00
25	1	SPARE TYRE X ₅₄	\$	330.00

TOTAL	\$	2,125.02	98 6 20
TOTAL PARTS	\$	26,828.37	

Putty And Spray Painting Of The Affected Portion.	\$	8,400.00 660
---	----	-------------------------

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	8,500.00 1000
---	----	--------------------------

To Rust-Proofing Of The Affected Areas.	\$	170.00 60
---	----	----------------------

To reinstall rear bumper parking sensor.	\$	170.00 60
--	----	----------------------

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 60
--	----	----------------------

To repair and realign rear exhaust pipe.	\$	170.00 X 47
--	----	------------------------

To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00 X 47
--	----	------------------------

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00 60
--	----	----------------------

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00 60
--	----	----------------------

To supply and re-do rear luggage floor panel insulation padding.	\$	380.00 100
--	----	-----------------------

To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00 X 47
---	----	------------------------

TRANS-CAB AUTO SERVICES PTE LTD**ROEL**

NO.42 SUNGEI KADUT ST 1 SINGAPORE 729346

TEL NO.6287 6666 FAX NO.6366 8862

CO/GST REG NO.201019626G

SHC 5745R - AXA

Towing Fees	\$	120.00 80
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00 X 117
To check steering geometry and computer wheel alignment	\$	220.00 X 92

TOTAL	\$	19,360.00	2140
Over All Total	\$	46,188.37	

(PARTS BY PARTS)**Repair Days****30Days**

Kalin (LKL)

M 17/4/15

5 Repair Days

Before Paint ph