LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd

AIG Building 78 Shenton Way #08-16

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 079120 Singapore 408933

Attn: Azlan, Syazairdina Date: 08 Apr 2020

Preliminary Advice

Vehicle No : SLD9595C **Accident Date** : 21/02/2020

Make : AUDI Q5 Policy No.

: 26/02/2020 **Excess** : S\$500.00 **Assignment Date** Date of Inspection : 25/02/2020 Est. Duration of Repair : 16 days

Inspection At : Premium Automobiles Pte Ltd (UBI)

> 55 Ubi Road 1 Singapore 408699

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross) :S\$ 47.094.00 (inclusive supp)

35,102.70 (inclusive supp & check) **Revised Amount** :S\$

Check Items (Estimated) :S\$ 1,065.00 Total :S\$ 36,164.70

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 194,000.00 COE / PARF Rebate :S\$ 74,318.00

Salvage Value :S\$

Margin for Repair :S\$ 119,682.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
	Kindly let us have your authorisation.

- The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- Other comments: check items no. 15 & 21 amount is \$1,062.00, supplementary amount is \$103.00. (X)