

Premium Automobiles Pte Ltd

55 Ubi Road 1, Singapore 408699

Tel : (65) 6366 2323 Fax : (65) 6841 1183

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0198/2020/NS
25-Mar-20
Glory Tan
1 of 1
SLD 9595 C
Audi Q5 SPORT 2.0 TFSI QU

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	Front fender inner top cover / BR	\$	29.00
2	Front fender inner top outer cover / BR	\$	74.00

TOTAL

\$ 103.00

For Premium Automobiles Pte Ltd

Steve

Authorised Signature

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183
Email: Nora.khai@prelumauto.com.sg / claims@prelumauto.com.sg

WIP : 30468

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0198/2020/NS
Date	:	24-Feb-20

Vehicle NOT IN workshop. Please arrange for survey

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Ng Siew Chye Peter Vincent
Address	:	Blk 525 Canberra Drive #01-63 Singapore 768136
Telephone	:	HP +65 84843318
Type of Claim	:	Own Damage Claims
Policy No.	:	190016884
Vehicle No	:	SLD 9595 C
Model Code	:	Audi Q5 SPORT 2.0 TFSI QU
Model / Year	:	Sep-19
Engine No	:	DAX 055837
Chassis No	:	WAUZZZF8K2091084
Mileage	:	-
Date In	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	21-Feb-20
Place of Accident	:	Along Upper Pickering

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6766 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLD 9595 C

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove, check and reinstall front wire harness for headlights, horns, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00 /	
2	To dismantle rhs front door panel trim. To remove and renew rhs wing mirror assy and rhs door window glass.	S/N \$ 400.00 /	
3	To renew front windscreen to facilitate A-pillar renewal.	S/N \$ 480.00 /	
4	To install front windscreen and rhs front door window glass solar film.	S/N \$ 600.00 /	
5	To dislodge and reinstall rhs A-pillar and rhs front door harness, multi-lock system and power window devices.	S/N \$ 780.00 /	(photo)

SUB TOTAL LABOUR CHARGES : \$ 2,740.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6041 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLD 9595 C

S/N	Nature of Jobs		Estimated Charges	Surveyor's Recommendations
6	To remove and reinstall centre console and dashboard assy for A-pillar renewal. Inspect for damages.	S/N \$	3,200.00	✓ (photo)
7	To remove and reinstall rhs front seat assy, ABCD pillar trims, sill trims, carpets, electronic components and fuse trajs.	S/N \$	1,800.00	✓ (photo)
8	To dismantle front bumper, rhs front fender, bonnet and rhs front door. Cut out and reweld rhs A-pillar. To renew rhs front fender, bonnet and rhs front door. Re-organise front crash management components. Reinstall all parts removed.	\$	7,200.00	3500
9	To respray rhs front fender, bonnet, rhs A-pillar, door entrances, rhs front door, door cover, rhs wing mirror cover and both front wheel arch trims. To carry out joint sealant works and stone chip treatment	\$	6,000.00	3125
10	To renew rhs front rim and tyre. To carry out wheel alignment.	S/N \$	280.00	✓
11	To carry out diagnostic checks.	S/N \$	192.00	✓
TOTAL LABOUR CHARGES		:	<u>\$ 21,412.00</u>	

530 x 45
+ 100

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLD 9595 C

Damage Parts & Prices
S/NETT Remarks

S/N Parts Description

1	FRONT FENDER - RH / <i>DD</i>	\$	1,344.00	
2	FRONT FENDER BRACKET - RH ?	\$	17.00	
3	FRONT FENDER CENTRE BRACKET - RH ?	\$	17.00	
4	FRONT FENDER CLOSING ELEMENT - RH ?	\$	98.00	
5	S-LINE INSCRIPTION / <i>MC</i>	\$	117.00	
6	FRONT WHEEL COVER - LH / RH / <i>CM</i>	2 \$	1,190.00	
7	FRONT WHEEL HOUSING LINER - RH ?	\$	248.00	
8	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS ?	\$	36.00	
9	FRONT DOOR - RH / <i>DD</i>	\$	2,972.00	
10	BONDING AGENT / <i>MC</i>	NEC \$	46.00	
11	CLEANING SOLUTION / <i>MC</i>	NEC \$	64.00	
12	FRONT DOOR ATTACHMENT PARTS / <i>MC</i>	\$	249.00	
13	FRONT DOOR OUTER SEAL - RH / <i>MC</i>	NEC \$	193.00	
14	FRONT DOOR CATCH X	\$	137.00	
15	FRONT DOOR COVER - RH ? / <i>CRU</i>	\$	683.00	
16	EXTERIOR MIRROR MOUNTING / <i>BR</i>	\$	1,647.00	
17	MIRROR CAP - RH / <i>MIS</i>	\$	445.00	
18	MIRROR GLASS - RH / <i>MIS</i>	\$	1,797.00	
19	CORNER TRIM - RH / <i>CM</i>	\$	43.00	
20	WINDOW GUIDE TRIM STRIP - RH / <i>CM (up)</i>	\$	320.00	

SUB TOTAL SPARE PARTS CHARGES

: \$ 11,663.00

Steve

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLD 9595 C

S/N	Parts Description	Damage Parts & Prices	Remarks
		S/NETT	
21	FRONT WINDOW SLOT SEAL - RH <i>7 / CM (rdn) - CM</i>	\$ 580.00	
22	WATER DEFLECTOR STRIP - RH <i>X</i>	\$ 63.00	
23	WINDOW GUIDE - RH <i>?</i>	\$ 454.00	
24	PILLAR A/B SECTIONAL PART - RH <i>/ 00</i>	\$ 3,380.00	
25	BONNET <i>X R</i>	\$ 3,824.00	
26	BONNET ATTACHMENT PARTS <i>X</i>	\$ 133.00	
27	BONNET IMPACT PROTECTION - CENTRE <i>X AK</i>	\$ 26.00	
28	BONNET IMPACT PROTECTION - LH / RH <i>X</i>	2 \$ 52.00	
29	FRONT WINDSCREEN <i>/ MC</i>	\$ 1,357.00	
30	RAIN SENSOR GEL FOIL <i>/ MC</i>	\$ 130.00	
31	RAIN SENSOR RETAINING SPRING <i>/ MC</i>	\$ 20.00	
32	FRONT DOOR WINDOW - RH <i>/ CM</i>	\$ 278.00	
33	FRONT ALUMINIUM RIM - RH <i>/ CM</i>	\$ 954.00	
34	FRONT TYRE - RH <i>/ TN (90%)</i>	\$ 1,193.00	
35	FRONT DOOR HINGE HALF UPPER PART - RH UPPER <i>?</i>	\$ 43.00	
36	FRONT DOOR HINGE HALF LOWER PART - RH UPPER <i>?</i>	\$ 43.00	
37	FRONT DOOR HINGE HALF UPPER PART - RH LOWER <i>?</i>	\$ 43.00	
38	FRONT DOOR HINGE HALF LOWER PART - RH LOWER <i>?</i>	\$ 43.00	
39	FRONT WINDSCREEN SEALANT <i>/ MC</i>	S/N \$ 200.00	
40	ACRYLIC SEALANT <i>/ MC</i>	S/N \$ 180.00	
41	CAVITY WAX <i>/ MC</i>	S/N \$ 140.00	
42	STONE CHIP <i>/ MC</i>	S/N \$ 180.00	
43	SUNDRIES <i>?</i>	\$ 600.00	

TOTAL SPARE PARTS CHARGES
TOTAL LABOUR CHARGES
GRAND TOTAL

: \$ 25,579.00
: \$ 21,412.00
: \$ 46,991.00

All charges are not inclusive of GST.
Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

88 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name
Surveyed Date
Authorised Date
Excess Cost
Liability
Remarks

: Steve (LKK)

00-144 A/L (rent)

EXCESS - ?

12 days

(16)

25/2/20, 11.30am

P/P

By BoL SK

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

- LKK** Consultants hence notify the insurer of the following:
- To survey before/after spray painting
 - To spray damaged part(s) during resurvey
 - Prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant