



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### TAX INVOICE

AUTO & GENERAL INSURANCE (S) PL  
(BUDGET DIRECT INSURANCE)  
190 CLEMENCEAU AVENUE #03-01  
SINGAPORE SHOPPING CENTRE  
SINGAPORE 239924

INV No. AC2003620  
INV Date 04/05/2020  
Reference CS/AGI20003189/Avf3n2  
Code AGI



### PROFESSIONAL SERVICE FEE

Vehicle No. SMH 7718X

Insured Veh. SLH 7954S

Claim No. C10005697

Policy No.

Accident Date 25/02/2020

Inspection Date 26/02/2020

Description	Total
Survey Inspection	250.00
Digital Photographs	
Transportation	
<b>Subtotal</b>	<b>250.00</b>
<b>GST (7%)</b>	<b>17.50</b>
<b>Grand Total</b>	<b>267.50</b>

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

*HYN*



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20003189/Avf3n2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 04-05-2020



Code : AGI

### 1. Policy Particulars :- THIRD PARTY CLAIM

<b>Insured Veh.</b>	SLH 7954S	<b>Veh. Inspected</b>	SMH 7718X
<b>Policy No.</b>		<b>Coverage (\$)</b>	0.00
<b>Claim No.</b>	C10005697	<b>Excess (\$)</b>	0.00
<b>Assign From</b>	IVY RATILLA	<b>Assign Date</b>	26/02/2020

### 2. Vehicle Particulars & Condition

<b>Make &amp; Model</b>	TOYOTA NOAH HYBRID	<b>c.c</b>	1797
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2019
<b>Chassis No.</b>	ZWR800348687	<b>Colour</b>	WHITE
<b>Odometer</b>	44670	<b>Steering</b>	IN ORDER
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM
<b>General</b>	GOOD		

### 3. Conditions of Tyres

	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>	195/65 R15	YOKOHAMA	6 mm
<b>L/H Front Tyre</b>	195/65 R15	YOKOHAMA	6 mm
<b>R/H Rear Tyre</b>	195/65 R15	YOKOHAMA	6 mm
<b>L/H Rear Tyre</b>	195/65 R15	YOKOHAMA	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.
---

### 5. General Information

<b>Accident Date</b>	25/02/2020	<b>Inspection Date</b>	26/02/2020
<b>Survey held at</b>	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	<b>3 Working Days</b>
-------------------------------------	-----------------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMH 7718X**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	DEFORMED	596.00	596.00
2	FRONT BUMPER SIDE HOLDER @\$189.50	NOT NECESSARY	379.00	-
1	FRONT BUMPER RH SIDE LOWER GARNISH	NOT NECESSARY	298.60	-
1	SET FRONT BUMPER CLIPS	NOT NECESSARY	66.00	-
1	FRONT RH FENDER	TO REPAIR SEE LABOUR	804.50	-
1	FRONT RH FENDER INNER SHIELD	NOT NECESSARY	408.90	-
1	SET FRONT RH FENDER INNER SHIELD CLIPS	NOT NECESSARY	66.00	-
1	FRONT RH FENDER HYBRID EMBLEM	NECESSARY	67.20	67.20
1	FRONT RH HEADLAMP	CUT	3,183.10	2,893.00
	LESS 25% DISCOUNT		-1,467.33	-889.05
			4,401.97	2,667.15
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT RH SPORT RIM (SN)	CUT	850.00	580.00
1	FRONT RH TYRE (SN)	NOT NECESSARY	380.00	-
			1,230.00	580.00
<b><u>LABOUR</u></b>				
	TO CHECK WHEEL ALIGNMENT.		100.00	80.00
	REMOVE, REPLACE & REPAIR CONSISTENT TO THE ACCIDENT. INCLUSIVE OF THE REPAIR OF FRONT RH FENDER.		1,000.00	250.00
	RESPRAY PAINTING.		1,200.00	450.00
			2,300.00	780.00
<b>GRAND TOTAL</b>			<b>7,931.97</b>	<b>4,027.15</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,200.00</b>

Report Ref No. CS/AGI20003189/Avf3n2

**ADRIAN LING WAI PING****B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI****Licensed Appraiser**

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMH 7718X

INSPECTION





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R







## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

