

ASS. REC. BY:

REF: CS/TP 200 03194 / Gq-f3s2 | Special Instruction:

Surveyor: Lim Qiny

ASSIGNMENT (Office)

From (Person): Benjamin Tan

of TOPLIS

Date/Time: 26.2.2020 10.54 a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMJ 9132L

Insured:

Public liability

at Workshop m/s

Tan Lim motor

Tel:

68585151

of

51 Defu Lane 10

Policy No:

U203506

Claim No:

SNC 200200007

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

11/2/2020

CA / REV / REP. / REV 24 HRS

np

H.O.D. Endorsement:

Date/Time:

26/2/2020 11.00 a.m

Person Contacted:

Raymen

Vehicle IN / OUT

Date/Time

Action/Instruction () Estimate:

SMJ 9132L - X

Public liability - CS / MSG 2002984103

6/3-353pm revised via email preliaduse:

11/3/20 Submit preli. report.

ASS. REC. BY: bel

REF: Toplis

ASSIGNMENT

From: _____ Date: 26.2.2020

Veh No: SMJ9132L Regn: 25 Mar 2019

Estimated Cost: _____

Type: Car M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or ST 1.6 Turbo

To Inspect Vehicle No: SMJ 9132L

Make: Opel Astra C.C. 1598

at Workshop m/s Tan Lim moto

Colour: Blue A/C: Insured / Std / NI / NA

of 51 Dofu Lane 10

Sp. Reading: 49800 T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: _____

Policy No. _____

C/No: W0VBD 8EG 6K8031586

Claims No. _____

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____ Excess: _____

Steering: In order / Jammed / Leaked / Burnt or


(Client's Record)

Brake: In order / Jammed / Leaked / Burnt or

Make of Veh: _____

Modi: Nil / S/Rim / STD / Rim or

(Policy Condition)



Remark: The veh had commenced its repair at the time of inspection.

Tyre Size: F: 205/55R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continental

Bal. or Market Value: \$80K

Front 6 mm Rear 6 mm

IDAC Accident Rpt: _____ Consistent?: Yes or No

R/Bal. 6 mm

GIA / PR Seen: _____ Consistent?: Yes or No

L/Bal. 6 mm

Est. Repairs: 9 days Res.: Yes or No

D.O.A. _____ D.O.I. 26-02-20

Lum Sum: _____ % 3 Val.: Yes or No

Survey held at w/s 1pm

CA / REV / REP. / 24 HRS mp

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>COB : 48277</u>

Date/Time, File Pass to? Prel. Report

Days Of Repair: _____

1) 11/3 tan lim Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to? _____

Survey Fee: 350

Report Format: _____

Transportation: 50

Lump Sum / I.B.I: (\$) _____

Site Insp (\$) _____

Interview (\$) _____

Tech. Invs (\$) _____

Weekend (\$) _____

12x15=180
180+170=350

Survey Fee:	<u>350</u>
Transportation:	<u>50</u>
S + RS, SI	
Photos	<u>30</u>
Others	<u>80</u>
TOTAL	<u>510</u>

Nivithia (LKK Auto)

From: Benjamin Tan <benjamintan@toplis.com.sg>
Sent: Wednesday, 26 February 2020 10:54 AM
To: assignments@lkkauto.com; sur@lkkauto.com
Cc: victorfong@toplis.com.sg; toplis@outlook.com
Subject: FW: Insured: Kim Bock Contractor Pte Ltd - Survey of third party vehicle SMJ9132L
CTI Ref: SNC20D200007 TH Ref: U203506
Attachments: SMJ9132L Estimate.pdf

Dear Summer

Resend as requested.

Kind regards
Benjamin Tan



Toplis And Harding (S) Pte Ltd
133 Cecil Street
#17-01A Keck Seng Tower
Singapore 069535
Company reg. no. 197300081R
Tel : +65 6226 2122
Fax : +65 6224 8981



(In association with Context International

Reply email : benjamintan@toplis.com.sg
Alternative email for large attachments: toplis@outlook.com

This email is confidential and may also be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any persons.

From: Benjamin Tan <benjamintan@toplis.com.sg>
Sent: Wednesday, 26 February 2020 9:48 am
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: 'Peng Peng' <peng.peng@sg.cntaiping.com>; 'victorfong@toplis.com.sg' <victorfong@toplis.com.sg>; 'toplis@outlook.com' <toplis@outlook.com>
Subject: Insured: Kim Bock Contractor Pte Ltd - Survey of third party vehicle SMJ9132L CTI Ref: SNC20D200007 TH Ref: U203506

Your Ref: Please advise
Our ref : U203506

Dear Sir

We are the loss adjuster appointed by China Taiping Insurance (Singapore) Pte Ltd to look into the matter involving a fallen tree on third party 'Opel' car SMJ9132L at Ngee Ann Polytechnic's open surface carpark near Blk 50, Ngee Ann Polytechnic.

On behalf of China Taiping Insurance, we would like to appoint you to survey / assess the damage to the third party's Opel car (no. SMJ9132L) on a 'without prejudice' basis. Attached is the estimate of repair of the said car for your reference.

Kindly carry out the 'without prejudice' survey as soon as possible and let us have your survey report on your assessment of the estimate of repair soonest.

Please contact the following motor workshop for your survey :-

Ms Caymen

Tan Lim Motor Pte Ltd

caymen@tlimotor.com.sg

O: +65 6858 5151

Please send your motor survey report to China Taiping (Singapore) Pte Ltd – for attention of Mr Peng Peng (Claim Reference: SNC20D200007) and copy your survey report to us for reference.

Kind regards

Benjamin Tan



Toplis And Harding (S) Pte Ltd
133 Cecil Street
#17-01A Keck Seng Tower
Singapore 069535
Company reg. no. 197300081R
Tel : +65 6226 2122
Fax : +65 6224 8981



(In association with Context International)

Reply email : benjamintan@toplis.com.sg

Alternative email for large attachments: toplis@outlook.com

This email is confidential and may also be privileged. If you are not the intended recipient, please delete it and notify us immediately; you should not copy or use it for any purpose, nor disclose its contents to any persons.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Friday, 6 March 2020 3:53 PM
To: Admin-D (LKKAuto); 'Benjamin Tan'; assignments; SUR
Cc: victorfong@toplis.com.sg; toplis@outlook.com
Subject: RE: Insured: Kim Bock Contractor Pte Ltd - Survey of third party vehicle SMJ9132L
CTI Ref: SNC20D200007 TH Ref: U203506
Attachments: PRELI ADVISED SMJ 9132L.pdf

Dear Benjamin,

Enclosed preliminary revised of vehicle **SMJ 9132L**
Number of days (estimated) : 9 days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto) <admin-d@lkkauto.com>
Sent: Wednesday, 26 February 2020 11:24 AM
To: 'Benjamin Tan' <benjamin@toplis.com.sg>; assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: victorfong@toplis.com.sg; toplis@outlook.com
Subject: RE: Insured: Kim Bock Contractor Pte Ltd - Survey of third party vehicle SMJ9132L CTI Ref: SNC20D200007 TH Ref: U203506

Dear Benjamin,

Thank you for the assignment.

Best Regards

G.NIVITHA

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Benjamin Tan [<mailto:benjamin@toplis.com.sg>]
Sent: Wednesday, 26 February 2020 10:54 AM
To: assignments@lkkauto.com; sur@lkkauto.com
Cc: victorfong@toplis.com.sg; toplis@outlook.com
Subject: FW: Insured: Kim Bock Contractor Pte Ltd - Survey of third party vehicle SMJ9132L CTI Ref: SNC20D200007 TH Ref: U203506



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL.: (065) 62563561 FAX : (065) 62564315

Your Ref: U203506

Date: 06/03/2020

Our Ref: CS/TP20003194/Gqf3

The Motor Claims Department
TOPLIS AND HARDING (S) PTE LTD

Without Prejudice

Dear Sirs/Mdm


PRELIMINARY ADVICE OF VEHICLE NO. SMJ 9132L .

Please be informed that we had conducted the inspection of the above mentioned vehicle on 26/02/2020 at the premises of M/s Tan Lim Motor and have the following to report: -

Workshop Estimate Amount	: S\$ <u>22,017.00</u>
Revised Estimate Amount	: S\$ <u>9,215.40</u>
"Check" Items Amount	: S\$ <u>1,421.20</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at rooftop.



Comments/ Present Status:

Damages Consistent.

Yours faithfully
Xing Guo Qiang
Automotive Assessor

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	12/02/2020 15:25
Date Of Accident	11/02/2020 19:30
Exact Location Of Accident	NGEE ANN POLY OPEN CARPARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMJ9132L
Insured/Policyholder	
Name Of Registered Owner	BIS MOTORING PTE LTD
Co Reg No	2XXXXX055D
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62523822

Vehicle Particulars

Manufacturer	OPEL
Model	ASTRA ST 1.6 TURBO DIESEL (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	ETIQA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	M0014361
Cover Note Number	26.12.2019 TO 25.12.2020

Driver

Name of Driver	MUHAMMAD NABEEL SHAHEEN BIN BAHARUDIN
NRIC No	SXXXX884B
Date Of Birth	12/11/1992
Occupation	OUTDOOR
Date Of Driving Pass	04/07/2013
Driving Experience	6 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92215824
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLOCK 223A SERANGOON AVENUE 4
 #10-205
 Postcode 551223
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OTHER - HIRER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident HIT BY FALLEN TREE / OTHER OBJECTS
 Weather Conditions RAINING
 Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 1
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance?
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 0

Details of Police Action

Was the accident reported to the police? YES
 If Yes, Please state which Police Station
 Police Station Name GEYLANG NEIGHBOURHOOD POLICE CENTRE
 Police Station Address ROAD: 1 CASSIA LINK , POSTCODE: 397618 , COUNTRY: SINGAPORE
 Police Station Contact TEL NO: - FAX NO:
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

Refer to Police Report G/20200212/2018

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? NO
 Was there any audio recorded? NO



**SINGAPORE
POLICE FORCE**



G/20200212/2018

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. G/20200212/2018

heavily dented. The management officer informed me that the tree had fallen over due to rotten roots. I wish to state that it was raining heavily at the time. I am lodging this report for insurance purposes.

Signature Of Officer Recording The Report: G / Sgt 2 MUHAMMAD ZUHAIR BIN MIOR ABDUL AZIZ	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 12/02/2020 10:19
Officer In-Charge Of Case: G / Bedok Police Divisional Investigation Branch / Sr Staff Sgt NEO JIN MING, EDWIN Contact No.: 62447200	Classification Of Case:
Authentication Stamp SINGAPORE POLICE FORCE SIGNATURE	

> [Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	055D
Vehicle Details	
Vehicle No.:	SMJ9132L
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Feb 2020
Vehicle Make:	OPEL
Vehicle Model:	ASTRA ST 1.6 TURBO DIESEL (A)
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	A3183129JR5X0049
Chassis No.:	W0VBD8EG6K8031586
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$21,882.00
Original Registration Date:	25 Mar 2019
First Registration Date:	25 Mar 2019
Transfer Count:	0
Actual ARF Paid:	\$22,635.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Mar 2029
PARF Rebate Amount:	\$16,976.00
Intended COE Rebate Details	
COE Expiry Date:	24 Mar 2029
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$34,509.00
COE Rebate Amount:	\$31,301.00
Total Rebate Amount:	\$48,277.00

The information contained herein is correct as at 26 Feb 2020

OK

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 055D

Vehicle Details

Vehicle No.: SMJ9132L
Vehicle to be Exported: No
Intended Deregistration Date: 12 Feb 2020
Vehicle Make: OPEL
Vehicle Model: ASTRA ST 1.6 TURBO DIESEL (A)
Primary Colour: Blue
Manufacturing Year: 2019
Engine No.: A3183129JR5X0049
Chassis No.: W0VBD8EG6K8031586
Maximum Power Output: 100.0 kW (134 bhp)
Open Market Value: \$21,882.00
Original Registration Date: 25 Mar 2019
First Registration Date: 25 Mar 2019
Transfer Count: 0
Actual ARF Paid: \$22,635.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 24 Mar 2029
PARF Rebate Amount: \$16,976.00

Intended COE Rebate Details

COE Expiry Date: 24 Mar 2029
COE Category: B - Car above 1600cc or 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$34,509.00
COE Rebate Amount: \$31,456.00
Total Rebate Amount: \$48,432.00

The information contained herein is correct as at 12 Feb 2020

OK



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

CTP Insured's Veh No : TREE
Date of Accident : 11 February 2020

Messrs BIS Motoring Pte Ltd

Date : 26 February 2020

26/2 - Guo qiang
125ch - HK.

Estimate To Repair SMJ9132L - Opel ASTRA ST 1.6 TURBO DIESEL (A)
Chassis No : W0VBD8EG6K8031586

S/No	Quantity	Description	Amount
LIST ITEMS			
01	1 pc	roof top / <i>rig</i>	\$ 2,019.60
02	1 set	roof top crossmember assy (front, centre, rear) / <i>BT</i>	\$ 340.80
03	2 ps	roof side panel - outer @ \$972.00 X <i>Repair</i>	\$ 1,944.00
04	2 ps	roof side panel - outer bracket @ \$210.00 ?	\$ 420.00
05	2 ps	roof side panel - centre @ \$150.00 <i>Repair</i> X	\$ 300.00
06	2 ps	roof side panel - inner @ \$132.00	\$ 264.00
07	2 ps	front A pillar @ \$1148.40 < <i>LH</i> - <i>Buc</i> / <i>RH</i> X <i>Repair</i>	\$ 2,296.80
08	2 ps	roof side trail @ \$438.00 / <i>re</i>	\$ 876.00
09	1 pc	front windscreen glass / <i>CR</i>	\$ 811.20
10	2 ps	front windscreen outer garnish - side @ \$40.80 / <i>re</i>	\$ 81.60
11	1 pc	front windscreen top moulding /	\$ 150.00
12	2 ps	front windscreen moulding - side @ \$16.80 / <i>re</i>	\$ 33.60
13	1 pc	front windscreen moulding - lower /	\$ 150.00
14	1 pc	front windscreen rain sensor ?	\$ 336.00
15	1 pc	roof lining / <i>Comp</i>	\$ 866.40
16	1 pc	roof lining clip / <i>del</i>	\$ 22.80
17	2 ps	sun visor @ \$260.40 ?	\$ 520.80
18	1 pc	room light control panel ?	\$ 44.40
19	1 pc	dashboard X	\$ 2,850.00 <i>sum</i>
20	1 pc	wiper blade set X	\$ 114.00
			\$ 14,442.00
SPECIAL NETT ITEMS			
21	1 pc	front windscreen IU bracket /	\$ 15.00
22	1 pc	front windscreen sealant / } <i>del</i>	\$ 50.00
23	1 pc	front windscreen inner seal /	\$ 50.00
			\$ 115.00
LABOUR & MISC. CHARGES			
01		Putty and spray painting of the affected portion.	\$ 2,500.00 <i>900</i>
02		To dismantle and refit rear seat, backrest, trimming, garnish, roof-lining, speaker shelfboard, carpeting and other to enable body work repair.	\$ 250.00 <i>120</i>
03		To remove and refit front windscreen glass.	\$ 180.00 <i>100</i>
04		To remove and refit rear windscreen glass.	\$ 180.00 <i>XNN</i>
05		To dismantle and refit instrument dashboard, check electrical lightings and re-run, re-route wire harness.	\$ 2,000.00 <i>100</i>



陳林學喙私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

CTP Insured's Veh No : TREE
Date of Accident : 11 February 2020

Messrs BIS Motoring Pte Ltd

Date : 26 February 2020

Estimate To Repair SMJ9132L - Opel ASTRA ST 1.6 TURBO DIESEL (A)
Chassis No : W0VBD8EG6K8031586

S/No	Quantity	Description	Amount
		LABOUR & MISC. CHARGES	
06		To rust-proofing of the affected areas.	\$ 250.00
07		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 2,000.00
08		Towing charges.	\$ 100.00
			\$ 7,460.00
		Total	\$ 22,017.00

80
1300
?

[Handwritten Signature]
21/2/2020
9 Days.
Lump sum repair.
After repair photos
Gmo @iang.
26/2/2020.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CS/TP20003194/Gqf3s2	
C/o: Toplis and Harding (S) Pte Lte 133 Cecil Street #17-01A Keck Seng Tower SINGAPORE 069535		Date : 11-03-2020	
		Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SMJ 9132L
Policy No.	U203506	Coverage (\$)	0.00
Claim No.	SNC20D200007	Excess (\$)	0.00
Assign From	BENJAMIN TAN	Assign Date	26/02/2020
2. Vehicle Particulars & Condition			
Make & Model	OPEL ASTRA ST 1.6 TURBO	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	W0VBD8EG6K8031586	Colour	BLUE
Odometer	49800	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/55 R16	CONTINENTAL	6 mm
L/H Front Tyre	205/55 R16	CONTINENTAL	6 mm
R/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm
L/H Rear Tyre	205/55 R16	CONTINENTAL	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE ROOFTOP. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/02/2020	Inspection Date	26/02/2020
Survey held at	TAN LIM MOTOR PTE LTD 51 DEFU LANE 10 SINGAPORE 539216		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMJ 9132L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	ROOF TOP	DISTORTED	2,019.60	2,019.60
1	SET ROOF TOP CROSSMEMBER ASSY (FRONT, CENTRE, REAR)	BENT	340.80	340.80
2	ROOF SIDE PANEL - OUTER @ \$972.00	TO REPAIR SEE LABOUR	1,944.00	-
2	ROOF SIDE PANEL - OUTER BRACKET @ \$210.00	* CHECK	420.00	-
2	ROOF SIDE PANEL - CENTRE @ \$150.00	TO REPAIR SEE LABOUR	300.00	-
2	ROOF SIDE PANEL - INNER @ \$132.00	TO REPAIR SEE LABOUR	264.00	-
2	FRONT A PILLAR @ \$1148.40	N/S BUCKLED / O/S TO REPAIR SEE LABOUR	2,296.80	1,148.40
2	ROOF SIDE TRAIL @ \$438.00	DEFORMED	876.00	876.00
1	FRONT WINDSCREEN GLASS	CRACKED	811.20	811.20
2	FRONT WINDSCREEN OUTER GARNISH - SIDE @ \$40.80	DEFORMED	81.60	81.60
1	FRONT WINDSCREEN TOP MOULDING	NECESSARY	150.00	150.00
2	FRONT WINDSCREEN MOULDING - SIDE @ \$16.80	NECESSARY	33.60	33.60
1	FRONT WINDSCREEN MOULDING - LOWER	NECESSARY	150.00	150.00
1	FRONT WINDSCREEN RAIN SENSOR	* CHECK	336.00	-
1	ROOF LINING	CRUMPLED	866.40	866.40
1	ROOF LINING CLIP	NECESSARY	22.80	22.80
2	SUN VISOR @ \$260.40	* CHECK	520.80	-
1	ROOM LIGHT CONTROL PANEL	* CHECK	44.40	-
1	DASHBOARD	NOT NECESSARY	2,850.00	-
1	SET WIPER BLADE	NOT NECESSARY	114.00	-
			14,442.00	6,500.40
SPECIAL NETT ITEMS				
1	FRONT WINDSCREEN IU BRACKET (SN)	NECESSARY	15.00	15.00
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	50.00	50.00
1	FRONT WINDSCREEN INNER SEAL (SN)	NECESSARY	50.00	50.00
			115.00	115.00
LABOUR				
PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.			2,500.00	900.00

Report Ref No. CS/TP20003194/Gqf3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE AND REFIT REAR SEAT, BACKREST, TRIMMING, GARNISH, ROOF-LINING, SPEAKER SHELFBOARD, CARPETING AND OTHER TO ENABLE BODY WORK REPAIR.		250.00	120.00
	TO REMOVE AND REFIT FRONT WINDSCREEN GLASS.		180.00	100.00
	TO REMOVE AND REFIT REAR WINDSCREEN GLASS.	NOT NECESSARY	180.00	-
	TO DISMANTLE AND REFIT INSTRUMENT DASHBOARD, CHECK ELECTRICAL LIGHTINGS AND RE-RUN, RE-ROUTE WIRE HARNESS.		2,000.00	100.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		250.00	80.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF ROOF SIDE PANEL - OUTER, ROOF SIDE PANEL - CENTRE, ROOF SIDE PANEL - INNER AND O/S FRONT A PILLAR.		2,000.00	1,300.00
	TOWING CHARGES.	* CHECK	100.00	-
			7,460.00	2,600.00
GRAND TOTAL			22,017.00	9,215.40
RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$1,421.20 NETT)				9,215.40

Report Ref No. CS/TP20003194/Gqf3s2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.