

A.S. REC BY: _____ | REP: 08/MSG20003203/Urds3 | Special Instruction: _____
 Envoys: Marcus Merimen
 From (Person): Christina Wong of MSIG Date/Time: 26/2/2020 @ 10:56am
 Estimated Cost: _____ Bill to: _____
 OD: PIP / WS / TP RES / OD RES / EVA / INV / MV / CS
 To Inspect Vehicle No: SMD 7768D Insured: SJQ 7187R
 at Workshop in/s: Zoom Autowerks Tel: 9450 7920
 of 15 Kaki Bukit Road 4 #01-53
 Policy No: 29122475QMX Claim No: _____
 Sum insured: _____ Excess: _____
 Make of Valt: _____ D.O.A. 23/02/2020
 (Client's record)
 CA / REV / REP. / REV 24 HRS ^{up}
 Date/Time: 11:08am @ 26/2/2020 Person Contacted: Eileen Vehicle: IN OUT

Date/Time	Action/Instruction	Remarks
	SMD 7768D - NA / Lip 2000 3097 / 24	DDA: 23/2/2020
	SJQ 7187R - NA / Lip 2000 3047 / 24	DDA: 23/2/2020
26/2/20	Informed Christina pending repairer est by merimen	
20/4/20	Send preli revised via merimen	

05/11/31 wef
ASS REC BY *Marcus*

REF:

MSIG

ASSIGNMENT

From _____ Date: _____
Estimated Cost: _____
OD / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: *SMQ7768D*
at Workshop m/s: *2200M*
of _____
Insured: _____
Policy No: _____
Claims No: _____
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: *86k*
IDAC Accident Rpt: Consistent? : Yes or No
GIA / PR Seen: Consistent? : Yes or No
Est. Repairs: *18* days Res.: Yes or No
Lum Sum: *20* % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

0762
Vehicle: IN / OUT

Veh No: *SMQ7768D* Yr Regn: *11/19*
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or *CA /*
Make: *Renault GRAND SCENIC 1.461*
Colour: *Green* A/C: Insured / Std / NI / NA
Sp Reading: *3304* T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: *VF1RFA00963522269*
Gen Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size F: *195/55 R 20*
R: _____
BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or
Front _____ Rear _____
R/Bal: *7* mm R/Bal: *7* mm
L/Bal: *7* mm L/Bal: *7* mm
D.O.A. *23/2/20* D.O.I. *26/2/20*
Survey held at _____
Des of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or
Rear & R.
The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

17/4/20 2/5 @ 16.00 confirmed with Elin (Red 28, 274, 97, 64)
LYA 45631

Date/Time, File Pass to? : Preli. Report
 : Final Report

Date/Time, File Return to?

2) *20/4 - typist*

Report Format: *Merimen*
Lump Sum / I.B.I: (\$) *16,000/2*

Days Of Repair: *18*
Resurvey No. of Trip: *2*

Add Fee: Site Insp (\$) Interview (\$) Tech Invs (\$) Weekend (\$)

Survey Fee: _____
Transportation _____

_____ S + RS _____
_____) Photos
_____) Others
_____) _____
TOTAL _____



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring
 #08-1339 Singapore 470130
 Tel: 9450 7920
 zoomautowerks@gmail.com

not A-Worked
nah
1/2 @ 16,000
18 days.

Car Number: SMQ7768D
 Model: RENAULT SCENIC
 Damaged Area: (Front & Rear Portion)
 Repairer Estimation Cost of Repair :
 Supplementary may be included during the cost of repair :

Date: 27/02/2020

Parts / Material :

Part No.	Description	Est. Cost	Material	Price	Status
1	Rear Bumper	1287.32	DIS	\$ 1,408.46	✓
2	Rear Bumper Side Retainer @ \$135.97		11	\$ 271.94	X
3	Rear Bumper Bracket ALS	65.00	CR	\$ 197.36	✓
4	Rear Bumper Centre Bracket	103.60	TR	\$ 168.97	✓
5	Rear Bumper Reflector @ \$195.46		N/SCNE	\$ 390.92	10 C
6	Rear Bumper Lower	480.00	DIS	\$ 968.44	✓
7	Rear Bumper Black Rivets (1 Set)	60.00	RE	\$ 117.45	✓
8	Rear Bumper LH Lower Under Garnish		CR	\$ 175.42	✓
9	Rear Bumper Centre Lower Under Garnish		DIS	\$ 224.23	✓
10	Rear Bumper RH Lower Under Garnish		11	\$ 274.86	X
11	Rear Bumper Beam	625.00	DIS	\$ 777.52	✓
12	Rear Bumper Beam Bracket @ \$225.92		11	\$ 451.84	X
13	Rear Bumper Clips	50.00	RE	\$ 80.00	✓
14	Rear Taillamp @ \$952.96		11	\$ 1,905.92	X
15	Rear Tailgate	2292.70	Soddy	\$ 2,872.68	✓
16	Rear Tailgate Logo	151.20	RE	\$ 234.52	✓
17	Rear Tailgate Emblem (RENAULT)	138.10	RE	\$ 225.36	✓
18	Rear Tailgate Emblem (SCENIC)	119.60	RE	\$ 225.36	✓
19	Rear Tailgate Chrome Moulding		11	\$ 470.06	X
20	Rear Tailgate Glass Inner Sponge Seal	60.00	RE	\$ 223.12	✓
21	Rear Tailgate inner Trimboard	665.10	TR	\$ 786.24	✓
22	Rear Tailgate inner Trimboard Clips		11	\$ 80.00	X
23	Rear Tailgate Lamp @ \$693.35		11	\$ 1,386.70	X
24	Rear Tailgate Lock	485.20	TR/Shift	\$ 495.67	✓
25	Rear Tailgate Sensor		11	\$ 395.26	X
26	Rear Tailgate Weather Strip	392.20	TR	\$ 492.92	✓
27	Rear Fender Inner Shield		11	\$ 495.63	X
28	Rear Fender Inner Shield Clips		11	\$ 80.00	X
29	Rear Left ARC Garnish		11	\$ 295.64	X
30	Rear End Panel	1005.00	Soddy	\$ 1,671.41	✓
31	Rear End Panel Top Garnish	545.20	TR	\$ 545.62	✓
32	Rear Spare Wheel Luggage Floor Panel	1652.00	CR	\$ 1,984.52	✓
33	Rear Exhaust Heat Shield	315.00	DIS	\$ 624.51	✓
34	Rear Exhaust Pipe	2800.00	sent/TR	\$ 4,489.05	✓
35	Rear Exhaust Mounting @ \$78.25		11	\$ 156.50	X
36	Rear Exhaust Muffler Chrome		RE	\$ 230.49	X
37	Rear Sensor (Set)	1022.00	Shift	\$ 1,986.00	✓
38	Front Bumper	1288.00	re/To	\$ 1,359.42	✓
39	Front Bumper lower Garnish		11	\$ 772.43	X

40	Front Bumper Centre Air-Grille		17	\$	296.82	X
41	Front Bumper Chrome Garnish @ \$110.24		17	\$	220.48	X
42	Front Bumper Fog Lamp Garnish @ \$207.21		17	\$	414.42	X
43	Front Bumper Fog Lamp @ \$388.62		17	\$	777.24	X
44	Front Bumper Side Retainer @ \$151.32		17	\$	302.64	X
45	Front Bumper Bracket @ \$98.65		17	\$	197.30	X
46	Front Bumper Support Bracket		17	\$	143.88	X
47	Front Bumper Sponge		17	\$	394.68	X
48	Front Bumper Reinforcement		2	\$	914.08	X
49	Front Bumper Rivets (1 Set)		15	\$	117.45	X
50	Front Bumper Clips	50.00	100	\$	80.00	
51	Front Centre Grille Assy	885.00	100	\$	1,707.84	
52	Front Radiator Grille Clips		17	\$	80.00	X
53	Front Grille Badge	1025.00	50	\$	225.36	
54	Front Headlamp @ \$1,712.40	1355.00	0/5 cna	\$	3424.80	170
55	Frame Full Support Panel		17	\$	815.92	X
56	Front Bumper Angle Sensor		17	\$	1,786.00	X
					Parts :	\$ 38,731.55
					Less Parts 5% :	\$ 1,936.57
					(102) Total Parts :	\$ 36,794.97

Special Net Items :

Rear End Panel Sealant	100	\$	80.00	50
Rear Tailgate Glass Sealant	100	\$	80.00	40
Rear Number Plate W/Garnish	50	\$	80.00	40
Front Number Plate W/Garnish	50	\$	80.00	X
Radiator Coolant	17	\$	80.00	X
Total S/N Parts : \$ 400.00				

Labour :

To Remove, Repair & Renew Rear Affected Accident Areas	\$	1,200.00	✓
To Putty, Spray Paint on Rear Affected Accident Areas	\$	1,400.00	1000
To Check & Re-Connect all electrical wiring	\$	80.00	50
To Remove & Install Rear Tailgate Components Trim & Garnish	\$	200.00	80
To Remove & Install Rear Left Fender Trim, Garnish	\$	200.00	100
To Remove & Install Rear Tailgate Glass	\$	200.00	120
To Remove & Install Rear Exhaust Pipe	\$	200.00	100
To Re-Position, Drill & Install Reverse Sensor	\$	200.00	50
To Conduct Water Leakage Test	\$	17 150.00	X
To Remove, Repair & Renew Front Affected Accident Areas	\$	1,200.00	200
To Putty, Spray Paint on Front Affected Accident Areas	\$	1,200.00	250
To Conduct AC Leakage Test & Top Up AC Gas	\$	17 200.00	X
To Diagnose & Re-Programme Fault Code	\$	450.00	50
To Rust Proof Affected Areas	\$	200.00	60
Total Labour : \$ 7,080.00			

TOTAL PARTS :	\$	36,794.97
TOTAL SPECIAL NET ITEM :	\$	400.00
TOTAL LABOUR :	\$	7,080.00
TOTAL REPAIR COST :	\$	44,274.97

3260

P. 18589.33

107

P. 16730.39

S.N - 130.00

L - 3260.00

20/2031