

Surveyor: Marcus

ASSIGNMENT (Office)

From (Person): Pauline Soh

of EG1

Date/Time: 25/2/2020@5.23pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLA 7594J

Insured:

YP7991M

at Workshop n/s

Automobile Integrated (AIM)

Tel:

9119 8371

of

23 kaki Bukit Ave 4 # 04-01

Policy No:

Claim No:

CDM CG 20000344

Sum Insured:

Excess:

Makes of Veh:

(Client's Record)

D.O.A.

24/02/2020

CA / REV / REP. / REV 24 HRS

1up

H.O.D. Endorsement:

Date/Time:

10:41am @ 26/2/2020

Person Contacted:

Jacynre

Vehicle:

IN/OUT

Date/Time	Action/Instruction	Signature
	SLA 7594J - NN / TM / 18008197 / 13	

D.O.A: 4/5/2018

(08/11/13) : wof
ASS. REC. BY: MOCUS

REF:

ER.1

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
OD / OWS / TP RES / OD RES / EVA / INV / MV
To inspect Vehicle No: SLA7584J
at Workshop m/s: AIM
of _____
Insured: _____
Policy No: _____
Claims No: _____
Sum insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

Veh No: SLA7584J Yr Regn: 8 08
Type: MC / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or CA
Make: Honda stream C.O. 1799
Colour: Silver A/C: Insured / Std / NI / NA
Sp. Reading: 196155 T/Radio: Insured / Std / NI / NA
Eng/No: _____
C/No: RN6 1062321
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Good / Jammed / Leaked / Burnt or
Brake: Good / Jammed / Leaked / Burnt or
Mod: NI / S/Rim / STD A/Rim or
Tyre Size: F: 215/60R16
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUM /
TOYO / YOKO or
Front: 6 mm Rear: 6 mm
R/Bal: 6 mm L/Bal: 6 mm
D.O.A. 24/2/20 D.O.I. 26/2/20

Survey held at _____
Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Lf.
The U/C / Chassis frame / Body Structure affected due to collision

N/S	O/S

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 21500
IDAC Accident Rpt: _____ Consistent? : Yes or No
GIA / PR Seen: _____ Consistent? : Yes or No
Est. Repairs: 5 days Res.: Yes or No
Lum Sum: 20 % S Val.: Yes or No

CA / REV / REP. / 24 HRS LIA 12677
Date: _____ Person Contacted: net 8823
Vehicle: IN / OUT

RECEIVED 04 MAR 2020

Date/Time, File Pass to? ☐ : Prel. Report
☐ : Final Report

Date/Time, File Return to? 4/3/20 Typist

Report Format :
Lump Sum (L.B.I.) (\$) \$6200/=

Days Of Repair: 5
Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:	
Transportation:	350
_____ \$ + RS _____ \$	11
Photo	
Others	
TOTAL	361

1/3/20 28/2/20 3/3/20
oe 30-6-2023 - 3yrs. 4mth.
Pending Estimate sent to Merina
Sent Prel: by Merina
1/5 @ 6200 conf. with kelvin (Red \$5946-36, 48%)

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:198607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 03 Mar 2020

Preliminary Advice

Insured Vehicle No	: YP7991M		
TP Vehicle No	: SLA7594J	Accident Date	: 24/02/2020
Make	: HYUNDAI AVANTE	Assignment Date	: 26/02/2020
Date of Inspection	: 26/02/2020	Est. Duration of Repair	: 5.00
Inspection At	: AUTOMOBILE INTEGRATED MANAGEMENT PTE LTD (HQ) 23 KAKI BUKIT AVE 4 #04-01, KAKI BUKIT (SOUTH WING) SINGAPORE 415933		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	12,146.36
Revised Amount	:S\$	6,200.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,200.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : The above survey was conducted on a without "prejudice" basis.

Adjuster Activity Log

ADJUSTER ACTIVITY LOG

Activity

VEHICLE NO: SLA75943 DOA: 24/02/20

[Add to Below](#)

[28/02/2020 19:39] YVONNE WONG YIN CHENG:
Hi officer-in charge

Please be informed that we have inspected the vehicle SLA75943 on 26/02/20.
We are pending estimate from repairer.

[Print...](#)

[DRAFT]

Nivitha (LKK Auto)

From: ERGO Insurance Pte. Ltd. (Claims Department) <claims@ergo.com.sg>
Sent: Tuesday, 25 February 2020 5:23 PM
To: AIM PTE LTD; Admin-D (LKKAuto (admin-d@lkkauto.com)); Admin A (admin-a@lkkauto.com); Mei Kwan (LKKAuto (Meikwan@lkkauto.com))
Cc: Ivy Yong; Zheng Hanyang; Phoebe Xie
Subject: RE: FW: Claims ref no. (P) CDMCG20000344 NOA- SLA7594J // TP Claim

Date Classification : Confidential, C3

**** NOTE: Please create case, input our Claim ref no. and upload ALL survey related documents into Merimen. Payment invoices shall be ignored for cases that are not submitted via Merimen.**

Hi LKK,

Please conduct this survey request.

(Note: Survey vehicle only, LOD will be handled by Ergo)

Kindly inform us if you are not able to attend it.

Thank you.

Warmest Regards,
Pauline Soh
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five
Singapore 038965
DID : +65 6829 9194
pauline.soh@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: AIM PTE LTD <automim.claim@gmail.com>
Sent: Tuesday, 25 February 2020 5:22 pm
To: ERGO Insurance Pte. Ltd. (Claims Department) <claims@ergo.com.sg>
Cc: Ivy Yong <ivy.yong@ergo.com.sg>; Zheng Hanyang <hanyang.zheng@ergo.com.sg>; Phoebe Xie <phoebe.xie@ergo.com.sg>
Subject: Re: FW: Claims ref no. (P) CDMCG20000344 NOA- SLA7594J // TP Claim

Hi Pauline,

We would like to appoint surveyor from LKK to conduct survey.

Thank you.

Regards,
Jacyne

Automobile Integrated Management Pte Ltd (aim)

Office: 28 Sin Ming Lane #07-147 Midview City Singapore 573972

W/S: 23 Kaki Bukit Ave 4, Kaki Bukit Vicom #04-01 (South Wing) Singapore 415933

Tel: 91198371

On Tue, Feb 25, 2020 at 5:19 PM ERGO Insurance Pte. Ltd. (Claims Department) <claims@ergo.com.sg> wrote:

Date Classification : Confidential, C3

Dear Jacyne,

We would like to conduct a PRI survey, please refer to our list of surveyors :

1	AIS	Automobile Inspection Services Pte Ltd
2	FTA	FormTeam Consultancy Pte Ltd
3	IAS	Infiniti Appraisal Service
4	JPK	JP Knights Pte Ltd
5	LBS	L.B.S Auto Consultants Pte Ltd
6	LKK	LKK Auto Consultants Pte Ltd
7	PS	Priority Services
8	VAC	Vicom Ltd
9	AJAX	AJAX Inspection Services Pte Ltd
10	AA	Appraisal Associate

Warmest Regards,

Pauline Soh

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five

Singapore 038985

DID : +65 6829 9194

pauline.soh@ergo.com.sg

www.ergo.com.sg

ERGO

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: AIM PTE LTD <automim.claim@gmail.com>

Sent: Tuesday, 25 February 2020 11:43 am

To: ERGO Insurance Pte. Ltd. (Claims Department) <claims@ergo.com.sg>

Subject: NOA- SLA7594J // TP Claim

Hi,

Please refer attached to advise further.

Thank you.

Regards,

Jacyné

Automobile Integrated Management Pte Ltd (aim)

Office: 28 Sin Ming Lane #07-147 Midview City Singapore 573972

W/S: 23 Kaki Bukit Ave 4, Kaki Bukit Vicom #04-01 (South Wing) Singapore 415933

Tel: 91198371

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Foru



ALL-NEW
Mercedes-Benz GLE450 AMG
Premium Plus

TEST DRIVE TODAY!

☎ 6250 6696 / 9637 5329

Stream

Price Range ▼

Depreciation ▼

> 10 year(s) ▼

Vehicle Type ▼



Home » Used Cars » V-Kar Traders Pte Ltd » Honda Stream 1.8A (COE till 06/2023)

Honda Stream 1.8A (COE till 06/2023)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map

Price \$21,800

Depreciation ⓘ \$6,610 /yr

Reg Date

14-Jun-2008
(3yrs 3mths 18days COE left)

Mileage N.A.

Manufactured ⓘ

2008

Road Tax ⓘ \$1,174 /yr

Transmission

Auto

Dereg Value ⓘ \$12,493 as of today (change)

OMV ⓘ

\$20,643

COE ⓘ \$18,953

ARF ⓘ

\$20,643

Engine Cap 1,799 cc

Power

103.0 kW (138 bhp)

Curb Weight ⓘ 1,370 kg

No. of Owners ⓘ

4

Type of Vehicle MPV

Features

1.8L DOHC 16V I- VTEC Engine, Digital Climatic Aircon Controls, Knockdown Rear Seats, 7 Seater MPV. View specs of the Honda Stream (2007-2014)

Accessories

Leather Upholstery Seats, 17" Sports Rims With Brand New Michelin Tyres, Pioneer Touchscreen DVD Audio Systems With Reverse Camera, Fog Lamps.

Description

Servicing Done, Road Tax Till June. Buy With A Peace Of Mind. 100% Loan Available, High Trade In. Do Not Miss It, Whatsapp For An Appointment To View.

Category

COE Car

Status

Available

Resourc

Compare



Location Map

Shortlist

Compare

Report Error

More Action

Seller Information

V-Kar Traders Pte Ltd

5 vehicles for sale. 12 sold in past 3 m

📍 24 Sin Ming Lane #01-94

Midview City

Tel: 63341582

Search cars nearby

👤 Rendous

88%

Ray

96%

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

UNSW Sydney - World Top 50 Uni

Meet UNSW @ SG Sat Feb 29. Degree in Commerce, Law, Engr, Arts, Biomed

Stream

Price Range ▼

Depreciation ▼

> 10 year(r) ▼

Vehicle Type ▼



Home » Used Cars » Mayfair Motoring » Honda Stream 1.8A (COE till 08/2023)

Honda Stream 1.8A (COE till 08/2023)

Overview

Financial

Insurance

Accessories

Similar

Research

Photos

Map



Price \$25,800

Depreciation ⓘ \$7,350 /yr

Reg Date 26-Nov-2008
(3yrs 6mths 5days COE left)

Mileage 172,354 km (15.3k /yr)

Manufactured ⓘ 2008

Road Tax ⓘ \$1,174 /yr

Transmission Auto

Dereg Value ⓘ \$12,290 as of today (change)

OMV ⓘ \$23,116

COE ⓘ \$17,496

ARF ⓘ \$23,116

Engine Cap 1,799 cc

Power 103.0 kW (138 bhp)

Curb Weight ⓘ 1,370 kg

No. of Owners ⓘ 3

Type of Vehicle MPV

Features

Reliable 1.8L I-VTEC 16 Valves DOHC Engine, 5 Speed Auto Transmission. SRS Airbags, ABS. View specs of the Honda Stream (2007-2014)

Accessories

Leather Seats, Sport Rims, DVD Player, Reverse Camera, Reverse Sensors, Arm Rest, Solar Film, Remote Key Alarm System.

Description

Kah Motor Model. In Excellent Condition. Best MPV In Its Class. Must View To Appreciate. Loan From 3.18%. High Trade In Possible.

Category

COE Car, Premium Ad Car

Compare



Shortlist

Compare

Report Error

More Action

Seller Information

Mayfair Motoring

★ PREMIUM DEALER 2020 ★

47 vehicles for sale. 174 sold in past 12 months

61 Ubi Avenue 2 #05-11/16

Automobile Megamart

Tel: 64792220

Search cars nearby

David Tan

98%

Alex E

84%

Winston

87%

Kenny Toh

91%

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	193A
Vehicle Details	
Vehicle No.:	SLA7594J
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Feb 2020
Vehicle Make:	HONDA
Vehicle Model:	STREAM 1.8X A
Primary Colour:	Silver
Manufacturing Year:	2008
Engine No.:	R18A1769483
Chassis No.:	RN61062321
Maximum Power Output:	103.0 kW (138 bhp)
Open Market Value:	\$18,941.00
Original Registration Date:	13 Aug 2008
First Registration Date:	13 Aug 2008
Transfer Count:	2
Actual ARF Paid:	\$18,941.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jun 2023
COE Category:	B - Car (1601cc & above)
COE Period(Years):	5
PQP Paid:	\$18,953.00
COE Rebate Amount:	\$12,677.00
Total Rebate Amount:	\$12,677.00
Message	
Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 26 Feb 2020

OK

ESTIMATE

Our Ref: AC2020015/TP/SLA7594J-24.02.2020

Vehicle number: SLA7594J

Vehicle Made & Model: HONDA STREAM

Not Authorised
2/5/20
Sdms.
Take photo After my

Items	Qty	List Items	Amount \$
1	1	Front bonnet 638.90	Bul 816.90
2	1	Front bonnet lock 145.50	Tul 183.50
3	1	Front bonnet lock cable	11 89.60 X
4	1	Front bonnet seal - Inner	11 48.60 X
5	1	Front bonnet seal - Outer 35.00	ner 86.20
6	1	Front bonnet insulator	11 126.20 X
7	10	Front bonnet insulator clips @ 5.50	11 55.00 X
8	2	Front bonnet hinges - L/R @ 55.60	11 112.20 X
9	1	Front grille base 218.80	CRA 341.20
10	1	Front grille chrome moulding	Che 242.60
11	1	Front grille logo 38.50	ner 89.90
12	1	Front bumper 638.00	Del/Prn 683.60
13	1	Front bumper reinforcement 218.80	Bul 410.70
14	2	Front bumper side retainers - L/R @ 41.20 32.50 x 2 = 65	Bul 82.40
15	10	Front bumper clips @ 4.50 35.00	ner 45.00
16	2	Front fenders - L/R @ 581.40	nlra o/sue 1,162.80 12C
17	2	Front fender inner top garnishes @ 81.50	11 163.00 X
18	10	Front fender inner top garnish clips @ 5.50	11 55.00 X
19	2	Front headlamps - L/R @ 1082.60 780.35 x 2 = 1560.70	Cru 2,165.20
20	2	Front headlamp lower brackets - L/R @ 86.60 45 x 2 = 90	Cru 173.00
21	1	Front support panel	Bul 587.60
22	1	Front support top garnish	Del/Prn 110.20
23	10	Front support top garnish clips @ 4.50	11 45.00 X
24	1	Air con condenser	Bul/Prn 790.60
25	1	Air con electric fan assy	11 441.50 X
26	1	Radiator assy 1483.00	Bul/cru 1,586.90
27	1	Radiator electric fan assy	11 481.60 X
28	1	Radiator top hose	11 86.60 X
29	1	Radiator spare tank	11 126.60 X
Sub-total			11,389.20
Less 20%			2,277.84
Total List			9,111.36

L/K Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To inspect damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No 40% concession(s) is allowed
- So (temporary items) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7479.60
20%
5983.68

Special Nett Items

- 30 1 set Front no. plate
31 1 bot Air con oil
32 1 bot Radiator coolant

SCN 60.00 40
11 65.00 X
M 60.00 30

Total Special Nett 185.00

Labour charges

- 33 To check front electrical wiring
35 To remove, refix A/C condenser & refill A/C gas
36 To respray undercoating
37 To respray painting and etc
38 Panel beating, cut, weld remove & replacing above parts

50.00 30

180.00 100

120.00 80

1,200.00 900

1,200.00 600

Total Labour 2,850.00

2750

12046.36

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

12,146.36

7763.68

6210.94

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI20003208/UYD3N2
Date: 05/03/2020

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No: DMCG19010513
Claimant Vehicle No : SLA7594J **Insured Vehicle No :** YP7991M
 Date of Loss: 24/02/2020 Nature of Claim: TP Claim No: CDMCG20000344

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLA7594J**
 Make & Model: HONDA STREAM, 1.8 X (A) Engine No: R18A1769483
 Reg. Date: 13/08/2008 (Man. Year: 2008) Chassis No: RN61062321
 Colour: Silver Odometer: 196155 km
 Engine Capacity: 1799 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,296.36	6,053.68	3,242.68	34.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,750.00	1,710.00	1,040.00	37.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,046.36	7,763.68	4,282.68	35.55
Approved Total (Overridden) (S\$)		6,200.00		
(S\$)	12,046.36	6,200.00	5,846.36	48.53
+ GST 7.00/7.00% (S\$)	843.25	434.00	409.25	48.53
Nett Amount (S\$)	12,889.61	6,634.00	6,255.61	48.53

INSPECTION

Date of Assignment: 25/02/2020
 Date Inspected: 26/02/2020 Inspected At: Automobile Integrated Management Pte Ltd (HQ)
 23 Kaki Bukit Ave 4 #04-01, Kaki Bukit (South Wing)
 Singapore 415933
 Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Mar 2020)
Parts:	M1-MPV	HONDA STREAM 1.8 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLA7594J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Buckled	816.90 FL	*638.90 FL
2	1		*FRONT BONNET LOCK	Twisted	183.50 FL	*145.50 FL
3	1		*FRONT BONNET LOCK CABLE	Not Necessary	89.60 FL	*- FL
4	1		*FRONT BONNET SEAL-INNER	Not Necessary	48.60 FL	*- FL
5	1		*FRONT BONNET SEAL-OUTER	Necessary	86.20 FL	*35.00 FL
6	1		*FRONT BONNET INSULATOR	Not Necessary	126.20 FL	*- FL
7	10		*FRONT BONNET INSULATOR CLIPS	Not Necessary	55.00 FL	*- FL
8	2		*FRONT BONNET HINGES-L/R	Not Necessary	112.20 FL	*- FL
9	1		*FRONT GRILLE BASE	Cracked	341.20 FL	*218.80 FL
10	1		*FRONT GRILLE CHROME MOULDING	Cracked	242.60 FL	*242.60 FL
11	1		*FRONT GRILLE LOGO	Necessary	89.90 FL	*38.50 FL
12	1		*FRONT BUMPER	Deformed/Torn	683.60 FL	*638.00 FL
13	1		*FRONT BUMPER REINFORCEMENT	Necessary	410.70 FL	*218.80 FL
14	2		*FRONT BUMPER SIDE RETAINERS-L/R	Bent	82.40 FL	*65.00 FL
15	10		*FRONT BUMPER CLIPS	Necessary	45.00 FL	*35.00 FL
16	1		*FRONT FENDERS-L/R	O/s Buckled/N/s Repair	1,162.80 FL	*581.40 FL
17	2		*FRONT FENDER INNER TOP GARNISHES	Not Necessary	163.00 FL	*- FL
18	10		*FRONT FENDER INNER TOP GARNISH CLIPS	Not Necessary	55.00 FL	*- FL
19	2		*FRONT HEADLAMPS-L/R	Cracked	2,165.20 FL	*1,560.70 FL
20	2		*FRONT HEADLAMP LOWER BRACKETS-L/R	Cracked	173.00 FL	*90.00 FL
21	1		*FRONT SUPPORT PANEL	Bent	587.60 FL	*587.60 FL
22	1		*FRONT SUPPORT TOP GARNISH	Deformed/Torn	110.20 FL	*110.20 FL
23	10		*FRONT SUPPORT TOP GARNISH CLIPS	Not Necessary	45.00 FL	*- FL
24	1		*AIR CON CONDENSER	Bent/Punctured	790.60 FL	*790.60 FL
25	1		*AIR CON ELECTRIC FAN ASSY	Not Necessary	441.50 FL	*- FL
26	1		*RADIATOR ASSY	Bent/Cracked	1,586.90 FL	*1,483.00 FL
27	1		*RADIATOR ELECTRIC FAN ASSY	Not Necessary	481.60 FL	*- FL
28	1		*RADIATOR TOP HOSE	Not Necessary	86.60 FL	*- FL
29	1		*RADIATOR SPARE TANK	Not Necessary	126.60 FL	*- FL
30	1		*SET FRONT NO PLATE	Scratched	60.00 FS	*40.00 FS
31	1		*BOT AIR CON OIL	Not Necessary	65.00 FS	*- FS
32	1		*BOT RADIATOR COOLANT	Necessary	60.00 FS	*30.00 FS

F=Franchise part, S=SpcNett, L=ListItemDisc.

Sub Total (S\$)	11,574.20	7,549.60
- List Item Discount on L Items 20.00/20.00% (S\$)	2,277.84	1,495.92
Total Parts (S\$)	9,296.36	6,053.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK FRONT ELECTRICAL WIRING	New	50.00	30.00
2	TO REMOVE,REFIX A/C CONDENSER & REFILL A/C GAS	New	180.00	100.00
3	TO RESPRAY UNDERCOATING	New	120.00	80.00
4	TO RESPRAY PAINTING AND ETC	New	1,200.00	900.00
5	PANEL BEATING,CUT,WELD,REMOVE & REPLACING ABOVE PARTS	New	1,200.00	600.00
Gross Labour Cost (S\$)			2,750.00	1,710.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >