

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5669C**AAD2002-156***Not Authorized
L/Sing @ 1550h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

25 FEB 2020

SHC 5669C

VF1ABL15AUC281155

RENAULT

LATITUDE

23.2.2020

AIG

24/12/2014

PART		LIST	
1	BUMPER COVER REAR	\$ Bu	561.70 ✓
1	BUMPER LOWER REAR	\$ Nd/Ln	411.90 ✓
1	BUMPER BRACKET CTR REAR	\$ Ln	98.10
1	BUMPER BRACKET SIDE RH REAR	\$ Ln	82.10
1	BUMPER RETAINER RH REAR	\$ Ln	59.80
1	BUMPER BRACKET SIDE LH REAR	\$ Ln	80.80
1	BUMPER RETAINER LH REAR	\$ Ln	54.20
1	BUMPER REFLECTOR LH	\$ Ln	16.60
1	BUMPER BEAM REAR	\$ N	547.80
1	BUMPER BEAM BRACKET LH REAR	\$ N	114.50
1	BUMPER BEAM BRACKET RH REAR	\$ N	100.90
1	OUTER PANEL REAR (End Panel)	\$ N	745.80
1	OUTER PANEL REAR (End Panel) TRIM	\$ Ln	404.56
1	TAILLAMP PANEL LH	\$ N	401.40
1	TAILLAMP LH	\$ Ln	401.40
1	BOOT REAR	\$ N	1,677.20
1	BOOT FINISHER	\$ Ln	344.70
1	BOOT WHEATERSTRIP	\$ Ln	178.20
1	BOOT REFLECTOR LAMP LH	\$ Ln	277.70
1	BOOT REFLECTOR LAMP RH	\$ Ln	277.70
1	BOOT BADGE 'RENAULT'	\$ Nn	82.40
1	BOOT BADGE	\$ Nn	95.80
1	BOOT INNER TRIM BOARD	\$ Ln	611.00
TOTAL		\$	7,626.26
10%		\$	762.63
		\$	6,863.63

Trans-cab Auto Services Pte Ltd**AAD2002-156**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5669C**Special Nett**

1SET PARKING AID	\$	Shat	700.00	400.00
1SET REAR BUMPER CLIP	\$	na	66.00	—
1SET BUMPER BRACKET CTR CLIP	\$	na	33.00	—
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
1SET BUMPER RETAINER RH CLIP RR	\$	na	20.00	X
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	na	10.00	X
1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
1 BOOT STICKER "Trans-cab"	\$	na	30.00	X
1 BOOT STICKER "6555-3333"	\$	na	30.00	X
1SET BOOT FINISHER CLIP	\$	na	24.20	X
1 TAILLAMP CLIP LH	\$	na	5.00	X
1 Rear Bumper Protector	\$	na	100.00	30.00
TOTAL	\$		1,136.20	
TOTAL PARTS	\$		7,999.83	

LABOUR

To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	na	170.00	X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	na	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00	X
To check steering geometry and computer wheel alignment	\$	na	220.00	X
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	na	380.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5669C**AAD2002-156**

To Rust-Proofing Of The Affected Areas.	\$	170.00	X
To transfer of tire, rim and on wheel balancing.	\$	170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	2001
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	X
To reinstall rear bumper parking sensor.	\$	170.00	601
Putty and spray painting of the affected portion.	\$	6,000.00	229
To Check Electrical Lighting Concerned.	\$	170.00	101
TOTAL	\$	14,170.00	
Over All Total	\$	22,169.83	

LUMP SUM (REPAIR DAY)**20 DAYS****2 days**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: