

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5669C**

**AAD2002-156**

*Not Authorized  
L/Smp @ 1550h*

Vehicle No.:  
Chassis No.:  
Vehicle Make:  
Vehicle Model:  
Date of Accident :  
Third Party Insurer :  
Date of Registration :

25 FEB 2020

**SHC 5669C**

VF1ABL15AUC281155

RENAULT

LATITUDE

23.2.2020

**AIG**

24/12/2014

PART	LIST		
1 BUMPER COVER REAR	\$ Bu	561.70	✓
1 BUMPER LOWER REAR	\$ Ad/Ln	411.90	✓
1 BUMPER BRACKET CTR REAR	\$ Sn	98.10	} X
1 BUMPER BRACKET SIDE RH REAR	\$ Sn	82.10	
1 BUMPER RETAINER RH REAR	\$ Sn	59.80	
1 BUMPER BRACKET SIDE LH REAR	\$ Sn	80.80	
1 BUMPER RETAINER LH REAR	\$ Sn	54.20	
1 BUMPER REFLECTOR LH	\$ Sn	16.60	
1 BUMPER BEAM REAR	\$ N	547.80	
1 BUMPER BEAM BRACKET LH REAR	\$ N	114.50	
1 BUMPER BEAM BRACKET RH REAR	\$ N	100.90	
1 OUTER PANEL REAR (End Panel)	\$ N	745.80	
1 OUTER PANEL REAR (End Panel) TRIM	\$ Sn	404.56	
1 TAILLAMP PANEL LH	\$ R	401.40	
1 TAILLAMP LH	\$ Sn	401.40	
1 BOOT REAR	\$ N	1,677.20	
1 BOOT FINISHER	\$ Sn	344.70	
1 BOOT WHEATERSTRIP	\$ Sn	178.20	
1 BOOT REFLECTOR LAMP LH	\$ Sn	277.70	
1 BOOT REFLECTOR LAMP RH	\$ Sn	277.70	
1 BOOT BADGE 'RENAULT'	\$ Nn	82.40	
1 BOOT BADGE	\$ Nn	95.80	
1 BOOT INNER TRIM BOARD	\$ Sn	611.00	
<b>TOTAL</b>	<b>\$</b>	<b>7,626.26</b>	
<b>10%</b>	<b>\$</b>	<b>762.63</b>	
	<b>\$</b>	<b>6,863.63</b>	

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5669C****AAD2002-156****Special Nett**

1SET PARKING AID	\$	<i>Shat</i> 700.00	<i>4000sn</i>
1SET REAR BUMPER CLIP	\$	<i>na</i> 66.00	<i>—</i>
1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00	<i>—</i>
1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00	<i>X</i>
1SET BUMPER RETAINER RH CLIP RR	\$	<i>na</i> 20.00	<i>X</i>
1SET BUMPER BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00	<i>X</i>
1SET BUMPER RETAINER CLIP LH RR	\$	<i>na</i> 20.00	<i>X</i>
1SET BUMPER LOWER REAR RIVET	\$	<i>na</i> 22.00	<i>X</i>
1SET BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00	<i>✓</i>
1 BOOT STICKER "Trans-cab"	\$	<i>na</i> 30.00	<i>X</i>
1 BOOT STICKER "6555-3333"	\$	<i>na</i> 30.00	<i>X</i>
1SET BOOT FINISHER CLIP	\$	<i>na</i> 24.20	<i>X</i>
1 TAILLAMP CLIP LH	\$	<i>na</i> 5.00	<i>X</i>
1 Rear Bumper Protector	\$	<i>na</i> 100.00	<i>300sn</i>
<b>TOTAL</b>	<b>\$</b>	<b>1,136.20</b>	
<b>TOTAL PARTS</b>	<b>\$</b>	<b>7,999.83</b>	

**LABOUR**

To transfer of rear bumper fittings, attachment and perform water seepage test.	\$	<i>na</i> 170.00	<i>X</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	<i>↳</i> 170.00	<i>X</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>↳</i> 380.00	<i>X</i>
To check steering geometry and computer wheel alignment	\$	<i>↳</i> 220.00	<i>X</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>↳</i> 380.00	<i>X</i>

**Trans-cab Auto Services Pte Ltd**

**AAD2002-156**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHC 5669C**

To Rust-Proofing Of The Affected Areas.	\$	<i>nu</i> 170.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>u</i> 170.00	<i>X</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	6,000.00	<i>2001</i>
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>u</i> 170.00	<i>X</i>
To reinstall rear bumper parking sensor.	\$	170.00	<i>601</i>
Putty and spray painting of the affected portion.	\$	6,000.00	<i>2201</i>
To Check Electrical Lighting Concerned.	\$	170.00	<i>101</i>
<b>TOTAL</b>	<b>\$</b>	<b>14,170.00</b>	
<b>Over All Total</b>	<b>\$</b>	<b>22,169.83</b>	

**LUMP SUM ( REPAIR DAY)**

*20 DAYS*

*2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: