

ASS. REC. BY:

REF: CS/MSG20003224/UTF3/172
Special Instruction:Survivor: MARCUS ASSIGNMENT (Office)From (Person): Koh Ming Shao of MSG Date/Time: 26.2.2020 1544p.u

Estimated Cost: _____ Bill to: _____

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SJZ 3260R Insured: SME 9016Jat Workshop m/s ASA Motorsports Tel: 67493811of 37A EVLHPolicy No: 29141314MEF Claim No: 620622

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 25/2/2020
(Client's Record)

CA / REV / REP. / REV 24 HRS

Date/Time: 26.2.2020 404p.u Person Contacted: LOU H.O.D. Endorsement: _____Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate Inspection
	15 kati Bukit Road 4 # 01-53
	SJZ 3260R - NM / INC 20003182/24 Don - 26/02/2020
	SME 9016J - NM / INC 20003182/24 Don - 26/02/2020
28/2	Sent via menimen pending estimate

ASS. REC. BY:

REF: MS16

ASSIGNMENT

From:

Date: 27.2.2020

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SJZ 3260R

at Workshop m/s Asia Motorsports

of 15 kaki Bukit Road 4 #01-53

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: 16500

BAC Accident Report: Consistent? : Yes or No

GLA / PR Seen: 2 Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Nett 4973

Veh No:

SJZ 3260R

Yr Regn:

15/10/10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

Honda city

C.C.

1497

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

246087

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

MRH6M267099020456

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55-R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

GST

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

25/2/20

D.O.I.

27/2/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear - 2 Fl.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

9/3/20

17A 011527 to 1800hrs. Nett 4973

1/5 4800 cont. with AM lorry (Cred: 16652.72: 11%)

9/3/2020

RECEIVED 9 MAR 2020

Date/Time, File Pass to?

1) 9/3 Typist

Date/Time, File Return to?

2)

Rep. Form:

Lump Sum / L.B.: 4800

☐ : Preli. Report
☒ : Final Report

Days Of Repair: 10

Resurvey No. of Trip:

Add Fee:

☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

200

11

211

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Feb 2020 14:30		26 Feb 2020 15:44 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	GRAB RENTALS PTE. LTD., Co. Reg. No.: 201617200G		
Main Claimant:	AUTO ALLIANCE LEASING PTE LTD, Co. Reg. No.: 201903807W		
Vehicle Reg. No.:	SJZ3260R	Date of Loss:	25/02/2020 10:00 - :59 [111 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	29141714MKF (Comprehensive) Coverage: 01/02/2020 - 31/12/2020
Vehicle Reg. No. (Insured):	SMK9016J	Policy No. (Claimant):	
		Excess:	
Repairer:	Asia Motorsports Solution Pte Ltd (HQ) 37A Everitt, 428586 Joo Chiat - Tel:		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Koh Ming Shao - 6594 2546]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 27/02/2020]		
Driver/Custodian (Insured):	CHUA SOON BEE (/ Male) , NRIC: S1369603I Email:		
Adj Asg. Remarks:	on WP, OI:Grab, Liab: clear, Agree on SJE, Assign: Marcus Chua from LKK Auto Consultants Pte Ltd. Contact: 6745 3811.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

View Sent Message

This mail is associated with :

***SJZ3260R (620622)
[SMK9016J]**

TP

AUTO ALLIANCE LEASING PTE LTD

Feb 25 2020 10:00AM

[GRAB RENTALS PTE. LTD.]

Asia Motorsports Solution Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on 28/02/2020 10:38 AM.
To mingshao_koh@sg.msig-asia.com
Subject *SJZ3260R (620622) [SMK9016J] TP

Dear Sir/Madam,

Please be informed that we have inspected the vehicle SJZ 3260R on 27/2/2020.
We are pending estimate from repairer.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sun@lkkauto.com | fax: 6256-4315

Bik 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

DOCUMENTS SUMMARY

There are no documents.



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

[Find out more](#)



Post an Advertisement

Sell it yourself! Advertise it at just **\$58 until it's SOLD!**

Post an AdAdvertiser LoginWays of Selling

Mercedes Benz E250 Cabriolet CGI A At \$71,800



High Loan Available, With 10 Years COE, Sell \$107,000
StarAd



Browse by Category

Sort by Date Posted20 results/page

3 vehicles

city

Advanced Search Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	city		Any	Any	2010	Any	Any	Any	Available
	Honda	City 1.5A LX VTEC (New 5-yr COE)	\$34,800	\$6,950 /yr	08-Feb-2010	1,497 cc	117,000 km	Sedan	Available
Lowest Price In Market, No More Worries About Transfer Of Ownership, Immediate Transfer Can Be Done When You Collect The Vehicle...									
Posted: 17-Feb-2020 Tags: 2010 Honda City, Honda City, Honda, City									
	Honda	City 1.5A LX VTEC	\$19,800	\$13,390 /yr	08-Dec-2010	1,497 cc	-	Sedan	Available
Highly Sought Out City With Good Power And Fuel Efficient. Easy On Maintenance And Spacious. High Trade In/Loan Available! Call Now!									
Posted: 09-Feb-2020 Tags: 2010 Honda City, Honda City, Honda, City									
	Honda	City 1.5A LX VTEC	\$17,800	N/A	12-Aug-2010	1,497 cc	121,000 km	Sedan	Available
Trade-In Welcome, Bank And In House Loan All Available. Interested Please Call For Viewing, Viewing By Appointment Only.									
Boeki Auto Pte Ltd									
Posted: 06-Feb-2020 Tags: 2010 Honda City, Honda City, Honda, City									

Save this search criteria, to get email alerts whenever a match is found.

MakeModelPriceDepreciationReg DateEng CapMileageVeh TypeStatus

For old advertisements, view Expired ads20 results/page

SG Mobile Platform/App Winner

Trade Over 100 Instruments, Including Currency Pairs, Indices, Commodities, Bonds & Metals OANDA

SIGN UP

city

Price Range

Depreciation

2010

Vehicle Type

Submit

Advanced Search

Home > Used Cars > William Lee Car Aircon Engineering > Honda City 1.5A LX VTEC

Honda City 1.5A LX VTEC

- Overview
- Financial
- Insurance
- Accessories
- Similar
- Research
- Photos
- Map

Price	\$19,800		
Depreciation	\$13,390 /yr View models with similar depre	Reg Date	08-Dec-2010 (9mths 10days COE left)
Mileage	N.A.	Manufactured	2009
Road Tax	\$684 /yr	Transmission	Auto
Dereg Value	\$12,412 as of today (change)	OMV	\$18,755
COE	\$39,000	ARF	\$18,755
Engine Cap	1,497 cc	Power	88.0 kW (118 bhp)
Curb Weight	1,150 kg	No. of Owners	4
Type of Vehicle	Mid-Sized Sedan		

Features
1.5L Vtec Engine, 5 Speed Automatic Transmission, 118hp. [View specs of the Honda City \(2006-2014\)](#)

Accessories
Factory Fitted Audio With USB/AUX, Paddle Shift Steering, Rear Knock Down Seats, 4 Disc Brakes, Sport Rims, Solar Film.

Description
Highly Sought Out City With Good Power And Fuel Efficient. Easy On Maintenance And Spacious. High Trade In/Loan Available! Call Now!

Category
PARF Car

Status
Available

Resources

 **Vehicle Evaluation**
Afraid of lemons? Request to have this car evaluated professionally. [Find out more.](#)

 **Car Valuation - Free**
Find out the market value of your existing car for free. [Get started](#)



- Shortlist
- Report Error
- Compare
- More Actions
- Add note

Seller Information

William Lee Car Aircon Engineering

26 vehicles for sale. 16 sold in past 3 mths

 61 Ubi Avenue 2 #08-04B
Automobile Megamart
Tel: 63821006
[Search cars nearby](#)

 Keith Lim	98290368 
Peng	86666566 
Erik Lee	96812139 
Ben	98274488 

Posted on: 09-Feb-2020 | Last Updated on: 25-Feb-2020

Upfront Payment [+ more Financial info](#)

Transfer Fee \$25

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 807W

Vehicle Details

Vehicle No.: SJZ3260R

Vehicle to be Exported: No

Intended Deregistration Date: 28 Feb 2020

Vehicle Make: HONDA

Vehicle Model: HONDA CITY LX 1.5 I-VTEC AUTO

Primary Colour: Black

Manufacturing Year: 2009

Engine No.: L15A71811105

Chassis No.: MRHGM26709P020456

Maximum Power Output: 88.0 kW (118 bhp)

Open Market Value: \$18,428.00

Original Registration Date: 15 Nov 2010

First Registration Date: 15 Nov 2010

Transfer Count: 1

Actual ARF Paid: \$18,428.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 14 Nov 2020

PARF Rebate Amount: \$9,214.00

Intended COE Rebate Details

COE Expiry Date: 14 Nov 2020

COE Category: A - Car (1600cc & below)

COE Period(Years): 10

QP Paid: \$32,415.00

COE Rebate Amount: \$2,313.00

Total Rebate Amount: \$11,527.00

The information contained herein is correct as at 27 Feb 2020

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/02/2020 09:23
Date Of Accident	25/02/2020 10:20
Exact Location Of Accident	AYE TWDS TUAS BEFORE MERCHANT RD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJZ3260R
Insured/Policyholder	
Name Of Registered Owner	AUTO ALLIANCE LEASING PTE LTD
Co Reg No	2XXXXX807W
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-83396986
Alternative Phone No	OFFICE-83396986

Vehicle Particulars

Manufacturer	HONDA
Model	HONDA CITY LX 1.5 I-VTEC AUTO
Exact Purpose for which vehicle was being used at time of accident	WORKING
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5110688602
Cover Note Number	

Driver

Name of Driver	LIM WEE KEONG (LIN WEIQIANG)
NRIC No	SXXXX050Z
Date Of Birth	17/12/1975
Occupation	OUTDOOR
Date Of Driving Pass	12/06/1998
Driving Experience	21 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-81235588
Fax Number	
Contact Number	OFFICE-81235588
Email Address	NOEMAIL

Address	BLK 170 YISHUN AVENUE 7 #14-869
Postcode	760170
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	4
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: - GENDER: FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO STATEMENT.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number	SMK9016J
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SGH3156P
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SGK9902Y
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name LIM WEE KEONG (LIN WEIQIANG)
Approximate Age
Injuries Sustain NECK
Injured person in which vehicle? SJZ3260R
Were seat belts worn? YES
Was this injured conveyed to hospital by ambulance? NO
Address
Postcode

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to re-evaluate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodging of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time


Driver's Signature
(If driver is not the policyholder)
Date & Time


Reporting Centre Person's Signature
Name
NRIC/ID No.

Accident Sketch Plan

SKETCH PLAN

page 2 of sketch plan

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

order to payment

DECLARATION

(We declare the following particulars are true in every respect)


Policyholder's Signature
Date & Time




Driver's Signature
(If driver is not the policyholder)
Date & Time



Reporting Centre Personnel's Signature
Name
NIC/PIN No.

Accident Sketch Plan

司机 81235588
QJ. 租 83396986

25/2/2020
10:20 AM

SSZ 3260 R



Accident Sketch Plan

ON STATED DATE AND TIME, I WAS TRAVELLING ALONG THE STATED VENUE. FRONT VEHICLE BRAKE, I BRAKE MY VEHICLE AS WELL. SUDDENLY I FELT AN IMPACT OF MY VEHICLE AND REALIZED THAT VEHICLE B HIT ONTO MY VEHICLE REAR PORTION. AFTER AN IMPACT, MY VEHICLE MOVED FORWARD AND HIT ONTO VEHICLE C REAR PORTION. THERE WERE 4 VEHICLES INVOLVED IN THIS ACCIDENT.

HSC

Not Authorized

2/5 4800
27/2/20

Page No. 1

10 days
10 days

VEHICLE NO. SJZ 3260R

HONDA CITY

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$)	SURVEYOR'S ADJUSTMENT
	PARTS (LIST ITEMS)			
1	Bonnet 406.10		BUC 1245.00	/
1	Bonnet Lock 87.70		twi 238.00	/
2	Bonnet Hinges @ \$48.00		bet 96.00	/
1	Bonnet Insulator 40.40		de 152.00	/
14	Bonnet Insulator Clips @\$2.10		17 29.40	X
1	Front Support Panel 337.80		bet 657.00	/
1	Front Radiator Grille 180.60		cm 372.00	/
1	Front Grille Logo		del 22.50	/
8	Front Grille Clips @ \$3.50		17 28.00	X
1	LHS Front Fender LHS 270.60		BUC 780.00	/
1	LHS Front Fender inner shield	REFIX	17 0.00	X
1	LHS Front Door	REPAIR	17 0.00	X
1	Front Fender RHS	REPAIR	17 0.00	X
1	Front Bumper 406.20		DUS 1152.00	/
1	Front Bumper under cover		17 480.00	X
2	Front Bumper Foglamp garnish @\$110		17 220.00	X
2	Front Bumper Foglamp @\$348.00		17 696.00	X
1	Front Bumper Grille		17 782.00	X
2	Front Bumper Retainer RH & LH @ \$40.00		17 80.00	X
1	Front Bumper reinforcement		17 450.00	X
1	Radiator		bet/cm 650.00	/
1	Radiator hose		17 120.00	X
1	Air con condensor 394.80		bet/pur 780.00	/
2	Air con condensor pipe		17 250.00	X
1	Air con fan motor w/cowling		17 324.00	X
2	Head Lamp RHS & LHS @ 782.50 324.10 X 2 = 648.20		cm 1565.00	/
2	Head Lamp Lower Bracket RHS & LHS @122.00		17 244.00	X
1	Front engine manifold		17 980.00	X
1	Air filter box		17 352.00	X
		PARTS C/F	12744.90	

VEHICLE NO. SJZ 3260R

HONDA CITY

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
	PARTS (LIST ITEMS)	PARTS B/F	12744.90	
1	Rear bootlid	480.60	oo/suc 1276.00	/
1	Rear bootlid Honda badge	28.50	nu 62.00	/
1	Rear bootlid IVTEC emblem	32.70	nu 72.00	/
1	Rear bootlid CITY emblem	30.60	nu 48.00	/
1	Rear bootlid centre chrome garnish		11 298.00	X
2	Rear bootlid hinges @78.60		11 157.20	X
1	Rear bootlid inner lock		8u 285.30	X
1	Rear bootlid inner lock catch		11 48.00	X
1	Rear bootlid inner trim		11 198.00	X
1	Rear boot edge weatherstrip	89.70	7u 142.00	/
2	Rear bootlid rubber stopper @48.20		11 96.40	X
1	Rear bootlid lock actuator		11 238.00	X
1	RHS Rear door	REPAIR	2 0.00	X
1	RHS Rear fender @780		2 780.00	X
1	LHS Rear fender	REPAIR	11 0.00	X
1	RHS Rear fender inner trim		11 298.20	X
1	RHS Rear fender inner splash shield		11 198.00	X
1	RHS Rear fender air vent		11 98.00	X
1	Rear bumper	404.20	D15 1164.00	/
2	Rear bumper side retainers	25.20	o/sent 128.00	IPC
1	Rear bumper reinforcement		15 580.00	X
1	Rear end panel	316.00	body 782.00	/
1	Rear end panel top garnish		11 289.00	X
1 set	Rear end panel top garnish clips		11 26.00	X
2	RHS & LHS Taillamps @978.20	284.20	o/sent 1956.40	IPC
2	RHS & LHS Taillamps panel @258.00		2 516.00	X
1	Exhaust silencer assembly		11 950.00	X
1	Exhaust silencer heat shield		11 254.00	X
4	Exhaust silencer mountings		11 96.00	X
1	Rear spare tyre panel top cover		11 298.00	X
1	Rear spare tyre panel		2 1182.00	X
1	Rear spare tyre panel top board		11 242.00	X
			25503.40	
		less	20%	20%
			5100.68	
			20402.72	
		PARTS C/F	20402.72	

5233.6
20%
4186.88

VEHICLE NO. SJZ 3260R

HONDA CITY

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYORS ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>	PARTS B/F	20402.72	
	<u>SPECIAL NETT ITEMS</u>			
1set	Reverse sensor		<i>shorted</i> 280.00	<i>200</i>
1	Reverse camera	REFIX	<i>17</i> 0.00	<i>X</i>
1	Rear end panel sealant		<i>rec</i> 120.00	<i>50</i>
1	Rear number plate w/holder		<i>17</i> 75.00	<i>X</i>
1	Front number plate w/holder		<i>sent</i> 75.00	<i>40</i>
2	Rear number plate lamps @72.00	REFIX	<i>17</i> 0.00	<i>X</i>
1	Rear bootlid inner trim clips		<i>17</i> 60.00	<i>X</i>
1set	Rear bumper clips		<i>rec</i> 60.00	<i>30</i>
1	Spare tyre panel insulator		<i>17</i> 140.00	<i>X</i>
1	Radiator coolant		<i>rec</i> 40.00	<i>30</i>
1	Rear windscreen sealant		<i>17</i> 100.00	<i>X</i>
1	Rear spare tyre panel sealant		<i>17</i> 100.00	<i>X</i>
		TOTAL PARTS	21452.72	

VEHICLE NO. SJZ 3260R HONDA CITY

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYORS ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas; replace the damaged parts and components. (FRONT AND REAR)	2400.00 -	1500
2	To supply paint materials, expandable items & putty, respray paint on parts replaced and repaired areas (FRONT AND REAR)	1800.00 -	1680
3	To remove and check and refix wiring at damaged areas	200.00 -	30
4	To perform anti rust treatment on affected areas	210.00 -	100
5	To remove and refix/replace inner trims, garnish and rear cushion seats etc. to facilitate repairs (rear)	250.00 -	80
6	To remove and replace rear exhaust silencer assembly	250.00 57 X	X
7	To remove and refix rear windscreen	140.00 11 X	X
8	To remove and replace air con condensor, vacuum and refill gas	150.00 -	100
9	To remove and replace radiator, pressure test and refill coolant	120.00 -	110
10	To remove and replace reverse sensors and test for proper function	120.00 -	40
Labour Total :		5640.00	
TOTAL (PARTS & LABOUR):		27092.72	8066.88 615.7

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20003224/UTF3N2
Date: 12/03/2020

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29141714
Claimant Vehicle No :	SJZ3260R	Insured Vehicle No :	SMK9016J
Date of Loss:	25/02/2020	Nature of Claim:	TP
		Claim No:	620622

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJZ3260R	Engine No:	L15A71811105
Make & Model:	HONDA CITY, 1.5 CVT (A)	Chassis No:	MRHGM26709P020456
Reg. Date:	15/11/2010 (Man. Year: 2009)	Odometer:	246097 km
Colour:	Black		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	GST 6 mm	Rear Left Side:	GST 6 mm
Front Right Side:	GST 6 mm	Rear Right Side:	GST 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,452.72	4,536.88	16,915.84	78.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,640.00	3,530.00	2,110.00	37.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	27,092.72	8,066.88	19,025.84	70.22
Approved Total (Overridden) (S\$)		4,800.00		
Nett Amount (S\$)	27,092.72	4,800.00	22,292.72	82.28

INSPECTION

Date of Assignment:	26/02/2020	
Date Inspected:	27/02/2020	Inspected At: 15 Kaki Bukit Road 4 #01-53 Repairer: Asia Motorsports Solution Pte Ltd
Estimated Period of Repair:	10.0 days	

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 12 Mar 2020)
Parts:	143	HONDA CITY 1.5 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJZ3260R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Buckled	1,245.00 FL	*406.10 FL
2	1		*BONNET LOCK	Twisted	238.00 FL	*87.70 FL
3	2		*BONNET HINGES	Bent	96.00 FL	*96.00 FL
4	1		*BONNET INSULATOR	Deformed	152.00 FL	*40.40 FL
5	14		*BONNET INSULATOR CLIPS	Not Necessary	29.40 FL	*- FL
6	1		*FRONT SUPPORT PANEL	Bent	657.00 FL	*337.80 FL
7	1		*FRONT RADIATOR GRILLE	Cracked	372.00 FL	*180.60 FL
8	1		*FRONT GRILLE LOGO	Necessary	22.50 FL	*22.50 FL
9	8		*FRONT GRILLE CLIPS	Not Necessary	28.00 FL	*- FL
10	1		*LHS FRONT FENDER LHS	Buckled	780.00 FL	*270.60 FL
11	1		*LHS FRONT FENDER INNER SHIELD (NPA)	Not Necessary	0.00 FL	*- FL
12	1		*LHS FRONT DOOR (NPA)	Repair	0.00 FL	*- FL
13	1		*FRONT FENDER RHS (NPA)	Repair	0.00 FL	*- FL
14	1		*FRONT BUMPER	Distorted	1,152.00 FL	*406.20 FL
15	1		*FRONT BUMPER UNDER COVER	Not Necessary	480.00 FL	*- FL
16	2		*FRONT BUMPER FOGLAMP GARNISH	Not Necessary	220.00 FL	*- FL
17	2		*FRONT BUMPER FOGLAMP	Not Necessary	696.00 FL	*- FL
18	1		*FRONT BUMPER GRILLE	Not Necessary	782.00 FL	*- FL
19	2		*FRONT BUMPER RETAINER RH & LH	Not Necessary	80.00 FL	*- FL
20	1		*FRONT BUMPER REINFORCEMENT	Repair	450.00 FL	*- FL
21	1		*RADIATOR	Bent/Cracked	650.00 FL	*650.00 FL
22	1		*RADIATOR HOSE	Not Necessary	120.00 FL	*- FL
23	1		*AIR CON CONDENSOR	Bent/Punctured	780.00 FL	*394.80 FL
24	2		*AIR CON CONDENSOR PIPE	Not Necessary	250.00 FL	*- FL
25	1		*AIR CON FAN MOTOR W/COWLING	Not Necessary	324.00 FL	*- FL
26	2		*HEAD LAMP RHS & LHS	Cracked	1,565.00 FL	*648.20 FL
27	2		*HEAD LAMP LOWER BRACKET RHS & LHS	Not Necessary	244.00 FL	*- FL
28	1		*FRONT ENGINE MANIFOLD	Not Necessary	980.00 FL	*- FL
29	1		*AIR FILTER BOX	Not Necessary	352.00 FL	*- FL
30	1		*REAR BOOTLID	Dented/Buckled	1,276.00 FL	*480.60 FL
31	1		*REAR BOOTLID HONDA BADGE	Necessary	62.00 FL	*28.50 FL
32	1		*REAR BOOTLID IVTEC EMBLEM	Necessary	72.00 FL	*32.70 FL
33	1		*REAR BOOTLID CITY EMBLEM	Necessary	48.00 FL	*30.60 FL
34	1		*REAR BOOTLID CENTRE CHROME GARNISH	Not Necessary	298.00 FL	*- FL
35	2		*REAR BOOTLID HINGES	Not Necessary	157.20 FL	*- FL
36	1		*REAR BOOTLID INNER LOCK	Serviceable	285.30 FL	*- FL
37	1		*REAR BOOTLID INNER LOCK CATCH	Not Necessary	48.00 FL	*- FL
38	1		*REAR BOOTLID INNER TRIM	Not Necessary	198.00 FL	*- FL
39	1		*REAR BOOT WEATHERSTRIP	Twisted	142.00 FL	*89.70 FL
40	2		*REAR BOOTLID RUBBER STOPPER	Not Necessary	96.40 FL	*- FL
41	1		*REAR BOOTLID LOCK ACTUATOR	Not Necessary	238.00 FL	*- FL
42	1		*RHS REAR DOOR (NPA)	Repair	0.00 FL	*- FL
43	1		*LHS REAR FENDER (NPA)	Not Necessary	0.00 FL	*- FL
44	1		*RHS REAR FENDER INNER TRIM	Not Necessary	298.20 FL	*- FL
45	1		*RHS REAR FENDER INNER SPLASH SHIELD	Not Necessary	198.00 FL	*- FL
46	1		*RHS REAR FENDER AIR VENT	Not Necessary	98.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*REAR BUMPER	Distorted	1,164.00 FL	*404.20 FL
48	1		*REAR BUMPER SIDE RETAINERS	O/s Bent	128.00 FL	*25.20 FL
49	1		*REAR BUMPER REINFORCEMENT	No such part	580.00 FL	*- FL
50	1		*REAR END PANEL	Badly Dented	782.00 FL	*316.00 FL
51	1		*REAR END PANEL TOP GARNISH	Not Necessary	289.00 FL	*- FL
52	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	26.00 FL	*- FL
53	1		*RHS & LHS TAILLAMPS	O/s Cracked	1,956.40 FL	*285.20 FL
54	2		*RHS & LHS TAILLAMPS PANEL	Repair	516.00 FL	*- FL
55	1		*EXHAUST SILENCER ASSEMBLY	Not Necessary	950.00 FL	*- FL
56	1		*EXHAUST SILENCER HEAT SHIELD	Not Necessary	254.00 FL	*- FL
57	4		*EXHAUST SILENCER MOUNTINGS	Not Necessary	96.00 FL	*- FL
58	1		*REAR SPARE TYRE PANEL TOP COVER	Not Necessary	298.00 FL	*- FL
59	1		*REAR SPARE TYRE PANEL	Repair	1,182.00 FL	*- FL
60	1		*REAR SPARE TYRE PANEL TOP BOARD	Not Necessary	242.00 FL	*- FL
61	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
62	1		*REVERSE CAMERA (NPA)	Not Necessary	0.00 FS	*- FS
63	1		*REAR END PANEL SEALANT	Necessary	120.00 FS	*50.00 FS
64	1		*REAR NUMBER PLATE W/HOLDER	Not Necessary	75.00 FS	*- FS
65	1		*FRONT NUMBER PLATE W/HOLDER	Bent	75.00 FS	*40.00 FS
66	2		*REAR NUMBER PLATE LAMPS (NPA)	Not Necessary	0.00 FS	*- FS
67	1		*REAR BOOTLID INNER TRIM CLIPS	Not Necessary	60.00 FS	*- FS
68	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
69	1		*SPARE TYRE PANEL INSULATOR	Not Necessary	140.00 FS	*- FS
70	1		*RADIATOR COOLANT	Necessary	40.00 FS	*30.00 FS
71	1		*REAR WINDSCREEN SEALANT	Not Necessary	100.00 FS	*- FS
72	1		*REAR SPARE TYRE PANEL SEALANT	Not Necessary	100.00 FS	*- FS
73	1		*RHS REAR FENDER	Repair	780.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	26,553.40	5,583.60
- List Item Discount on L Items 20.00/20.00% (\$\$)	5,100.68	1,046.72
Total Parts (\$\$)	21,452.72	4,536.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS;PANEL BEAT & RESHAPE THE AFFECTED AREAS;REPLACE THE DAMAGED PARTS AND COMPONENTS (FRONT AND REAR)	New	2,400.00	1,500.00
2	TO SUPPLY PAINT MATERIALS,EXPANDABLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED AND REPAIRED AREAS (FRONT AND REAR)	New	1,800.00	1,680.00
3	TO REMOVE AND CHECK AND REFIX WIRING AT DAMAGED AREAS	New	200.00	30.00
4	TO PERFORM ANTI RUST TREATMENT ON AFFECTED AREAS	New	210.00	100.00
5	TO REMOVE AND REFIX/REPLACE INNER TRIMS,GARNISH AND REAR CUSHION SEATS ETC.TO FACILITATE REPAIRS (REAR)	New	250.00	80.00
6	TO REMOVE AND REPLACE REAR EXHAUST SILENCER ASSEMBLY	New	250.00	0.00
7	TO REMOVE AND REFIX REAR WINDSCREEN	New	140.00	0.00
8	TO REMOVE AND REPLACE AIR CON CONDENSOR,VACUUM AND REFILL GAS	New	150.00	100.00
9	TO REMOVE AND REPLACE RADIATOR,PRESSURE TEST AND REFILL COOLANT	New	120.00	0.00
10	TO REMOVE AND REPLACE REVERSE SENSORS AND TEST FOR PROPER FUNCTION	New	120.00	40.00
Gross Labour Cost (S\$)			5,640.00	3,530.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >