

NOS.	SPECIAL NETT	QTY	UNIT \$	TOTAL \$	
1	Sundries	1	\$	80.00	\$
2	Rear fender sealant	1	\$	100.00	\$
3	Rear fender inner cowling clips	1	\$	80.00	\$
4	Rear fender inner trim board clips	1	\$	80.00	\$
5	Rear bumper clips	1	\$	60.00	\$
6	Rear no plate w/cowling	1	\$	60.00	\$
7	Tail lamp seal	1	\$	80.00	\$
8	Tail lamp clips	1	\$	60.00	\$
9	Boothid sealant	1	\$	100.00	\$
10	Boothid inner trim board clips	1	\$	60.00	\$
11	Boothid outer garnish clips	1	\$	60.00	\$
12	Rear end panel sealant	1	\$	100.00	\$
13	Rear end panel top garnish clips	1	\$	60.00	\$
14	Spare tyre panel sealant	1	\$	100.00	\$
15	Rear windscreen seal	1	\$	80.00	\$
16	Rear windscreen sealant	1	\$	100.00	\$
17	Rear bumper sensor	4	\$	300.00	\$
SPECIAL NETT TOTAL :				\$ 2,220.00	\$

Nos.	LABOUR	\$
1	To R&R rear component	\$ 70.00
2	To R&R tailgate component	\$ 60.00
3	R&R Exhaust pipe	\$ 50.00
4	R&R rear windscreen	\$
5	To check wiring	\$ 50.00
6	To panel beat	\$ 50.00
7	Diagnostic & reset fault code	\$ 40.00
8	To R&R reverse sensor	\$
9	To rust proof	\$ 60.00
10	To spray painting	\$ 60.00
LABOUR TOTAL :		\$ 720.00

Survey 27/2/2020 Resurvey 28/2/2020
1500 hrs Train Wm

Parts Total : \$11983.22 463.10
SPECIAL NETT TOTAL : \$ 2220.00 2420.00
LABOUR TOTAL : \$ 720.00 4340.00
GRAND TOTAL : \$ 29223.10

@ 20%
15023.92
3005.98
12023.92

45 12,000/2

Train Wm
2/3/2020

LXX Auto Consultants hereby notify the Repainer of the following:

- To resurvey before any spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be replaced and is subject to final approval from Insurance Company

Acknowledged by Repainer
Signature: _____
Date: _____

OTS Boost

Team AutoPro Pte Ltd 105 Sin Ming Dr. #02-11 Sin Ming AutoCity Singapore 575 122
Tel: 6266-9999 Email: estimate-lap@gmail.com / teamautoproteam@gmail.com

2016

S/E: _____
Date of Survey: _____
Date of ReSurvey: _____
Contacts: _____
Vehicle Nos: SLE 3330 J
Made: Volvo
Model: S80
Chassis No: _____
After-Paint: _____

* AGREED Cost Of Repair and Repair Day/s with S/E *
Amount: _____
Working Day: _____

Nos.	PARTS	QTY	Unit \$	TOTAL \$	
1	Rear fender LH	1	\$ 2,030.70	\$ 2,030.70	DD ✓
2	Rear fender inner cowl LH	1	\$ 485.60	\$ 485.60	NDX ✓
3	Rear fender inner trim board LH	1	\$ 652.00	\$ 652.00	TN ✓
4	Rear bumper	1	\$ 2,581.00	\$ 2,581.00	BR ✓
5	Rear bumper lower	1	\$ 1,256.00	\$ 1,256.00	BR ✓
6	Rear bumper side retainer	2	\$ 145.40	\$ 290.80	BR ✓
7	Rear bumper reinforcement	1	\$ 1,852.00	\$ 1,852.00	NEC ✓
8	Rear bumper centre bracket	1	\$ 320.50	\$ 320.50	DD ✓
9	Rear bumper tow cap	1	\$ 250.00	\$ 250.00	BR ✓
10	Rear end panel	1	\$ 1,795.60	\$ 1,795.60	MIS ✓
11	Rear end panel top garnish	1	\$ 894.20	\$ 894.20	DD ✓
12	Spare tyre panel	1	\$ 1,811.00	\$ 1,811.00	DL ✓
13	Spare tyre panel top board	1	\$ 863.40	\$ 863.40	PD ✓
14	Tail lamp LH	1	\$ 1,025.00	\$ 1,025.00	CU ✓
15	Tail lamp lower bracket LH	1	\$ 625.30	\$ 625.30	CU ✓
16	Rear windscreen moulding	1	\$ 482.30	\$ 482.30	NSP ✓
17	Bootlid	1	\$ 3,250.00	\$ 3,250.00	NDX ✓
18	Bootlid emblem 'VOLVO'	1	\$ 185.50	\$ 185.50	DD ✓
19	Bootlid outer garnish	1	\$ 88.40	\$ 88.40	NEC ✓
20	Bootlid inner trim board	1	\$ 685.30	\$ 685.30	CU ✓
21	Bootlid weatherstrip	1	\$ 425.60	\$ 425.60	NDX ✓
22	Bootlid lock	1	\$ 478.90	\$ 478.90	NDX ✓
23	Exhaust pipe	1	\$ 695.20	\$ 695.20	JAM ✓
24	Exhaust mounting	1	\$ 1,520.00	\$ 1,520.00	BT ✓
25	Exhaust heat shield	1	\$ 68.50	\$ 68.50	NN ✓
PARTS Sub Total:				\$ 22,219.89	TN ✓
Discount:				\$ 1,359.78	
PARTS TOTAL:				\$ 20,860.11	

L&K Auto Consultants hence notify the Repairer of the following:

- * To survey before repair spray painting
- * Parts prices are subject to confirmation
- * Third party survey is in a "Without Prejudice" basis
- * No legal modification(s) is allowed
- * Supplementary benefit(s) must be recovered and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____