



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2006615
INV Date 24/09/2020
Reference CC4/FCI20003235/R1ba3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SKA 6972U
Insured Veh. SHC 7320U
Claim No. D20001053MFSH
Policy No. D-20094921MFSH
Accident Date 21/01/2020
Inspection Date 25/02/2020

Description	Total
Third Party Express Settlement	350.00
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI20003235/R1ba3q2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 24-09-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 7320U	Veh. Inspected	SKA 6972U
Policy No.	D-20094921MFSH	Coverage (\$)	0.00
Claim No.	D20001053MFSH	Excess (\$)	0.00
Assign From	ERIC	Assign Date	20/02/2020

2. Vehicle Particulars & Condition

Make & Model	MITSUBISHI ASX 2.0 A	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JMFXTGA2WHZ001721	Colour	WHITE
Odometer	39666	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	225/55 R18	BRIDGESTONE	6 mm
L/H Front Tyre	225/55 R18	BRIDGESTONE	6 mm
R/H Rear Tyre	225/55 R18	BRIDGESTONE	6 mm
L/H Rear Tyre	225/55 R18	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	21/01/2020	Inspection Date	25/02/2020
Survey held at	WAH HONG MOTORS & CREDIT PTE LTD 38 TOH GUAN ROAD EAST #01-57 ENTERPRISE HUB SINGAPORE 608581		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKA 6972U

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR LH DOOR	TO REPAIR SEE LABOUR	1,500.00	-
1	REAR LH DOOR HANDLE	NOT NECESSARY	120.00	-
1	REAR LH FENDER	NOT NECESSARY	1,200.00	-
	LESS 10% DISCOUNT		-282.00	-
			2,538.00	-
<u>SPECIAL NETT ITEMS</u>				
1	FRONT FENDE CLIPS (SN)	NOT NECESSARY	35.00	-
			35.00	-
<u>LABOUR</u>				
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS ,PANEL BEAT & RESHAPE THE AFFECTED AREAS AND REPLACE THE DAMAGED PARTS AND COMPONENTS.INCLUSIVE OF THE REPAIR OF REAR LH DOOR .		800.00	150.00
	TO SUPPLY PAINT MATERIALS EXPANDABLE ITEMS & PUTTY ,RESPRAY PAINT ON PARTS REPLACED & REPAIRED.		600.00	200.00
	TO PROVIDE ANTI-RUST TREATMENT ON AFFECTED AREA.	NOT NECESSARY	150.00	-
			1,550.00	350.00
GRAND TOTAL			4,123.00	350.00
RECOMMENDED COST OF REPAIRS				350.00

Report Ref No. CC4/FCI20003235/R1ba3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKA 6972U

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKA 6972U

RE-INSPECTION

