

VIC



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Page No. 1

Vehicle No: SKA6972U MITSUBISHI ASX-2.0 (A)

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>			
1	Rear LH door <i>repair</i>		1500.00	<i>R</i>
1	Rear LH door handle <i>X</i> NN		120.00	<i>X</i>
1	Rear LH fender <i>X</i> NN		1200.00	<i>X</i>
		Less 10%	2820.00	
			282.00	
			2538.00	
	<u>SPECIAL NETT ITEMS</u>			
1	Front fender clips <i>X</i> NN		35.00	<i>X</i>
	Total Parts		2573.00	



Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806233M)

Page No. 2

Vehicle No. SKA6972U MITSUBISHI ASX-2.0 (A)

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
1	<u>LABOUR</u> To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.	800.00 150	} 350
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	600.00 200	
4	To provide anti-rust treatment on affected area	150.00 X X	
Labour Total :		1550.00	
TOTAL (PARTS & LABOUR):		4123.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Rahul

Hp 90010068

2 days

P/P

25/02/2020 @ 1540

Reay after repair

\$350 / 2 days